

CITY OF MEMPHIS

311 FACILITIES INSPECTION REPORT

Division of Public Works — Code Enforcement

Case ID: CASE-2026-001

Inspector Name: James Williams

Date: 01/15/2026

Phone: (901) 555-0147

Location: 1234 Poplar Ave, Memphis, TN 38104

Ward: District 7

Severity: High

Violation Type: Road Damage

Description:

Large pothole approximately 18 inches in diameter and 4 inches deep located in the eastbound lane of Poplar Avenue, 200 feet west of the Overton Park entrance. The pothole has exposed the gravel base layer and poses a hazard to vehicles and cyclists. Immediate repair recommended before further deterioration occurs.

Photos Attached: 2

Follow-up Required: Yes

Inspector Signature

Date