

# CITY OF MEMPHIS

## 311 FACILITIES INSPECTION REPORT

Division of Public Works — Code Enforcement

---

**Case ID:** CASE-2026-003

**Inspector Name:** Patricia Johnson

**Date:** 02/03/2026

**Phone:** (901) 555-0283

**Location:** 567 Beale St, Memphis, TN 38103

**Ward:** District 3

**Severity:** Medium

**Violation Type:** Property Violation

**Description:**

Multiple instances of graffiti spray paint found on the south-facing wall of the vacant commercial building at 567 Beale Street. Tags cover approximately 40 square feet of brick surface. Also observed illegal dumping of household furniture (couch, mattress) on the adjacent vacant lot. Property owner notification required.

**Photos Attached:** 3

**Follow-up Required:** Yes

---

Inspector Signature

---

Date