

CITY OF MEMPHIS

311 FACILITIES INSPECTION REPORT

Division of Public Works — Code Enforcement

Case ID: CASE-2026-009

Inspector Name: Michael Davis

Date: 01/28/2026

Phone: (901) 555-0391

Location: 890 Front St, Memphis, TN 38103

Ward: District 1

Severity: High

Violation Type: Utility Issue

Description:

Active water main leak detected at the intersection of Front Street and Monroe Avenue. Water is flowing across the sidewalk and into the street, creating icy conditions during cold weather. Estimated flow rate suggests a significant pipe rupture. MLGW has been notified for emergency response. Area cordoned off with traffic cones.

Photos Attached: 1

Follow-up Required: No

Inspector Signature

Date