



Use your smart phone to
scan the QR code and get
detailed autoinspekt report

Address : MAZZANINE FLOOR, PLOT 209-A, OFFICE NO U-9
THADDARAM COMPLEX ZONE I M.P. NAGAR , BHOPAL- 462001

Phone: 9229398801 , 9229398800

Email : help.mfcw@mahindra.com

Insurer Ref No. `

4-WHEELER INSPECTION REPORT

Ref No. PI17918551

Proposer : SHAHID KHAN	Insurer/Broker : NATIONAL INSURANCE CO. LTD.	
Officer/Agent Name & No : Uiic -- 8435278180	Inspection Date : 24/07/2026 06:31 PM	Request Date : 24/07/2026 06:20 PM
Inspection Place : Others		Self-Inspection Case : No

VEHICLE DETAILS

Vehicle NO : MP04CS5209	Chassis NO : HM354160	Engine NO : HM265828	Make : HYUNDAI
Model & Variant : I20	Colour : WHITE	Year of Manufacture : 2017	Odometer Reading : 111588
R.C. Verified : Yes	Fuel Used : Diesel	Stepney Make-Dot No. : `	
RH Front Tyre DOT No. : `		RH Rear Tyre DOT No. : `	
LH Front Tyre DOT No. : `		LH Rear Tyre DOT No. : `	

ELECTRICAL & NON-ELECTRICAL ACCESSORIES

Stereo Make : `	CD Changer Make : `	Other Electrical : `	Seat Cover : Yes
Centre Lock : Yes	Gear Locking : Yes	Other Non-Electrical : ``	

INSPECTION DETAILS

FRONT / REAR			
Front Bumper: Bracket Broken	Indicator Light (LT) : Safe	Front Panel : Safe	Dicky : Safe
Grill: Safe	Indicator Light (RT) : Safe	Bonnet : Safe	Rear Bumper : Scratch
Head Lamp (LT) : Safe	Fog Lamp (LT) : Broken	Left Apron : Safe	Tail Lamp (LT): Safe
Head Lamp (RT) : Safe	Fog Lamp (RT) : Safe	Right Apron : Safe	Tail Lamp (RT) : Safe

LEFT


LT FrontFender : Scratch	LT Pillar Door (A) : Safe	LT FrontDoor : Spot Dent	LT Pillar Centre (B) : Safe
LT RearDoor : Safe	LT Pillar Rear (C) : Safe	LT RunningBoard : Spot Dent	LT Qtr Panel : Safe

RIGHT

RT Qtr Panel : Safe	RT Center Pillar (B) : Safe	Floor / Silencer : Safe	RT Rear Door : Scratch
RT Rear Pillar (C): Safe	Rear View Mirror(LT): Safe	RT Front Door : Spot Dent	RT Running Board : Spot Dent
Rear View Mirror(RT): Safe	RT Front Pillar (A): Safe	RT Front Fender : Safe	Tyres : Safe

GLASS/OTHERS

Back Glass : Intact	RF Door Glass : Intact	LF Door Glass : Intact	Rim: Safe
Front ws Glass Laminated : Intact	RR Door Glass : Intact	LR Door Glass : Intact	Under Carriage : Safe
Airbags : NA	Remarks :		Inspection Status : Recommended

Video Link : [Click Here To Play Video](#)


MP04CS5209 - 24/07/2026 06:23:37 PM - 22.75723 - 77.70873



MP04CS5209 - 24/07/2026 06:24:51 PM - 22.75730 - 77.70899



MP04CS5209 - 24/07/2026 06:22:32 PM - 22.75656 - 77.71243




MP04CS5209 - 24/07/2026 06:23:08 PM - 22.75723 - 77.70873



MP04CS5209 - 24/07/2026 06:22:16 PM - 22.75723 - 77.70873



MP04CS5209 - 24/07/2026 06:24:26 PM - 22.75723 - 77.70873



MP04CS5209 - 24/07/2026 06:26:57 PM - 22.75723 - 77.70873



MP04CS5209 - 24/07/2026 06:22:21 PM - 22.75723 - 77.70873



MP04CS5209 - 24/07/2026 06:22:42 PM - 22.75723 - 77.70874



MP04CS5209 - 24/07/2026 06:22:28 PM - 22.75656 - 77.71243



MP04CS5209 - 24/07/2026 06:22:38 PM - 22.75723 - 77.70874



MP04CS5209 - 24/07/2026 06:22:48 PM - 22.75723 - 77.70874



MP04CS5209 - 24/07/2026 06:22:53 PM - 22.75723 - 77.70874



MP04CS5209 - 24/07/2026 06:22:59 PM - 22.75723 - 77.70874



MP04CS5209 - 24/07/2026 06:24:11 PM - 22.75723 - 77.70873



MP04CS5209 - 24/07/2026 06:23:16 PM - 22.75723 - 77.70874



MP04CS5209 - 24/07/2026 06:23:22 PM - 22.75656 - 77.71243



MP04CS5209 - 24/07/2026 06:24:05 PM - 22.75723 - 77.70873



MP04CS5209 - 24/07/2026 06:24:21 PM - 22.75723 - 77.70873



MP04CS5209 - 24/07/2026 06:24:32 PM - 22.75723 - 77.70873



MP04CS5209 - 24/07/2026 06:24:45 PM - 22.75730 - 77.70899



MP04CS5209 - 24/07/2026 06:25:06 PM - 22.75728 - 77.70859




MP04CS5209 - 24/07/2026 06:24:56 PM - 22.75748 - 77.70842



MP04CS5209 - 24/07/2026 06:25:01 PM - 22.75748 - 77.70842




MP04CS5209 - 24/07/2026 06:25:26 PM - 22.75723 - 77.70861



MP04CS5209 - 24/07/2026 06:25:31 PM - 22.75721 - 77.70863



MP04CS5209 - 24/07/2026 06:25:20 PM - 22.75723 - 77.70861



MP04CS5209 - 24/07/2026 06:27:07 PM - 22.75767 - 77.71035

DECLARATION

- I/We hereby confirm that the vehicle has been inspected in presense of me/my/our representative.
- I/We hereby confirm that the identification details and damages of vehicle as noted / photographs taken by the inspecting officer are correct. Nothing has been hidden/undisclosed.
- I/We agreed that Repair/Replacement of dented/crack parts & Repair Painting of dented/scratched panels as per this inspection photographs shall be excluded in event of any claim lodged during the policy period.
- I hereby certify that I have shown the same vehicle which I have to get insured and if later at the time of claim it is found that vehicle shown and accidental are different then no claim is payable to me.
- I hereby certify that I will not claim for damages existing in my vehicle whether same are mentioned in report or not if same are seen in photograph taken by the inspector.



Verified Seal

Approved By

Kingshuk Sanyal

Kingshuk Sanyal
23279373
CBO - Services
www.autoinspekt.com

Authorized Signature

TIMING ANALYSIS

Number	Part Name	Time
	Front	18:22:16
	Under Carriage	18:22:21
	Front Left Corner 45 Degree	18:22:28
	Left Side	18:22:32
	Rear Left Corner 45 Degree	18:22:38
	Rear	18:22:42
	Under Chassis Photo Back	18:22:48
	Dicky Open Photo	18:22:53
	Rear Right Corner 45 Degree	18:22:59
	Right Side	18:23:08
	Interior1	18:23:16
	Windshield Inner	18:23:22
	Chassis Thumb	18:23:37
	Eng Regis Plate	18:24:05
	Front Right Corner 45 Degree	18:24:11
	Front With Number Plate 90	18:24:21
	Engine Compartment	18:24:26
	Windshield Outer	18:24:32
	Selfie	18:24:45
	Rc	18:24:51
	Tyre 2	18:24:56
	Tyre 3	18:25:01
	Tyre 1	18:25:06
	Damage2	18:25:20
	Tyre 4	18:25:26
	Damage1	18:25:31
	Odometer	18:26:57
	Damage3	18:27:07

Time Difference