



Use your smart phone to scan the QR code and get detailed autoinspekt report

Address : MAZZANINE FLOOR, PLOT 209-A, OFFICE NO U-9 THADDARAM COMPLEX ZONE I M.P. NAGAR , BHOPAL - 462001

Phone: 9229398801 , 9229398800

Email : help.mfcw@mahindra.com

Insurer Ref No. NA
4-WHEELER INSPECTION REPORT
Ref No. PI17891076

Proposer : MOHAMMAD MUSHTAQ	Insurer/Broker : NATIONAL INSURANCE CO. LTD.	
Officer/Agent Name & No : Abc -- 8827560923	Inspection Date : 15/07/2026 03:35 PM	Request Date : 15/07/2026 03:30 PM
Inspection Place : Chota talab		Self-Inspection Case : No

VEHICLE DETAILS

Vehicle NO : MP04YB1973	Chassis NO : GM232279	Engine NO : GM235692	Make : HYUNDAI
Model & Variant : XCENT	Colour : SILVER	Year of Manufacture : 2016	Odometer Reading : 78231
R.C. Verified : Yes	Fuel Used : Diesel	Stepney Make-Dot No. : `	
RH Front Tyre DOT No. : `		RH Rear Tyre DOT No. : `	
LH Front Tyre DOT No. : `		LH Rear Tyre DOT No. : `	

ELECTRICAL & NON-ELECTRICAL ACCESSORIES

Stereo Make : `	CD Changer Make : `	Other Electrical : `	Seat Cover : Yes
Centre Lock : Yes	Gear Locking : Yes	Other Non-Electrical : .	

INSPECTION DETAILS

FRONT / REAR			
Front Bumper: Safe	Indicator Light (LT) : Safe	Front Panel : Safe	Dicky : Spot Dent
Grill: Safe	Indicator Light (RT) : Safe	Bonnet : Safe	Rear Bumper : Safe
Head Lamp (LT) : Safe	Fog Lamp (LT) : Safe	Left Apron : Safe	Tail Lamp (LT): Crack
Head Lamp (RT) : Safe	Fog Lamp (RT) : Safe	Right Apron : Safe	Tail Lamp (RT) : Safe

LEFT

LT FrontFender : Safe	LT Pillar Door (A) : Safe	LT FrontDoor : Safe	LT Pillar Centre (B) : Safe
LT RearDoor : Dented	LT Pillar Rear (C) : Safe	LT RunningBoard : Safe	LT Qtr Panel : Spot Dent

RIGHT

RT Qtr Panel : Dented	RT Center Pillar (B) : Safe	Floor / Silencer : Safe	RT Rear Door : Spot Dent
RT Rear Pillar (C): Safe	Rear View Mirror(LT): Safe	RT Front Door : Safe	RT Running Board : Dented
Rear View Mirror(RT): Safe	RT Front Pillar (A): Safe	RT Front Fender : Safe	Tyres : Safe

GLASS/OTHERS

Back Glass : Intact	RF Door Glass : Intact	LF Door Glass : Intact	Rim: Safe
Front ws Glass Laminated : Intact	RR Door Glass : Intact	LR Door Glass : Intact	Under Carriage : Safe
Airbags : NA	Remarks :		Inspection Status : Recommended

Video Link : [Click Here To Play Video](#)


MP04YB1973 - 15/07/2026 03:33:33 PM - 23.25346 - 77.40834

RC Image

MP04YB1973 - 0.00000 - 0.00000



MP04YB1973 - 15/07/2026 03:31:04 PM - 23.25357 - 77.40843



MP04YB1973 - 15/07/2026 03:32:42 PM - 23.25342 - 77.40826



MP04YB1973 - 15/07/2026 03:31:17 PM - 23.25356 - 77.40843



MP04YB1973 - 15/07/2026 03:30:39 PM - 23.25357 - 77.40840



MP04YB1973 - 15/07/2026 03:30:14 PM - 23.25325 - 77.40805



MP04YB1973 - 15/07/2026 03:32:50 PM - 23.25340 - 77.40818



MP04YB1973 - 15/07/2026 03:30:52 PM - 23.25357 - 77.40843



MP04YB1973 - 15/07/2026 03:30:28 PM - 23.25331 - 77.40807



MP04YB1973 - 15/07/2026 03:30:44 PM - 23.25357 - 77.40840



MP04YB1973 - 15/07/2026 03:31:53 PM - 23.25349 - 77.40833



MP04YB1973 - 15/07/2026 03:32:22 PM - 23.25356 - 77.40841



MP04YB1973 - 15/07/2026 03:30:57 PM - 23.25357 - 77.40843



MP04YB1973 - 15/07/2026 03:31:10 PM - 23.25353 - 77.40840



MP04YB1973 - 15/07/2026 03:32:54 PM - 23.25340 - 77.40818



MP04YB1973 - 15/07/2026 03:32:58 PM - 23.25340 - 77.40818



MP04YB1973 - 15/07/2026 03:31:42 PM - 23.25353 - 77.40839



MP04YB1973 - 15/07/2026 03:31:22 PM - 23.25356 - 77.40843



MP04YB1973 - 15/07/2026 03:31:25 PM - 23.25356 - 77.40843



MP04YB1973 - 15/07/2026 03:31:30 PM - 23.25343 - 77.40827



MP04YB1973 - 15/07/2026 03:31:35 PM - 23.25343 - 77.40827



MP04YB1973 - 15/07/2026 03:31:47 PM - 23.25353 - 77.40839



MP04YB1973 - 15/07/2026 03:32:00 PM - 23.25349 - 77.40833



MP04YB1973 - 15/07/2026 03:32:04 PM - 23.25352 - 77.40829

DECLARATION

- I/We hereby confirm that the vehicle has been inspected in presense of me/my/our representative.
- I/We hereby confirm that the identification details and damages of vehicle as noted / photographs taken by the inspecting officer are correct. Nothing has been hidden/undisclosed.
- I/We agreed that Repair/Replacement of dented/crack parts & Repair Painting of dented/scratched panels as per this inspection photographs shall be excluded in event of any claim lodged during the policy period.
- I hereby certify that I have shown the same vehicle which I have to get insured and if later at the time of claim it is found that vehicle shown and accidental are different then no claim is payable to me.
- I hereby certify that I will not claim for damages existing in my vehicle whether same are mentioned in report or not if same are seen in photograph taken by the inspector.

**Verified Seal****Authorized Signature**

TIMING ANALYSIS

Number	Part Name	Time
	Front	15:30:14
	Front Left Corner 45 Degree	15:30:28
	Left Side	15:30:39
	Rear Left Corner 45 Degree	15:30:44
	Rear	15:30:52
	Rear Right Corner 45 Degree	15:30:57
	Right Side	15:31:04
	Front Right Corner 45 Degree	15:31:10
	Under Carriage	15:31:17
	Front With Number Plate 90	15:31:22
	Windshield Outer	15:31:25
	Selfie	15:31:30
	Tyre 1	15:31:35
	Eng Regis Plate	15:31:42
	Tyre 2	15:31:47
	Under Chassis Photo Back	15:31:53
	Tyre 3	15:32:00
	Tyre 4	15:32:04
	Dicky Open Photo	15:32:22
	Engine Compartment	15:32:42
	Odometer	15:32:50
	Interior1	15:32:54
	Windshield Inner	15:32:58
	Chassis Thumb	15:33:33

