



Use your smart phone to scan the QR code and get detailed autoinspekt report

Address : MAZZANINE FLOOR, PLOT 209-A, OFFICE NO U-9 THADDARAM COMPLEX ZONE I M.P. NAGAR , BHOPAL - 462001

Phone: 9229398801 , 9229398800

Email : help.mfcw@mahindra.com

Insurer Ref No. deepak sir

4-WHEELER INSPECTION REPORT

Ref No. PI17937572

Proposer : RAMPRASAD MUJAVDIYA	Insurer/Broker : NATIONAL INSURANCE CO. LTD.	
Officer/Agent Name & No : NA -- 9999999999	Inspection Date : 31/07/2026 01:40 PM	Request Date : 31/07/2026 12:00 PM
Inspection Place : Others		Self-Inspection Case : No

VEHICLE DETAILS

Vehicle NO : MP09CT0835	Chassis NO : MALA851CLFM338705	Engine NO : G4LAFM800331	Make : HYUNDAI
Model & Variant : GRAND I10 SPORTZ 1.2 KAPPA VTVT	Colour : RED	Year of Manufacture : 2015	Odometer Reading : 65002
R.C. Verified : Yes	Fuel Used : Petrol	Stepney Make-Dot No. : `	
RH Front Tyre DOT No. : `		RH Rear Tyre DOT No. : `	
LH Front Tyre DOT No. : `		LH Rear Tyre DOT No. : `	

ELECTRICAL & NON-ELECTRICAL ACCESSORIES

Stereo Make : `	CD Changer Make : `	Other Electrical : `	Seat Cover : Yes
Centre Lock : Yes	Gear Locking : Yes	Other Non-Electrical : `	

INSPECTION DETAILS

FRONT / REAR			
Front Bumper: Scratch	Indicator Light (LT) : Safe	Front Panel : Safe	Dicky : Safe
Grill: Safe	Indicator Light (RT) : Safe	Bonnet : Safe	Rear Bumper : Safe
Head Lamp (LT) : Safe	Fog Lamp (LT) : Safe	Left Apron : Safe	Tail Lamp (LT): Safe
Head Lamp (RT) : Safe	Fog Lamp (RT) : Safe	Right Apron : Safe	Tail Lamp (RT) : Safe

LEFT

LT FrontFender : Spot Dent	LT Pillar Door (A) : Safe	LT FrontDoor : Safe	LT Pillar Centre (B) : Safe
LT RearDoor : Spot Dent	LT Pillar Rear (C) : Safe	LT RunningBoard : Safe	LT Qtr Panel : Safe

RIGHT

RT Qtr Panel : Scratch	RT Center Pillar (B) : Safe	Floor / Silencer : Safe	RT Rear Door : Scratch
RT Rear Pillar (C): Safe	Rear View Mirror(LT): Safe	RT Front Door : Safe	RT Running Board : Safe
Rear View Mirror(RT): Safe	RT Front Pillar (A): Safe	RT Front Fender : Scratch	Tyres : Safe

GLASS/OTHERS

Back Glass : Intact	RF Door Glass : Intact	LF Door Glass : Intact	Rim: Safe
Front ws Glass Laminated : Intact	RR Door Glass : Intact	LR Door Glass : Intact	Under Carriage : Safe
Airbags : NA	Remarks :		Inspection Status : Recommended

Video Link : [Click Here To Play Video](#)



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835



MP09CT0835

DECLARATION

- I/We hereby confirm that the vehicle has been inspected in presense of me/my/our representative.
- I/We hereby confirm that the identification details and damages of vehicle as noted / photographs taken by the inspecting officer are correct. Nothing has been hidden/undisclosed.
- I/We agreed that Repair/Replacement of dented/crack parts & Repair Painting of dented/scratched panels as per this inspection photographs shall be excluded in event of any claim lodged during the policy period.
- I hereby certify that I have shown the same vehicle which I have to get insured and if later at the time of claim it is found that vehicle shown and accidental are different then no claim is payable to me.
- I hereby certify that I will not claim for damages existing in my vehicle whether same are mentioned in report or not if same are seen in photograph taken by the inspector.



Verified Seal

Approved By

Kingshuk Sanyal

Kingshuk Sanyal
23279373
CBO - Services
www.autoinspekt.com

Authorized Signature