



Use your smart phone to scan the QR code and get detailed autoinspekt report

**Address :** MAZZANINE FLOOR, PLOT 209-A, OFFICE NO U-9 THADDARAM COMPLEX ZONE I M.P. NAGAR , BHOPAL - 462001

**Phone:** 9229398801 , 9229398800

**Email :** help.mfcw@mahindra.com

Insurer Ref No. NA

4-WHEELER INSPECTION REPORT

Ref No. PI17890469

|                                            |                                                  |                                    |
|--------------------------------------------|--------------------------------------------------|------------------------------------|
| Proposer : MANISH JOHARI                   | Insurer/Broker : THE NEW INDIA ASSURANCE CO.LTD. |                                    |
| Officer/Agent Name & No : NA -- 9999999999 | Inspection Date : 15/07/2026 12:55 PM            | Request Date : 15/07/2026 12:50 PM |
| Inspection Place : ..                      |                                                  | Self-Inspection Case : No          |

#### VEHICLE DETAILS

|                           |                       |                            |                          |
|---------------------------|-----------------------|----------------------------|--------------------------|
| Vehicle NO : RJ14CT5308   | Chassis NO : DN400313 | Engine NO : 74135398       | Make : HONDA             |
| Model & Variant : CITY    | Colour : WHITE        | Year of Manufacture : 2013 | Odometer Reading : 53486 |
| R.C. Verified : Yes       | Fuel Used : Petrol    | Stepney Make-Dot No. : `   |                          |
| RH Front Tyre DOT No. : ` |                       | RH Rear Tyre DOT No. : `   |                          |
| LH Front Tyre DOT No. : ` |                       | LH Rear Tyre DOT No. : `   |                          |

#### ELECTRICAL & NON-ELECTRICAL ACCESSORIES

|                   |                     |                          |                  |
|-------------------|---------------------|--------------------------|------------------|
| Stereo Make : `   | CD Changer Make : ` | Other Electrical : `     | Seat Cover : Yes |
| Centre Lock : Yes | Gear Locking : Yes  | Other Non-Electrical : ` |                  |

#### INSPECTION DETAILS

| FRONT / REAR          |                             |                    |                       |
|-----------------------|-----------------------------|--------------------|-----------------------|
| Front Bumper: Scratch | Indicator Light (LT) : Safe | Front Panel : Safe | Dicky : Dented        |
| Grill: Safe           | Indicator Light (RT) : Safe | Bonnet : Safe      | Rear Bumper : Scratch |
| Head Lamp (LT) : Safe | Fog Lamp (LT) : Safe        | Left Apron : Safe  | Tail Lamp (LT): Safe  |
| Head Lamp (RT) : Safe | Fog Lamp (RT) : Safe        | Right Apron : Safe | Tail Lamp (RT) : Safe |

**LEFT**

|                         |                           |                             |                             |
|-------------------------|---------------------------|-----------------------------|-----------------------------|
| LT FrontFender : Safe   | LT Pillar Door (A) : Safe | LT FrontDoor : Safe         | LT Pillar Centre (B) : Safe |
| LT RearDoor : Spot Dent | LT Pillar Rear (C) : Safe | LT RunningBoard : Spot Dent | LT Qtr Panel : Safe         |

**RIGHT**

|                            |                             |                         |                         |
|----------------------------|-----------------------------|-------------------------|-------------------------|
| RT Qtr Panel : Spot Dent   | RT Center Pillar (B) : Safe | Floor / Silencer : Safe | RT Rear Door : Safe     |
| RT Rear Pillar (C): Safe   | Rear View Mirror(LT): Safe  | RT Front Door : Scratch | RT Running Board : Safe |
| Rear View Mirror(RT): Safe | RT Front Pillar (A): Safe   | RT Front Fender : Safe  | Tyres : Safe            |

**GLASS/OTHERS**

|                                   |                        |                        |                                 |
|-----------------------------------|------------------------|------------------------|---------------------------------|
| Back Glass : Intact               | RF Door Glass : Intact | LF Door Glass : Intact | Rim: Safe                       |
| Front ws Glass Laminated : Intact | RR Door Glass : Intact | LR Door Glass : Intact | Under Carriage : Safe           |
| Airbags : NA                      | Remarks :              |                        | Inspection Status : Recommended |

Video Link : [Click Here To Play Video](#)


RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308



RJ14CT5308

### DECLARATION

- I/We hereby confirm that the vehicle has been inspected in presense of me/my/our representative.
- I/We hereby confirm that the identification details and damages of vehicle as noted / photographs taken by the inspecting officer are correct. Nothing has been hidden/undisclosed.
- I/We agreed that Repair/Replacement of dented/crack parts & Repair Painting of dented/scratched panels as per this inspection photographs shall be excluded in event of any claim lodged during the policy period.
- I hereby certify that I have shown the same vehicle which I have to get insured and if later at the time of claim it is found that vehicle shown and accidental are different then no claim is payable to me.
- I hereby certify that I will not claim for damages existing in my vehicle whether same are mentioned in report or not if same are seen in photograph taken by the inspector.



Verified Seal

Approved By

*Kingshuk Sanyal*

**Kingshuk Sanyal**  
23279373  
CBO - Services  
www.autoinspekt.com

Authorized Signature