LIVE AI INFERENCE · Model: nim:nvidia/nemotron-3.5-super-vl-120b-a12b

Provisional observations generated from uploaded photo. Requires licensed on-site inspection.

Property Documentation Draft

Preliminary Severity: Unknown

The image is a synthetic illustration of a single-story house with visible roof damage. It is not a real photograph and should not be used as primary evidence of actual property damage.

VISIBLE OBSERVATIONS

- Illustration shows a house with a gabled roof.
- Several roof shingles appear displaced or missing near the ridge.
- One section of roofing material appears torn or lifted.
- A window and front door are visible on the front facade.
- A small palm-like tree is visible to the right of the house.
- Text at the top reads 'SYNTHETIC ILLUSTRATION - NOT A REAL PHOTO'.
- Text at the bottom reads 'Cape Coral not sample - StandardAI - illustrative only'.
- No people are visible.
- No address, evacuation zone, or official classification is shown.

POTENTIAL CONCERNS & HAZARDS

- Exposed roof decking or underlayment may be present where shingles are missing, but this cannot be confirmed from an illustration.
- Potential for water intrusion through damaged roof areas, but actual leakage cannot be verified.
- No visible structural collapse, fire, floodwater, or mold in the illustration.

RECOMMENDED NEXT STEPS

- Do not treat this illustration as documentation of real storm damage.
- Obtain clear, dated photographs of the actual property from multiple angles.
- Document any visible roof, window, door, siding, or interior damage on the real structure.
- Note the date and time of the inspection and weather conditions if known.
- Avoid entering areas with suspected structural instability or electrical hazards.
- Consult a qualified professional for an in-person assessment before making repair or insurance decisions.

LIMITATIONS & SCOPE

Provisional observation from a single photo; not an official inspection or structural-safety determination.

Not a FEMA classification, coverage or eligibility determination, or repair quote.

Some damage or hazards may be hidden, out of frame, or misidentified; consult qualified professionals.

Image is a synthetic illustration, not a photograph of real damage.

No actual property address or location is verified.

No official FEMA, insurance, or safety determination can be made from this image.

Repair costs and eligibility cannot be estimated.

Concealed damage cannot be ruled out.

Document ID: `assessment-bbe3823a-b41c-448b-94e3-7845f9715e47`

Generated: Nov 2, 2026, 11:41 AM