SAMPLE · Pre-written illustrative fixture

This is a pre-written illustrative fixture, not an automated AI inference.

Property Documentation Draft

Preliminary Severity: Minor

Sample: the illustration suggests screen-enclosure separation and frame deformation. Stability and the full extent of damage are unverified.

VISIBLE OBSERVATIONS

- An illustrative screen panel appears separated from its frame.
- The frame is shown with a visible deformation.
- No foundation or structural connection is visible in this sample.

POTENTIAL CONCERNS & HAZARDS

- Sharp edges and loose panels may be present.
- The enclosure may not be stable in wind; keep people away until it is assessed.

RECOMMENDED NEXT STEPS

- Document the visible separation from a safe distance.
- Keep people and pets away from loose panels or sharp edges.
- Arrange an inspection by a qualified enclosure or screen contractor.

LIMITATIONS & SCOPE

- This is a synthetic illustration, not a photograph of a real property.
- A single view cannot establish whether the enclosure remains structurally stable.
- Pre-written illustrative sample, not live AI analysis of an uploaded image.
- Not an official FEMA classification, coverage or eligibility determination, or repair quote.
- Provisional documentation only; consult qualified professionals before decisions.

Document ID: `sample-sanibel-lanai`

Generated: Nov 2, 2026, 11:52 AM