

测试编号: TEST-2025-0228 测试时间: 2025-02-28 14:30:00

测试人员: 车载接收机 环境温度: 25°C 环境湿度: 65%

备注: 在开阔场地进行测试, 天气晴朗, 无电磁干扰

| 测试项 | 测试数据 | 标准值 | 结果 |
|--------|--------------------|-----|------|
| 静态定位精度 | 179782.33691164467 | 15 | FAIL |
| 静态定位精度 | 179782.33691164467 | 15 | FAIL |
| 静态定位精度 | 179782.33691164467 | 15 | FAIL |
| 静态定位精度 | 179782.33691164467 | 15 | FAIL |
| 静态定位精度 | 179782.39401237032 | 15 | FAIL |
| 静态定位精度 | 179782.43207952075 | 15 | FAIL |
| 静态定位精度 | 179782.4592703425 | 15 | FAIL |
| 静态定位精度 | 179782.4796634588 | 15 | FAIL |
| 静态定位精度 | 179782.5208864499 | 15 | FAIL |
| 静态定位精度 | 179786.3271404571 | 15 | FAIL |
| 静态定位精度 | 179786.3271404571 | 15 | FAIL |
| 静态定位精度 | 179786.27628919863 | 15 | FAIL |



| 静态定位精度 | 179786.25086356938 | 15 | FAIL |
|--------|--------------------|----|------|
| 静态定位精度 | 179786.23560819184 | 15 | FAIL |
| 静态定位精度 | 179786.1841018897 | 15 | FAIL |
| 静态定位精度 | 179786.14731167388 | 15 | FAIL |
| 静态定位精度 | 179786.119719012 | 15 | FAIL |
| 静态定位精度 | 179785.74903740545 | 15 | FAIL |
| 静态定位精度 | 179785.74903740545 | 15 | FAIL |
| 静态定位精度 | 179785.74903740545 | 15 | FAIL |
| 静态定位精度 | 179785.74903740545 | 15 | FAIL |
| 静态定位精度 | 179785.45793767215 | 15 | FAIL |
| 静态定位精度 | 179785.3609044277 | 15 | FAIL |
| 静态定位精度 | 179785.3123878055 | 15 | FAIL |
| 静态定位精度 | 179785.28327783215 | 15 | FAIL |
| 静态定位精度 | 179778.31007479905 | 15 | FAIL |
| 静态定位精度 | 179778.31007479905 | 15 | FAIL |



| 179778.31007479908 | 15 | FAIL |
|----------------------|---|--|
| 179778.31007479905 | 15 | FAIL |
| 179778.3092353615 | 15 | FAIL |
| 179778.30867573645 | 15 | FAIL |
| 179778.3082760043 | 15 | FAIL |
| 179778.2977173535 | 15 | FAIL |
| 179778.28950506955 | 15 | FAIL |
| 179780.04369133172 | 15 | FAIL |
| 179778.57962291193 | 15 | FAIL |
| 179783.48212131168 | 15 | FAIL |
| 179783.87755000932 | 15 | FAIL |
| 0.016576543209876546 | 15 | PASS |
| 0.19270307520611069 | 15 | PASS |
| 0.21308502290904083 | 15 | PASS |
| 0.07447408204416704 | 15 | PASS |
| | 179778.31007479905 179778.3092353615 179778.30867573645 179778.3082760043 179778.2977173535 179778.28950506955 179780.04369133172 179778.57962291193 179783.48212131168 179783.87755000932 0.016576543209876546 0.19270307520611069 0.21308502290904083 | 179778.31007479905 15 179778.3092353615 15 179778.30867573645 15 179778.3082760043 15 179778.2977173535 15 179778.28950506955 15 179780.04369133172 15 179778.57962291193 15 179783.48212131168 15 179783.87755000932 15 0.016576543209876546 15 0.19270307520611069 15 0.21308502290904083 15 |



| 里程偏差 | 0.15402516542498024 | 15 | PASS |
|-------|---------------------|----|------|
| 跟踪灵敏度 | -134 | 15 | PASS |
| 跟踪灵敏度 | -119 | 15 | PASS |
| 跟踪灵敏度 | -119 | 15 | PASS |
| 跟踪灵敏度 | -119 | 15 | PASS |
| 跟踪灵敏度 | -119 | 15 | PASS |
| 跟踪灵敏度 | -119 | 15 | PASS |
| 跟踪灵敏度 | -119 | 15 | PASS |
| 跟踪灵敏度 | -119 | 15 | PASS |
| 跟踪灵敏度 | -119 | 15 | PASS |
| 跟踪灵敏度 | -119 | 15 | PASS |
| 跟踪灵敏度 | -119 | 15 | PASS |
| 跟踪灵敏度 | 1 | 15 | PASS |
| 跟踪灵敏度 | -119 | 15 | PASS |
| 跟踪灵敏度 | -119 | 15 | PASS |