



RentalEase

Ease Every Lease

2026

SMOKE ALARM AND ELECTRICAL REPORT



03 5906 7723



www.rentalease.com.au

- Safety checks made easy
- Trades services
- Seamless software integration
- Ease for property managers.

Electrical and Smoke Alarm Report

Compliant

Address:	123 Demo Street, Melbourne VIC 3000
Inspection Date:	Saturday 9 May 2026
Inspection Summary:	Compliant
Next Compliance Date:	Monday 8 May 2028
Technician Details:	Demo Technician Licence: LIC-DEMO-001
Regulations / Standards:	AS/NZS 3000 Wiring Rules; AS/NZS 3019:2022 Electrical Installations - Periodic Verification; Energy Safe Victoria residential tenancy electrical safety check requirements; Residential Tenancies Regulations 2021
Declaration:	Not captured
Signature:	Not captured

Recommendations

- Next steps / notes: No faults identified during demo inspection.
- Extent notes: Compliant demo response using local asset-backed report generation.
- Visual inspection notes: Compliant demo response using local asset-backed report generation.
- Testing notes: Compliant demo response using local asset-backed report generation.
- Earth continuity notes: Compliant demo response using local asset-backed report generation.
- RCD notes: Compliant demo response using local asset-backed report generation.
- Smoke alarm notes: Compliant demo response using local asset-backed report generation.
- Certification notes: Compliant demo response using local asset-backed report generation.

Electrical Safety Check

No faults identified

Smoke Alarm Check

Pending



Comments on Next Steps

No faults identified during demo inspection.

Contact Information

Email	Demo response
-------	---------------

Phone	Demo response
-------	---------------

Extent of Installation Checked

Main Switchboard	Included
Main Earthing System	Included
Kitchen	Included
Bathroom (main)	Included
Other bathrooms/ensuites	Included
Laundry	Included
Garage	Included
Living room	Included
Other living areas	Included
Bedroom (main)	Included
Other bedrooms	Included
Electric water heater	Included
Electric room/space heaters	Included
Dishwasher	Included
Solar/battery system	Included
Swimming pool equipment	Included

Compliant demo response using local asset-backed report generation.

Visual Inspection

Consumers mains	Satisfactory
Switchboards	Satisfactory
Exposed earth electrode	Satisfactory
Metallic water pipe bond	Satisfactory
RCDs (Safety switches)	Satisfactory
Space heaters	Satisfactory
Cooking equipment	Satisfactory
Dishwasher	Satisfactory
Exhaust fans	Satisfactory
Ceiling fans	Satisfactory
Circuit protection (circuit breakers / fuses)	Satisfactory
Washing machine/dryer	Satisfactory
Socket-outlets	Satisfactory
Light fittings	Satisfactory
Installation wiring	Satisfactory
Solar and other renewable systems	Satisfactory
Electric water heater	Satisfactory
Swimming pool equipment	Satisfactory
Air conditioners	Satisfactory
Vehicle chargers	Satisfactory

Compliant demo response using local asset-backed report generation.



Polarity & Correct Connections Testing

Consumers mains	Pass
Electric water heater	Pass
Circuit protection (circuit breakers / fuses)	Pass
Air conditioners	Pass
RCDs (Safety switches)	Pass
Cooking equipment	Pass
Dishwasher	Pass
Light fittings	Pass
Solar and other renewable systems	Pass
Socket-outlets	Pass
Swimming pool equipment	Pass
Vehicle chargers	Pass

Compliant demo response using local asset-backed report generation.



Earth Continuity Testing

Mains earth conductor	Pass
Electric water heater	Pass
Switchboards enclosure	Pass
Air conditioners	Pass
Metallic water pipe bond	Pass
Cooking equipment	Pass
Socket-outlets	Pass
Light fittings	Pass
Exhaust fans	Pass
Ceiling fans	Pass
Dishwasher	Pass
Solar and other renewable systems	Pass
Swimming pool equipment	Pass
Vehicle chargers	Pass

Compliant demo response using local asset-backed report generation.

RCD Testing

All RCDs have passed push and time tests	Pass
--	------

Compliant demo response using local asset-backed report generation.

Smoke Alarms

All smoke alarms are correctly installed, operational, and tested	Yes
Next smoke alarm check due	Sunday 9 May 2027

Smoke Alarm Inventory

Voltage	Status	Location	Level	Expiration
Demo response	compliant	Demo response	Demo response	09/05/2026

Compliant demo response using local asset-backed report generation.

Inspection Photos



Switchboard - Switchboard demo photo (electrical-safety-cover.jpg)



Smoke Alarm - Smoke Alarm demo photo (electrical_safety_report_cover_page.jpg)



Aircon - Aircon demo photo (gas_safety_report_cover_page.jpg)



GPO with tester lit up - GPO with tester lit up demo photo (smoke_alarm_safety_report_cover_page.jpg)



Oven - Oven demo photo
(minimum_standard_report_cover_page.jpg)



Rangehood - Rangehood demo photo (logo-report-header.png)



Additional Photos - Additional Photos demo photo
(electrical-safety-cover.jpg)

Electrical Safety Check Certification

Inspection date

Saturday 9 May 2026

Next inspection due

Monday 8 May 2028

Signed at

9 May 2026, 11:14 pm

Certification notes

Compliant demo response using local asset-backed report generation.

Inspector Observations and Suggestions

Generated compliant demo report using local assets.

Declaration and Certification

This electrical and smoke alarm report summarises the inspection findings and certifies that the attending technician has performed the required checks and recommendations recorded below.

- AS/NZS 3000 Wiring Rules
- AS/NZS 3019:2022 Electrical Installations - Periodic Verification
- Energy Safe Victoria residential tenancy electrical safety check requirements
- Residential Tenancies Regulations 2021

I certify that this inspection has been conducted by a qualified inspector and the information contained in this report is true and accurate to the best of my knowledge at the time of inspection.

Inspector Certification:

Inspector Name:
Demo Technician
Date: Saturday 9 May 2026



Next Compliance Schedule

Next Inspection Date Monday 8 May 2028

Regulations This electrical safety check has been completed in line with the Residential Tenancies Regulations 2021 and AS/NZS 3019: Electrical Installations — Periodic Verification. It ensures the property's electrical system is safe and free from damage or deterioration that could pose a risk. Any defects or safety concerns identified during the inspection are reported for corrective action.

