



RentalEase

Ease Every Lease

2026

SMOKE ALARM CHECK REPORT



03 5906 7723



www.rentalease.com.au

- Safety checks made easy
- Trades services
- Seamless software integration
- Ease for property managers.

Smoke Compliance Report

Compliant

Address:	123 Demo Street, Melbourne VIC 3000
Inspection Date:	Saturday 9 May 2026
Inspection Summary:	Compliant
Next Compliance Date:	Monday 8 May 2028
Technician Details:	Demo Technician Licence: LIC-DEMO-001
Regulations / Standards:	AS 3786 Smoke Alarms; Victorian rental smoke alarm annual check requirements; Residential Tenancies Regulations 2021
Declaration:	Not captured
Signature:	Captured

Recommendations

- Access notes: full-access
- Access notes comments: Compliant demo response using local asset-backed report generation.

Smoke Alarm Inspection Summary

Our inspection identified compliance status of smoke alarms at this property.
Please review the information below for findings and recommendations.

Inspection Photos





Property Overview - Property Overview demo photo (electrical-safety-cover.jpg)



Alarm Installation Context - Alarm Installation Context demo photo (electrical_safety_report_cover_page.jpg)



Manufacturer Labels - Manufacturer Labels demo photo (gas_safety_report_cover_page.jpg)



Testing in Progress - Testing in Progress demo photo (smoke_alarm_safety_report_cover_page.jpg)



Replacement Work - Replacement Work demo photo (minimum_standard_report_cover_page.jpg)



Defects or Issues - Defects or Issues demo photo (logo-report-header.png)



Additional Photos - Additional Photos demo photo
 (electrical-safety-cover.jpg)

Inspection Summary

Item	Result
Inspection Date	09/05/2026
Date of previous smoke alarm check (if any)	09/05/2026
Inspector name	Demo response
Licence/registration number	Demo response
Smoke alarm inspection outcome	compliant
Next service due	08/05/2028
Access notes	Full access obtained
Access notes comments	Compliant demo response using local asset-backed report generation.

Property Coverage Assessment

Item	Result
Property type	House
Number of storeys	1
Number of bedrooms	3
Hallway serving bedrooms has smoke alarm	Yes
Smoke alarm between sleeping areas and living areas	Yes
Every storey has at least one smoke alarm	Yes
Property has garage with internal access	Yes
Garage with internal access has smoke alarm	Yes
Additional coverage areas	Kitchen
Property coverage meets AS 3786 requirements	Yes
Coverage deficiencies	Compliant demo response using local asset-backed report generation.

Smoke Alarm Inventory

Item	Result
Total smoke alarms on property	1

Individual Alarm Records #1

Item	Result
Alarm ID	Demo response
Location	Hallway (bedrooms)
Location Detail	Demo response
Brand & Model	Demo response
Alarm Type	Photoelectric
Power Source	240V mains hardwired
Manufacture Date	09/05/2026
Manufacture date unknown/unreadable	No
Age (Years)	1
Expired (over 10 years old)	Yes
Mounting Position	Ceiling (centre of room)
Positioning meets AS 3786	Yes
Physical Condition	Excellent
Test Button Result	Pass
Sound level adequate ("e85dB)	Yes
Sound Level Measured (dB)	1
Interconnection Type	Not interconnected
Interconnection working correctly	Yes
Battery Condition	N/A - Hardwired only
Overall Compliance	Compliant
Action Required	No action required

Work Completed Today

Tested only

Comments

 Compliant demo response
 using local asset-backed
 report generation.

Overall Compliance Assessment
Item
Result
Overall property compliance status

 Fully Compliant - All
 requirements met

Certification & Testing Status
Item
Result
Company/Organization

 RentalEase Technical
 Services

Contact Phone Number

+61 3 9876 5432

Standards and regulations applied

 AS 3786:2014 Smoke alarms
 using scattered light,
 transmitted light or ionization,
 Residential Tenancies Act
 (Victoria) 2021

**I declare that I am appropriately qualified and licensed to
 conduct this smoke alarm inspection**

Yes

**I declare that this inspection has been conducted in
 accordance with the applicable Australian Standards and
 Victorian legislation**

Yes

**I declare that the information recorded in this report is
 true and accurate to the best of my knowledge**

Yes

**I declare that the compliance assessment provided is
 based on the current condition of the smoke alarms at
 the time of inspection**

Yes

Signature Date

09/05/2026

Report Completion Date

09/05/2026

Report Template Version

3.0 - Smoke Only

General Comments

Additional compliance issues identified: secure alarm mounting.

Inspector Observations and Suggestions

Generated compliant demo report using local assets.

Declaration and Certification

This smoke compliance report summarises the inspection findings and certifies that the attending technician has performed the required checks and recommendations recorded below.

- AS 3786 Smoke Alarms
- Victorian rental smoke alarm annual check requirements
- Residential Tenancies Regulations 2021

I certify that this inspection has been conducted by a qualified inspector and the information contained in this report is true and accurate to the best of my knowledge at the time of inspection.

Inspector Certification:

Date: Saturday 9 May 2026

Next Compliance Schedule

Next Inspection Date Monday 8 May 2028

Regulations This smoke alarm safety inspection has been completed in accordance with the Residential Tenancies Regulations 2021 and AS 3786: Smoke Alarms. It confirms alarms are correctly installed, powered, and positioned to alert occupants in the event of a fire.

