

Pigging & Decoking

Pass Cleanliness sign off

Date: 9-26-26
Facility Name: Cenovus
Furnace Detail: HDS PF-175169 PASS# 1+2
Client Name: ALFREDO TREVINO
Operator Name: PETER Campbell



USA DEBUSK

1 Effluent Return

Should be very little and grey in color Should have rusty colored water confirming metal to metal contact.

2 Visual condition of cleaning pigs

Pigs should have no tracking or gouges and be smooth.

3 Condition of final white gauge foam

It should be smooth and show no signs of tracking

4 Flow Test Result

Initial Flow Test

Final Flow Test

RPM	PSI	GPM		RPM	PSI	GPM
1700	320	800		1550	267	800
1600	290	750		1463	238	750
1450	250	700		1385	215	700
1350	215	650		1276	184	650

Final test should show a decrease in PSI at the same GPM rate.
RPM Should be lower to reach the same GPM rate.

Debusk
Initials

Client
Initials

PC

PC

PC

Debusk signature

Customer Signature

DEBUSK
SERVICES CANADA

USA DEBUSK

Thanks you for the opportunity to provide pigging services to your facility.

Pigging & Decoking

Pass Cleanliness sign off

Date: 9/26/26

Facility Name: Cenoxus

Furnace Detail: HDS PR-175169

PASS# 3/4

Client Name:

Operator Name: Justin Kelly

1 Effluent Return

Should be very little and grey in color Should have rusty colored water confirming metal to metal contact.

2 Visual condition of cleaning pigs

Pigs should have no tracking or gouges and be smooth.

3 Condition of final white gauge foam

It should be smooth and show no signs of tracking

4 Flow Test Result

Initial Flow Test

Final Flow Test

RPM	PSI	GPM		RPM	PSI	GPM
1450	230	650		1290	180	650
1380	210	600		1190	170	600
1250	175	550		1090	140	550
1180	150	500		990	120	500

Final test should show a decrease in PSI at the same GPM rate.
RPM Should be lower to reach the same GPM rate.

USA DEBUSK

Thanks you for the opportunity to provide pigging services to your fac

Pigging & Decoking

Pass Cleanliness sign off

Date: 9-23-2021
Facility Name: CENOVUS
Furnace Detail: CRUDE PASS# 1
Client Name: ALFREDO TREVINO
Operator Name: PETER CAMPBELL

1 Effluent Return

Should be very little and grey in color Should have rusty colored water confirming metal to metal contact.

2 Visual condition of cleaning pigs

Pigs should have no tracking or gouges and be smooth.

3 Condition of final white gauge foam

It should be smooth and show no signs of tracking

4 Flow Test Result

Initial Flow Test

Final Flow Test

RPM	PSI	GPM		RPM	PSI	GPM
1650	310	750		1500	270	750
1500	285	700		1350	255	700
1400	250	650		1250	225	650
1300	210	600		1150	180	600

Final test should show a decrease in PSI at the same GPM rate.

RPM Should be lower to reach the same GPM rate.

USA DEBUSK

Thanks you for the opportunity to provide pigging services to your facility

Pigging & Decoking

Pass Cleanliness sign off

Date: 9-23-2026
Facility Name: Cenorus
Furnace Detail: crude PASS# 2
Client Name: _____
Operator Name: Justin Kelly

1 Effluent Return

Should be very little and grey in color Should have rusty colored water confirming metal to metal contact.

2 Visual condition of cleaning pigs

Pigs should have no tracking or gouges and be smooth.

3 Condition of final white gauge foam

It should be smooth and show no signs of tracking

4 Flow Test Result

Initial Flow Test

Final Flow Test

RPM	PSI	GPM		RPM	PSI	GPM
1680	315	750		1600	280	750
1550	295	700		1460	270	700
1480	270	650		1320	255	650
1360	230	600		1200	210	600

Final test should show a decrease in PSI at the same GPM rate.

RPM Should be lower to reach the same GPM rate.

USA DEBUSK

Thanks you for the opportunity to provide pigging services to your facility.

Pigging & Decoking

Pass Cleanliness sign of

Date: 9-23-2024
Facility Name: Cenovus
Furnace Detail: crude PASS# 3
Client Name: _____
Operator Name: ~~Don~~ Justin Kelly / Rodney Lynch

1 Effluent Return

Should be very little and grey in color Should have rusty colored water confirming metal to metal contact.

2 Visual condition of cleaning pigs

Pigs should have no tracking or gouges and be smooth.

3 Condition of final white gauge foam

It should be smooth and show no signs of tracking

4 Flow Test Result

Initial Flow Test

Final Flow Test

RPM	PSI	GPM		RPM	PSI	GPM

Final test should show a decrease in PSI at the same GPM rate.
RPM Should be lower to reach the same GPM rate.

DECOCKING DATA SHEET

CUSTOMER: Conoco

LOCATION: Lincoln OH

CONTACTS:

TOTALIZER VOLUME: Inter

SMART PIGGING: Inter

FILTRATION: Pass 3

DEBUSK

PIGGING & DECOCKING

PUMPER 5

LEFT (MIDDLE) RIGHT

PASS # 4

HEATER# Grade

FOOTAGE:

PIPE ID'S:

DATE 9/20/06 PAGE #

JOB #

PROJECT MANAGER: Peter Carroll

DAY SUPERVISOR:

NIGHT SUPERVISOR:

DAYS	OPERATOR LIST	NIGHTS

RPM	PIG FORCE PSI	DIGITAL PSI	GPM	HEATER NOTES:	RPM	PIG FORCE PSI	DIGITAL PSI	GPM
<u>1760</u> <u>1525</u>		<u>324</u>	<u>750</u>		<u>1700</u>		<u>295</u>	<u>750</u>
<u>1510</u>		<u>248</u>	<u>650</u>		<u>1480</u>		<u>230</u>	<u>650</u>
<u>1268</u>		<u>177</u>	<u>550</u>		<u>1250</u>		<u>165</u>	<u>550</u>
<u>1055</u>		<u>123</u>	<u>450</u>		<u>1000</u>		<u>115</u>	<u>450</u>



TEST OPERATOR NAME: Jeremiah Harman

SIGNATURE: Jeremiah Harman

CONFIRM MANUAL BY-PASS IS CLOSED Yes

TEST OPERATOR NAME: Adrian Curran

SIGNATURE: Adrian Curran

CONFIRM MANUAL BY-PASS IS CLOSED Yes

DECOCKING DATA SHEET

CUSTOMER: _____

LOCATION: Lima

CONTACTS: _____

TOTALIZER VOLUME: _____

SMART PIGGING: Info

FILTRATION: Yes Pass 3

DEBUSK

PIGGING & DECOCKING

PUMPER TriMax 5

(LEFT) MIDDLE / RIGHT

PASS # 5

HEATER# Grade PR 17 0028

FOOTAGE: _____

PIPE ID'S: _____

DATE 9/20/26 PAGE # _____

JOB # _____


PROJECT MANAGER Peter Campbell

DAY SUPERVISOR _____

NIGHT SUPERVISOR James McDaniel

DAYS	OPERATOR LIST	NIGHTS

RPM	PIG FORCE PSI	DIGITAL PSI	GPM	HEATER NOTES:	RPM	PIG FORCE PSI	DIGITAL PSI	GPM
1525		270	750		1430	245		750
1345		215	650		1280	190		650
1155		155	550		1100	125		550
950		100	450		920	85		450



TEST OPERATOR NAME: James McDaniel

SIGNATURE: [Signature]

CONFIRM MANUAL BY-PASS IS CLOSED [Signature]

TEST OPERATOR NAME: [Signature]

SIGNATURE: [Signature]

CONFIRM MANUAL BY-PASS IS CLOSED [Signature]

Pigging & Decoking

Pass Cleanliness sign off

Date: 9/18/2016
Facility Name: Cenaves Lima
Furnace Detail: Coude Heater PASS# 16
Client Name:
Operator Name: Isidore LeBlanc / Peter Campbell



USA DEBUSK

1 Effluent Return

Should be very little and grey in color Should have rusty colored water confirming metal to metal contact.

2 Visual condition of cleaning pigs

Pigs should have no tracking or gouges and be smooth.

3 Condition of final white gauge foam

It should be smooth and show no signs of tracking

4 Flow Test Result

Debusk
Initials

Client
Initials

AMG

AT

AMG

AT

AMG

AT

Initial Flow Test

RPM	PSI	GPM		RPM	PSI	GPM
1800	200	800		1655	285	800
1600	280	700		1480	295	700
1400	240	600		1265	205	600
1300	215	500		1110	185	500

Final Flow Test

Final test should show a decrease in PSI at the same GPM rate.
RPM Should be lower to reach the same GPM rate.

Debusk signature

Customer Signature

USA DEBUSK

Thanks you for the opportunity to provide pigging services to your facility.

DEBUSK
SERVICES CANADA

Pigging & Decoking

Pass Cleanliness sign off

Date: 9/18/26
Facility Name: Leavine Lignite
Furnace Detail: Crude unit PASS# 7
Client Name: _____
Operator Name: Rodney Lynch



USA DEBUSK

1 Effluent Return

Should be very little and grey in color Should have rusty colored water confirming metal to metal contact.

2 Visual condition of cleaning pigs

Pigs should have no tracking or gouges and be smooth.

3 Condition of final white gauge foam

It should be smooth and show no signs of tracking

4 Flow Test Result

Initial Flow Test

Final Flow Test

RPM	PSI	GPM		RPM	PSI	GPM
1815	290	800		1600	265	400
1625	265	700		1485	240	700
1375	230	600		1215	205	600
1295	200	500		1120	175	500

Final test should show a decrease in PSI at the same GPM rate.
RPM Should be lower to reach the same GPM rate.

Debusk
Initials

Client
Initials

RL

AT

RL

AT

RL

AT

Debusk signature

Customer Signature

DEBUSK
SERVICES CANADA

USA DEBUSK

Thanks you for the opportunity to provide pigging services to your facility.

DECOKING DATA SHEET

CUSTOMER: *Genovus*

LOCATION: *Lima*

CONTACTS:

TOTALIZER VOLUME:

SMART PIGGING:

FILTRATION:

DEBUSK

PIGGING & DECOKING

PUMPER:

(LEFT / MIDDLE / RIGHT)

PASS # *8*

HEATER# *Crude*

FOOTAGE:

PIPE ID'S:

DATE: _____ PAGE # _____

JOB # _____

PROJECT MANAGER: _____

DAY SUPERVISOR: _____

NIGHT SUPERVISOR: _____

DAYS	OPERATOR LIST	NIGHTS

RPM	PIG FORCE PSI	DIGITAL PSI	GPM	HEATER NOTES:	RPM	PIG FORCE PSI	DIGITAL PSI	GPM
1700		250	800		1650		221	800
1500		220	700		1425		190	700
1300		200	600		1250		165	600
1100		160	500		1025		100	500

PRE DECOKE FLOW TEST

BLUE $\longleftrightarrow$ RED

POST DECOKE FLOW TEST

BLUE $\longleftrightarrow$ RED

TEST OPERATOR NAME: *Brady LeBlanc*

SIGNATURE: *Brady LeBlanc*

CONFIRM MANUAL BY-PASS IS CLOSED

TEST OPERATOR NAME: *Brady LeBlanc*

SIGNATURE: *Brady LeBlanc*

CONFIRM MANUAL BY-PASS IS CLOSED

0.00

Pigging & Decoking

Pass Cleanliness sign off

Date: 4-27-20
Facility Name: Cenovus
Furnace Detail: Coker All
Client Name: Kelly Kuhlman
Operator Name: Justin Kelly

1 Effluent Return

Should be very little and grey in color Should have rusty colored water confirming metal to metal contact.

2 Visual condition of cleaning pigs

Pigs should have no tracking or gouges and be smooth.

3 Condition of final white gauge foam

It should be smooth and show no signs of tracking

4 Flow Test Result

Initial Flow Test			Final Flow Test			
RPM	PSI	GPM		RPM	PSI	GPM
1750	435	350		1600	375	350
1510	330	300		1360	290	300
1240	220	250		1145	180	250
1025	153	200		950	120	200

Final test should show a decrease in PSI at the same GPM rate.
RPM Should be lower to reach the same GPM rate.

USA DEBUSK

Thanks you for the opportunity to provide pigging services to your facility.

Pigging & Decoking

Pass Cleanliness sign off

Date: 9-27-20
Facility Name: cenovus
Furnace Detail: coker PASS# C+D
Client Name: Kelly Kuhlman
Operator Name: James McDaniel

1 Effluent Return

Should be very little and grey in color Should have rusty colored water confirming metal to metal contact.

2 Visual condition of cleaning pigs

Pigs should have no tracking or gouges and be smooth.

3 Condition of final white gauge foam

It should be smooth and show no signs of tracking

4 Flow Test Result

Initial Flow Test				Final Flow Test		
RPM	PSI	GPM		RPM	PSI	GPM
1783	419	350		1514	287	350
1555	320	300		1314	219	300
1295	223	250		1114	159	250
1035	142	200		904	108	200

Final test should show a decrease in PSI at the same GPM rate.
RPM Should be lower to reach the same GPM rate.

USA DEBUSK

Thanks you for the opportunity to provide pigging services to your facility.

US

Debu

Cus

75.2