


Final Assembly Reporting and Maintenance System Features






Production Report Monitoring and Management

Reports









3D Objects Rendering (Lectures for Newly Hired)

Pan the 3d Object by using your mouse and mouse scroll. Press F11 to full screen.



Illustrated by: Aldrin Garces

Chat Feature for faster Communication Across Production Area



Locator Board for Manpower and Work Assignment Monitoring












Signed in as: Earl Gerald

Reports













Schedule for Repairs

Signed in as: Earl Gerald

For Scheduling

Search:

Conveyor ↑↓	Shift ^{↑↓}	Tools/Machine	Trouble ^{↑↓}	Details ↑↓	Note/ Findings	Date Reported †↓	Reported By 1	Incharge 11
E02	A	Sub-Assy Hanger (Sub Assy Navigation Station) Malfunction		SSC PALLET #12 ALL STATION	NAVIGATION MALFUNCTION SA SSC PALLET	2023-03-07	Jaena Saquisame	Lance Edwin Pica
E04	В	Clip/ Clamp Attachment Others		broken traverse holder		2023-03-13	Shirley Lomboy	
E04	В	SSC Pallet Others		bagon #9,14,12 ayaw tumakbo sa kadena	DUMUDULAS ANG BOLT SA KADENA	2023-02-17	Cristeta Celestino	Javier Baguidudol
E05	Α	Parts Tray	Others	NO PARTS TRAY NUMBER	Change diameter	2022-12-10	Lea Saratan	Francis Aniel
E05	A	Jigboard Others		ALL J/B conn # 61 wrong wire color	CONN. #61WRONG WIRE COLOR ON CONN. INSERTION GUIDE	2022-12-10	Lea Saratan	Javier Baguidudol
E07	Α	Appearance Board	Others	SIRA NA YUNG PLASTIC NG TABLE NG PACKING	NO PLASTIC TABLE ON PACKING	2023-03-03	Royaliza Diato	Christian Mendoza
H02	Α	Finishing Board	Others	sira na yung gutter, pakisabay na yung gutter ng lay outing ng mainboard	FOR REPLACEMENT GUTTER	2023-02-21	Royaliza Diato	Jonuel Edillo
H02	В	Bigsub Board	Detached Holder	bagon 5	MISSING CONN. HOLDER	2023-02-18	Lovella Velando	Javier Baguidudol
H02	Α	Sub-Assy Hanger (Sub Assy Station)	Navigation Malfunction	BAGON NO.23,22,1,7,10,6,5,4 ACO1 /BAGON NO.20,12,8 AC02	SCHEDULE FOR COMPANY HOLIDAY	2023-02-08	Royaliza Diato	CHRISTIAN MENDOZA
H04	В	Appearance Board Others		mga wiring sa ilalim ng board ay nakalawit pinalalagyan ng cover at sa fese checker mga wiring din l	AUDIT FINDINGS	2023-02-24	Geraldine Capili	Patrick Lee

Showing 1 to 10 of 85 entries

Previous 1 2 3 4 5 ... 9 Next



































Parts Ordering Monitoring and Tracking

Processed Orders 60

Search: CSV Excel PDF Print Column visibility • Reference ↑↓ RFO ↑↓ Conveyor ↑ Supplier ltem Part Number Quantity Arrival Date Incharge Status 111 N23 PROTECTOR HOLDER 76-2852 5 SJS 2022-09-26 Received Action -Jhun Carlo PR2303-Camacho 10067 14 SJS H07 CLIP HOLDER, PU 7047-7787-OT 2022-09-27 Arnold Received Action -PR2303-Loste 10320 1549 N41 SSC HOLDER WITH CYLINDRICAL MAGNET 1PC PCB (1-39 CAVITIES) 7287-1918 2 GT JIGS 2022-10-04 Ronald Received Action -PR2303-Naval 11606 CONNECTOR HOLDER 3 GT-JIGS 1634 N13 7383-4673-30A S2 2022-10-17 Received Sydney Action -PR2303-Sam Oasay 11682 1631 N42 SSC HOLDER WITH CYLINDRICAL MAGNET 1PC PCB (1-39 CAVITIES) 7289-8063-30 3 COBARRUBIAS 2022-10-17 Sydney Received PR2303-Sam Oasay 12279 2 1635 N51 PROTECTOR HOLDER, PU 7176-3432-00 JAPAN 2022-10-17 Mar Francis Received Action * PR2303-Decena 12671 N12 CLAMP CHECKER FOR CIRCUIT 7052-7194-30 MF 2022-10-19 Mar Francis Received Action -PR2303-Decena 14168 N22 CONNECTOR HOLDER, REVISED 6.2 WITH TPO GUAGE 7289-7428-10 BPC 2022-10-13 Ronnie 1594 Received Action -PR2303-Fermin 14206 E05 CLIP HOLDER 47-7666-30 3J Neil 2022-10-12 Received Action -PR2303-Alexander 14218 Organista MF 2022-10-19 N24 PROTECTOR HOLDER 7176-1618-04 Received Action -Diego












































Trouble Reports Generation









Date Range: Mar-14-2023 - Mar-14-2023


	PRODUCTION										_		
Reference Code	Date	Shift	Conveyor	Carline	Harness Code	Process/ Machine	Problem	Details	Report Classification	Reported By	Time Reported (a)	Real Cause	Counter Measure
PR2303-53470	2023-03-14 00:03:04	Α	ND3	Nissan	MR15-E POWER	Mainboard Conveyor	Motor Malfunction	malfunction	Breakdown	Theresa	12:03	out of timing	Reset To Homeposition
PR2303-53471	2023-03-14 00:06:06	Α	N83	Toyota	798W/792W	Sub-Assy Hanger (Sub Assy Station)	Navigation Malfunction	FS ATTACHMENT.	Breakdown	Edison	12:06	loose inspection wire	Fixed
PR2303-53473	2023-03-14 00:20:57	Α	N71	Toyota	738W/776W	Circuit Continuity Board T-CKT-1018-06	Others	7052-7335 CLIP CHECKER AYAW MAMATAY	Breakdown	Remedios	12:20	CIRCUIT B PIN SWITCH STUCK UP ON CLIP CHECKER	Fixed
PR2303-53475	2023-03-14 00:47:16	Α	NB1	D2UC	BODY	Rectangular Conveyor	Out of Timing	J/B 8	Breakdown	Desiree	12:47	OUT OF TIMING	Reset To Homeposition
PR2303-53479	2023-03-14 01:02:13	Α	N71	Toyota	738W/776W	Sub-Assy Hanger (Sub Assy Station)	Navigation Malfunction	AA1	Breakdown	Carol	01:02	SHORTED NAVI LIGHT	Replaced Navigation Light
PR2303-53480	2023-03-14 01:10:00	Α	N31	Toyota	828/721/ 831/792W	Jigboard	Detached Holder	conn.#84 jb #5	Breakdown	Yolanda	01:10	damaged holder	Checked
PR2303-53481	2023-03-14 01:12:40	Α	N22	Toyota	721/770/792W	SSC Conveyor	Others	s/a puller maif.	Breakdown	Lorena	01:12	out of timing	Reset To Homeposition
PR2303-53482	2023-03-14 01:23:01	Α	S12	Toyota	879W/885W/886W	Circuit Continuity Board T-CKT-71321-10	Open Points	STUCK-UP PIN	Breakdown	Marissa	01:23	BUSTED PIN SWITCH	Replaced Pin Switch
PR2303-53483	2023-03-14 01:28:08	Α	N62	Toyota	792W	SSC Pallet	Others	pallet no. 1 navi malfunction	Breakdown	Marilyn	01:28	un allign family seal on pallet	Aligned
PR2303-53485	2023-03-14 01:36:53	Α	NC1	D2UC	BODY	Jigboard	Detached Holder	conn 26 jigboard 16 side a	Breakdown	Emelita	01:36	DETACHED HOLDER	Replaced
PR2303-53486	2023-03-14 01:52:24	Α	NB1	D2UC	BODY	Rectangular Conveyor	Out of Timing	j/b8	Breakdown	Milagros	01:52	NASABIT ANG BEARING SA GUIDE NG SHIFTER	Adjusted
PR2303-53487	2023-03-14 01:53:35	Α	S73	Toyota	738W/751W RHD HV	Circuit Continuity Board	Open Points	conn. 110	Breakdown	Mary Ann	01:53	OPEN POINTS	Fixed Wiring
PR2303-53489	2023-03-14 01:59:09	Α	N71	Toyota	738W/776W	Appearance Board T-APP-1018-05	Others	AIRLEAK BUTTON -MAHIRAP PINDUTIN	Breakdown	Marites	01:59	defective start button switch	Replaced
PR2303-53495	2023-03-14 02:18:40	Α	S73	Toyota	738W/751W RHD HV	Appearance Board T-APP-0918-02	Ok Marker Malfunction	incomplete 0k mark	Breakdown	Edeliza	02:18	INCOMPLETE OK MARKER	Refilled
PR2303-53497	2023-03-14 02:26:44	Α	N62	Toyota	792W	Appearance Board T-APP-21621-04	Others	airleak malfunction conn #92	Breakdown	Marilyn	02:26	cut connecting wire	Replaced Connecting Wire
					·	I				L	I ,		






Machine Downtime Summary With Trend Analysis




































Overtime Submission & Monitoring
























Engineering Overtime

Production Overtime

Showing 1 to 10 of 17 entries



Overtime History



Overtime 17

Copy CSV PDF Print Column visibility ▼					Search:
Conveyor	Start 11	Finish 14	Shift	Submitted By	11
E03	17:00:00	18:00:00	А	Lydia Baon	
H05	17:00:00	19:00:00	A	Madonna Gatchalian	
N23	17:00:00	19:00:00	В	Elisa Sayaman	
N32	17:00:00	19:00:00	В	Ma. Salva Camamhot	
N41	17:00:00	19:00:00	В	Annaliza Crisostomo	
N62	17:00:00	19:00:00	В	Analiza Amisoga	
N71	17:00:00	19:00:00	В	Pilita Manucom	
NB1	17:00:00	19:00:00	В	Analiza Pajares	
ND1	17:00:00	19:00:00	В	Lorilie Amoguis	
542	17:00:00	18:00:00		Alejandrea Munsayac	



































Tools, Machine and Equipment with Fixed Asset(Capital Equipment) Monitoring

Tools, Machines and Equipments

HONDA TLAX RHD

NISSAN P42M TR7




Signed in as: Earl Gera

letired Machines 🌙 🥬 Under Repair 📁 🗏 Stockro

NISSAN KH1 IR2 ICE/ E. DOM

Retired Machines

































































Functional











40-1744


Production Monitor

List of Capital Equipment									
	Tag Number	Machine	Location	Acquisition Date	Status	Action			
	40-3375	Grommet Expander Machine - Both Side	S61	2020-06-05	Functional	O			
	40-3379	Silicon Machine	S61	2020-06-05	Functional	O			
	40-3373	Water Leak Machine	S61	2020-06-05	Functional	O			
	40-2611	Fuse Checking Machine	NB1	2016-06-01	Functional	O			
	40-2675	Grommet Expander Machine - Big	NB1	2022-07-02	Functional	O			
	40-2547	Grommet Expander Machine - Big	NC1	2015-08-25	Functional	O			
	40-2575	Grommet Expander Machine - Big	NC1	2022-07-02	Functional	O			
	40-2598	Grommet Expander Machine - Big	NC1	2016-04-05	Functional	O			
	40-2668	Grommet Expander Machine - Big	NB1	2016-09-12	Functional	O			
	40-2595	Grommet Expander Machine - Big	NB1	2016-04-05	Functional	O			
	40-1766	Production Monitor	PEMTA Stockroom	2006-03-15	Functional	O			
	40-2756	Grommet Expander Machine - Big	W01	2017-06-09	Functional	O			
	82-0226	Vacuum Machine	N32	2022-07-02	Functional	O			

N42


2007-07-31

Machine Trouble History



Waiting for cache...





Output- Engineering

Output - Production

BE INFORMED THAT FGVS /SISV COMPUTERS AT APPEARANCE AND C