



STR Photo-01, View of 2-anchor roof hanger plate that has begun to pull away from the tunnel roof in the westbound D Street portal tunnel after the accident