



STR Photo-04, View of 2-anchor roof hanger plates that have begun to pull away from the tunnel roof in the westbound D Street portal tunnel after the accident