PROPERTY CONDITION ASSESSMENT

Prepared for: Buckeye Industrial Properties, LLC

Inspection Date: 01/18/2026

Report Date: 03/15/2026

Insured Buckeye Industrial Properties, LLC	Policy Number CP-BIP-2025-4420
Address 6500 Alum Creek Drive	City, State, ZIP Columbus, OH 43217
SIC Code 6512	Inspector S. Martinez, PE

OVERALL RISK GRADE: Average

Grading Scale: Travelers Risk Assessment

LOCATIONS INSPECTED

Location 1: Rickenbacker Logistics Center - A
Address: 6500 Alum Creek Drive, Columbus, OH 43217
Construction: Non-Combustible • Year Built: 2014 • Stories: 1 • Sprinklered: Yes • Protection Class: 1

Location 2: Rickenbacker Logistics Center - B
Address: 6600 Alum Creek Drive, Columbus, OH 43217
Construction: Non-Combustible • Year Built: 2016 • Stories: 1 • Sprinklered: Yes • Protection Class: 5

Location 3: Cleveland Distribution Hub
Address: 4800 Tiedeman Road, Brooklyn, OH 44144
Construction: Non-Combustible • Year Built: 2008 • Stories: 1 • Sprinklered: Yes • Protection Class: 3

Location 4: Dayton Manufacturing Facility
Address: 2100 Kuntz Road, Dayton, OH 45404
Construction: Joisted Masonry • Year Built: 1992 • Stories: 1 • Sprinklered: Yes • Protection Class: 4

Location 5: Cincinnati Cross-Dock Terminal
Address: 11600 Mosteller Road, Cincinnati, OH 45241
Construction: Non-Combustible • Year Built: 2019 • Stories: 1 • Sprinklered: Yes • Protection Class: 4

Location 6: Toledo Industrial Park - Building 1
Address: 3200 Hill Avenue, Toledo, OH 43607
Construction: Masonry Non-Combustible • Year Built: 2004 • Stories: 1 • Sprinklered: Yes • Protection Class: 5

Location 7: Toledo Industrial Park - Building 2

Address: 3250 Hill Avenue, Toledo, OH 43607
Construction: Masonry Non-Combustible • Year Built: 1998 • Stories: 1 • Sprinklered: No • Protection Class: 3

Location 8: Akron Flex Space
Address: 1475 Corporate Woods Parkway, Uniontown, OH 44685
Construction: Non-Combustible • Year Built: 2011 • Stories: 1 • Sprinklered: Yes • Protection Class: 4

Location 9: Corporate Administrative Office
Address: 250 Civic Center Drive, Suite 600, Columbus, OH 43215
Construction: Fire Resistive • Year Built: 2006 • Stories: 1 • Sprinklered: Yes • Protection Class: 1

EXECUTIVE SUMMARY

An on-site inspection was conducted at 9 location(s) for Buckeye Industrial Properties, LLC. The survey assessed fire protection, building construction, occupancy hazards, and general risk management practices. The overall risk grade assigned is Average on the Travelers Risk Assessment scale.

PURPOSE AND SCOPE

This assessment was conducted in accordance with standard industry practices to evaluate the physical condition, fire protection adequacy, and risk exposure of the subject property. The scope includes visual inspection of all accessible areas, review of available documentation, and interviews with on-site management.

SITE ASSESSMENT

Paving / Parking Good	Landscaping Good
Drainage Fair	Fencing / Security Fair

STRUCTURAL FRAME & BUILDING ENVELOPE

Foundation Fair	Exterior Walls Good
Windows / Doors Good	Building Envelope Integrity Deteriorating

ROOFING

Roof Type Shingle	Roof Age 14 years

Condition Rating
Poor

Estimated Remaining Useful Life
0 years

PLUMBING

Water Supply
Fair

Waste / Drain
Deteriorating

Water Heaters
Electric

Pipe Material
PVC

HEATING, VENTILATION & AIR CONDITIONING

HVAC System Type
Split System

System Condition
Needs Service

System Age
18 years

Maintenance Program
Yes

ELECTRICAL

Service Entrance
400 Amp

Panel Condition
Fair

Emergency / Standby Power
No

GFCI Protection
Yes

FIRE PROTECTION SYSTEMS

Automatic sprinkler system: Wet Pipe, N/A coverage
Last inspection: 1 months ago — NFPA 25 compliant
Fire extinguishers: 11 units, some tags expired

CAPITAL EXPENDITURE FORECAST

System	Immediate (Yr 0)	Short-Term (Yr 1-2)	Reserve (Yr 3-12)
Plumbing	$4,147.00	$9,627.00	$334,094.00
Roofing	$21,480.00	$28,469.00	$385,980.00
Fire Protection	$38,234.00	$79,399.00	$167,216.00

PHOTOGRAPHIC DOCUMENTATION

Photo 1: Roof condition (aerial or ladder view) [Image Reference: IMG-1359]
Photo 2: Fire protection equipment [Image Reference: IMG-6450]

Photo 3: Electrical panel room [Image Reference: IMG-3529]

Photo 4: Rear of building [Image Reference: IMG-8431]

Photo 5: Front of building — street view [Image Reference: IMG-9095]

Photo 6: Storage area — housekeeping conditions [Image Reference: IMG-8040]