NSPIRE PHYSICAL INSPECTION REPORT

Multifamily (Project-Based Rental Assistance)

(Simplified model of a REAC NSPIRE report - not an official HUD form)

Property	Bellmont Terrace, 77 Tinderbox Court, Wexmoor, OH 45000
Contract	DEMO-PBRA-0412
Inspection date	08/31/2026
Score	74
Units inspected	1A, 1B, 1C, 1D + site and common areas

Deficiencies

Unit	Location	Deficiency	Severity	Correct by	Corrected
1B	Unit - utility closet	Water heater - leaking into drip pan	Moderate	09/30/2026	-
1D	Unit - bathroom	GFCI outlet inoperable	Severe	09/01/2026	09/01/2026
Site	Walkway, bldg entry	Sidewalk trip hazard (3/4 in. vertical)	Moderate	09/30/2026	-
1A	-	No deficiencies	-	-	-
1C	-	No deficiencies	-	-	-

Owner must correct Severe deficiencies within 24 hours and Moderate deficiencies within 30 days, and certify all corrections to the contract administrator by the correction date.

OWNER CERTIFICATION OF REPAIRS - STATUS

Certification due	09/30/2026
Report printed	10/01/2026
Status	NOT RECEIVED
Items outstanding	1B water heater; site sidewalk trip hazard

Failure to certify may result in a follow-up inspection and referral for enforcement.

SYNTHETIC TEST DATA - fictional properties and people; simplified model forms, not official HUD forms. Abstractly test fixture.