

P. S. 73-91

Week of: _____ Date Received: 1/25/91

LASER PERFORATED TIPPING APPEARANCE CHECK
HOLE DEPTH, SCORCHING, CRATERING

Module: 412 Brand: CARLTON Filter 100's - 4 Mg Laser
Shift & Date: _____ Mfg. for Taiwan
Pulse: _____ Power: _____

FRONT CIGARETTES

Hole Depth: <1 mm 13.0 mm from end
Scorching : Insignificant.
Cratering : None to insignificant.
Comments : Excellent appearance (18 holes).

BACK CIGARETTES

Hole Depth: <1 mm 13.0 mm from end
Scorching : Insignificant.
Cratering : None to insignificant.
Comments : Excellent appearance (18 holes).

Module: _____ Brand: _____
Shift & Date: _____ Pulse: _____ Power: _____

FRONT CIGARETTES

Hole Depth: _____
Scorching : _____
Cratering : _____
Comments : _____

BACK CIGARETTES

Hole Depth: _____
Scorching : _____
Cratering : _____
Comments : _____

ATX02 0062194