

Prüfbericht – BatteryMS-12 EV Plattform – Labor TUV Rheinland Koeln

Pruefergebnis

| Norm      | Pruefpunkt | Sollwert | Istwert   | Ergebnis |
|-----------|------------|----------|-----------|----------|
| ISO 85838 | Test 1     | 28.7 Ref | 19.0 Meas | PASS     |
| ISO 37205 | Test 2     | 96.8 Ref | 35.0 Meas | PASS     |
| ISO 21015 | Test 3     | 65.8 Ref | 90.1 Meas | PASS     |
| ISO 88142 | Test 4     | 97.5 Ref | 28.0 Meas | FAIL     |
| ISO 82341 | Test 5     | 76.1 Ref | 36.8 Meas | PASS     |
| ISO 24268 | Test 6     | 91.6 Ref | 38.1 Meas | PASS     |
| ISO 95601 | Test 7     | 92.9 Ref | 10.8 Meas | FAIL     |
| ISO 90919 | Test 8     | 55.1 Ref | 47.9 Meas | FAIL     |
| ISO 39919 | Test 9     | 24.0 Ref | 67.4 Meas | PASS     |
| ISO 26872 | Test 10    | 19.8 Ref | 28.1 Meas | PASS     |