

Preliminary Map Report

A final EDR Report will be delivered after quality review is conducted.




Nationwide Customer Service

Telephone: 1-800-352-0050

Internet: www.edrnet.com

GeoServices, LLC
765 Mickey Lane
Orlando, FL 32830

May 03, 2025



★ Target Property

▲ Sites



National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

PRELIMINARY EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

765 MICKEY LANE
ORLANDO, FL 32830

COORDINATES

Latitude (North):	28.3864020 - 28° 23' 11.04"
Longitude (West):	-81.5720840 - -81° -34' -19.50"
Universal Transverse Mercator:	Zone 17
UTM X (Meters):	443953.0
UTM Y (Meters):	3140140.0

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property:	ORLANDO, FL
Source:	U.S. Geological Survey

SEARCH RESULTS

Sites were identified.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal RCRA generators

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small

PRELIMINARY EXECUTIVE SUMMARY

quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 02/17/2025 has revealed that there is 1 RCRA-VSQG site within approximately 0.75 miles of the target property.

Lists of state and tribal leaking storage tanks

LAST: The file for Leaking Aboveground Storage Tanks. Please remember STCM does not track the source of the discharge so the agency provides a list of facilities with an aboveground tank and an open discharge split by facilities with aboveground tanks only and facilities with aboveground and underground tanks.

A review of the LAST list, as provided by EDR, and dated 01/21/2025 has revealed that there is 1 LAST site within approximately 1 mile of the target property.

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Environmental Protection's PCTO1--Petroleum Contamination Detail Report.

A review of the LUST list, as provided by EDR, and dated 01/21/2025 has revealed that there are 2 LUST sites within approximately 1 mile of the target property.

Lists of state and tribal registered storage tanks

UST: The Underground Storage Tank database contains registered USTs. Shortly after the September 11 event, the DEP was instructed to remove the detail about some of the storage tank facilities in the state from their reports. Federal-owned facilities and bulk storage facilities are included in that set.

A review of the UST list, as provided by EDR, has revealed that there are 2 UST sites within approximately 0.75 miles of the target property.

AST: Shortly after the Sept 11 event, the DEP was instructed to remove the detail about some of the storage tank facilities in the state from their reports. Federal-owned facilities and bulk storage facilities are included in that set.

A review of the AST list, as provided by EDR, has revealed that there are 2 AST sites within approximately 0.75 miles of the target property.

ADDITIONAL ENVIRONMENTAL RECORDS

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or

PRELIMINARY EXECUTIVE SUMMARY

dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 02/17/2025 has revealed that there is 1 RCRA NonGen / NLR site within approximately 0.75 miles of the target property.

UST FINDER: EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories. UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

A review of the UST FINDER list, as provided by EDR, and dated 06/08/2023 has revealed that there are 2 UST FINDER sites within approximately 0.75 miles of the target property.

UST FINDER RELEASE: US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

A review of the UST FINDER RELEASE list, as provided by EDR, and dated 06/08/2023 has revealed that there are 2 UST FINDER RELEASE sites within approximately 1 mile of the target property.

DWM CONTAM: A listing of active or known sites. The listing includes sites that need cleanup but are not actively being working on because the agency currently does not have funding (primarily petroleum and drycleaning).

A review of the DWM CONTAM list, as provided by EDR, and dated 07/14/2023 has revealed that there are 2 DWM CONTAM sites within approximately 1 mile of the target property.

HAZ WASTE: The records in this data set are generated by county SQG Assessment, Notification and Verification Programs on-site surveys (see 403.7225 FS). The waste records are wastes observed during county inspections. Even though this state program targets SQGs and VSQGs for outreach, some counties choose to additionally look at their LQGs.

A review of the HAZ WASTE list, as provided by EDR, and dated 02/10/2025 has revealed that there is 1 HAZ WASTE site within approximately 0.75 miles of the target property.

UIC: A listing of Class I wells. Class I wells are used to inject hazardous waste, nonhazardous waste, or municipal waste below the lowermost USDW.

A review of the UIC list, as provided by EDR, and dated 01/10/2025 has revealed that there are 2 UIC sites within approximately 0.5 miles of the target property.

PRELIMINARY EXECUTIVE SUMMARY

NPDES: Domestic and Industrial Wastewater Facilities

A review of the NPDES list, as provided by EDR, and dated 01/27/2025 has revealed that there is 1 NPDES site within approximately 0.5 miles of the target property.

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there is 1 EDR Hist Auto site within approximately 0.625 miles of the target property.

PRELIMINARY EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 0 records
There were no unmapped sites in this report.

PRELIMINARY MAP FINDINGS SUMMARY

<u>Database</u>	<u>Search Distance (Miles)</u>	<u>Target Property</u>	<u>< 1/8</u>	<u>1/8 - 1/4</u>	<u>1/4 - 1/2</u>	<u>1/2 - 1</u>	<u>> 1</u>	<u>Total Plotted</u>
<u>STANDARD ENVIRONMENTAL RECORDS</u>								
<i>Lists of Federal NPL (Superfund) sites</i>								
NPL	1.500		0	0	0	0	0	0
Proposed NPL	1.500		0	0	0	0	0	0
NPL LIENS	1.500		0	0	0	0	0	0
<i>Lists of Federal Delisted NPL sites</i>								
Delisted NPL	1.500		0	0	0	0	0	0
<i>Lists of Federal sites subject to CERCLA removals and CERCLA orders</i>								
FEDERAL FACILITY	1.000		0	0	0	0	NR	0
SEMS	1.000		0	0	0	0	NR	0
<i>Lists of Federal CERCLA sites with NFRAP</i>								
SEMS-ARCHIVE	1.000		0	0	0	0	NR	0
<i>Lists of Federal RCRA facilities undergoing Corrective Action</i>								
CORRACTS	1.500		0	0	0	0	0	0
<i>Lists of Federal RCRA TSD facilities</i>								
RCRA-TSDF	1.000		0	0	0	0	NR	0
<i>Lists of Federal RCRA generators</i>								
RCRA-LQG	0.750		0	0	0	0	NR	0
RCRA-SQG	0.750		0	0	0	0	NR	0
RCRA-VSQG	0.750		0	0	0	1	NR	1
<i>Federal institutional controls / engineering controls registries</i>								
LUCIS	1.000		0	0	0	0	NR	0
US ENG CONTROLS	1.000		0	0	0	0	NR	0
US INST CONTROLS	1.000		0	0	0	0	NR	0
<i>Federal ERNS list</i>								
ERNS	0.500		0	0	0	NR	NR	0
<i>Lists of state- and tribal hazardous waste facilities</i>								
SHWS	1.500		0	0	0	0	0	0
<i>Lists of state and tribal landfills and solid waste disposal facilities</i>								
SWF/LF	1.000		0	0	0	0	NR	0
<i>Lists of state and tribal leaking storage tanks</i>								
LAST	1.000		0	0	0	1	NR	1

PRELIMINARY MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LUST	1.000		0	0	0	2	NR	2
INDIAN LUST	1.000		0	0	0	0	NR	0
<i>Lists of state and tribal registered storage tanks</i>								
FF TANKS	0.750		0	0	0	0	NR	0
FEMA UST	0.750		0	0	0	0	NR	0
UST	0.750		0	0	0	2	NR	2
AST	0.750		0	0	0	2	NR	2
INDIAN UST	0.750		0	0	0	0	NR	0
TANKS	0.750		0	0	0	0	NR	0
<i>State and tribal institutional control / engineering control registries</i>								
ENG CONTROLS	1.000		0	0	0	0	NR	0
INST CONTROL	1.000		0	0	0	0	NR	0
<i>Lists of state and tribal voluntary cleanup sites</i>								
VCP	1.000		0	0	0	0	NR	0
INDIAN VCP	1.000		0	0	0	0	NR	0
<i>Lists of state and tribal brownfield sites</i>								
BROWNFIELDS	1.000		0	0	0	0	NR	0
<u>ADDITIONAL ENVIRONMENTAL RECORDS</u>								
<i>Local Brownfield lists</i>								
US BROWNFIELDS	1.000		0	0	0	0	NR	0
<i>Local Lists of Landfill / Solid Waste Disposal Sites</i>								
SWRCY	1.000		0	0	0	0	NR	0
INDIAN ODI	1.000		0	0	0	0	NR	0
ODI	1.000		0	0	0	0	NR	0
DEBRIS REGION 9	1.000		0	0	0	0	NR	0
IHS OPEN DUMPS	1.000		0	0	0	0	NR	0
<i>Local Lists of Hazardous waste / Contaminated Sites</i>								
US HIST CDL	0.500		0	0	0	NR	NR	0
PRIORITYCLEANERS	1.000		0	0	0	0	NR	0
FI Sites	1.500		0	0	0	0	0	0
US CDL	0.500		0	0	0	NR	NR	0
<i>Local Land Records</i>								
LIENS 2	0.500		0	0	0	NR	NR	0
<i>Records of Emergency Release Reports</i>								
HMIRS	0.500		0	0	0	NR	NR	0
SPILLS	0.500		0	0	0	NR	NR	0
SPILLS 90	0.500		0	0	0	NR	NR	0

PRELIMINARY MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
SPILLS 80	0.500		0	0	0	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.750		0	0	0	1	NR	1
FUDS	1.500		0	0	0	0	0	0
DOD	1.500		0	0	0	0	0	0
SCRD DRYCLEANERS	1.000		0	0	0	0	NR	0
US FIN ASSUR	0.500		0	0	0	NR	NR	0
EPA WATCH LIST	0.500		0	0	0	NR	NR	0
2020 COR ACTION	0.750		0	0	0	0	NR	0
TSCA	0.500		0	0	0	NR	NR	0
TRIS	0.500		0	0	0	NR	NR	0
SSTS	0.500		0	0	0	NR	NR	0
ROD	1.500		0	0	0	0	0	0
RMP	0.500		0	0	0	NR	NR	0
RAATS	0.500		0	0	0	NR	NR	0
PRP	0.500		0	0	0	NR	NR	0
PADS	0.500		0	0	0	NR	NR	0
ICIS	0.500		0	0	0	NR	NR	0
FTTS	0.500		0	0	0	NR	NR	0
MLTS	0.500		0	0	0	NR	NR	0
COAL ASH DOE	0.500		0	0	0	NR	NR	0
COAL ASH EPA	1.000		0	0	0	0	NR	0
PCB TRANSFORMER	0.500		0	0	0	NR	NR	0
RADINFO	0.500		0	0	0	NR	NR	0
HIST FTTS	0.500		0	0	0	NR	NR	0
DOT OPS	0.500		0	0	0	NR	NR	0
CONSENT	1.500		0	0	0	0	0	0
INDIAN RESERV	1.500		0	0	0	0	0	0
FUSRAP	1.500		0	0	0	0	0	0
UMTRA	1.000		0	0	0	0	NR	0
LEAD SMELTERS	0.500		0	0	0	NR	NR	0
US AIRS	0.500		0	0	0	NR	NR	0
US MINES	0.750		0	0	0	0	NR	0
MINES MRDS	0.500		0	0	0	NR	NR	0
ABANDONED MINES	0.750		0	0	0	0	NR	0
FINDS	0.500		0	0	0	NR	NR	0
UXO	1.500		0	0	0	0	0	0
ECHO	0.500		0	0	0	NR	NR	0
DOCKET HWC	0.500		0	0	0	NR	NR	0
FUELS PROGRAM	0.750		0	0	0	0	NR	0
PFAS NPL	0.750		0	0	0	0	NR	0
PFAS FEDERAL SITES	0.750		0	0	0	0	NR	0
PFAS TRIS	0.750		0	0	0	0	NR	0
PFAS TSCA	0.750		0	0	0	0	NR	0
PFAS RCRA MANIFEST	0.750		0	0	0	0	NR	0
PFAS ATSDR	0.750		0	0	0	0	NR	0
PFAS WQP	0.750		0	0	0	0	NR	0
PFAS NPDES	0.750		0	0	0	0	NR	0
PFAS PROJECT	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.750		0	0	0	0	NR	0

PRELIMINARY MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
PFAS ECHO FIRE TRAIN	0.750		0	0	0	0	NR	0
PFAS PT 139 AIRPORT	0.750		0	0	0	0	NR	0
AQUEOUS FOAM NRC	0.750		0	0	0	0	NR	0
BIOSOLIDS	0.500		0	0	0	NR	NR	0
UST FINDER	0.750		0	0	0	2	NR	2
UST FINDER RELEASE	1.000		0	0	0	2	NR	2
E MANIFEST	0.750		0	0	0	0	NR	0
PFAS	0.750		0	0	0	0	NR	0
AQUEOUS FOAM	0.750		0	0	0	0	NR	0
AIRS	0.500		0	0	0	NR	NR	0
ASBESTOS	0.500		0	0	0	NR	NR	0
CLEANUP SITES	0.500		0	0	0	NR	NR	0
DEDB	0.750		0	0	0	0	NR	0
DRYCLEANERS	0.750		0	0	0	0	NR	0
DWM CONTAM	1.000		0	0	0	2	NR	2
Financial Assurance	0.500		0	0	0	NR	NR	0
FL Cattle Dip. Vats	0.750		0	0	0	0	NR	0
HAZ WASTE	0.750		0	0	0	1	NR	1
HW GEN	0.750		0	0	0	0	NR	0
RESP PARTY	1.000		0	0	0	0	NR	0
SOLCP	0.500		0	0	0	NR	NR	0
SITE INV SITES	1.000		0	0	0	0	NR	0
TIER 2	0.500		0	0	0	NR	NR	0
UIC	0.500		0	0	2	NR	NR	2
NPDES	0.500		0	1	0	NR	NR	1
ERIC WASTE CLEANUP	0.500		0	0	0	NR	NR	0

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP	1.500		0	0	0	0	0	0
EDR Hist Auto	0.625		0	0	0	1	NR	1
EDR Hist Cleaner	0.625		0	0	0	0	NR	0

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS	0.500		0	0	0	NR	NR	0
RGA LF	0.500		0	0	0	NR	NR	0
RGA LUST	0.500		0	0	0	NR	NR	0

- Totals --		0	0	1	2	17	0	20
-------------	--	---	---	---	---	----	---	----

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

1
NE
1/8-1/4
0.224 mi.
1182 ft.

WORLD DRIVE NORTH EARLY WORKS

NPDES

S118898032
N/A

ORLANDO, FL

WASTEWATER:

Name: WORLD DRIVE NORTH EARLY WORKS
Address: Not reported
City,State,Zip: ORLANDO, FL
Facility ID: FLR20AY75
Facility Type: Construction Generic Dewatering
Status: Active - Existing, permitted facility/site for which effluent, reclaimed water or wastewater residual discharge into the environment and/or monitoring is taking place.

District Office: TLST
NPDES Permitted Site: Not reported
Environmental Interest: Not reported
Owner Type: Private
Permit Capacity: Not reported
Party Name: James Davis , PMTE
Company Name: Not reported
RP Address: 210 S Hoagland Blvd
RP Address 2: Not reported
RP City,Stat,Zip: Kissimmee FL 34741-4534
Telephone: 4078700066
Email: Angelam@jr-davis.com
Issue Date: 10/06/2016
Effective Date: 10/06/2016
Expiration Date: 10/05/2021
DOC Description: Generic Permit
Latitude Degrees: 28
Latitude Minutes: 23
Latitude Seconds: 19.88
Longitude Degrees: 81
Longitude Minutes: 34
Longitude Seconds: 10.82
Treatment: Not reported
Decode For Fstatus: Active
Cell Phone: Not reported
Permit Type: Not reported
Major Minor Discharge: Not reported
Nature of Business: Not reported

A2
SSW
1/4-1/2
0.431 mi.
2274 ft.

CITY OF ORLANDO - MERRITT PARK DRIVE
MERRITT PARK DRIVE, CORRINE SOUTH
ORLANDO, FL

UIC

S120698018
N/A

Site 1 of 2 in cluster A

UIC:

Name: CITY OF ORLANDO - MERRITT PARK DRIVE
Address: MERRITT PARK DRIVE, CORRINE SOUTH
City,State,Zip: ORLANDO, FL
Facility ID: 103902
GMS ID: Not reported
Well Name: IW-1
Facility Type: 5
Responsible Authority: Not reported
Responsible Authority Address: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

CITY OF ORLANDO - MERRITT PARK DRIVE (Continued)

EDR ID Number
EPA ID Number

Database(s)

S120698018

Responsible Authority City: Not reported
Responsible Authority State: Not reported
Responsible Authority Zip: Not reported
Responsible Authority Tele: Not reported
Section Township Range: Not reported
Facility Status: ACTIVE
Facility Status Data: 04/21/2017
Well Type: STORMWATER DRAINAGE WELL
Injection Well Latitude: 28:21:22
Well EPA Number: FLSCD4818094
Injection Well Longitude: 81:34:59.1
Well Status: ACTIVE
Injection Interval Begin-End: Not reported
Depth: 285
Complete Date: Not reported
Date Injection Well Plugged: Not reported
MIT Date: Not reported
Start Date: Not reported
District: CD

A3
SSW
1/4-1/2
0.431 mi.
2274 ft.

CITY OF ORLANDO - OBERLIN AVE.
OBERLIN AVE. WEST KING ST.
ORLANDO, FL

UIC S120698019
N/A

Site 2 of 2 in cluster A

UIC:
Name: CITY OF ORLANDO - OBERLIN AVE.
Address: OBERLIN AVE. WEST KING ST.
City,State,Zip: ORLANDO, FL
Facility ID: 103903
GMS ID: Not reported
Well Name: IW-1
Facility Type: 5
Responsible Authority: Not reported
Responsible Authority Address: Not reported
Responsible Authority City: Not reported
Responsible Authority State: Not reported
Responsible Authority Zip: Not reported
Responsible Authority Tele: Not reported
Section Township Range: Not reported
Facility Status: ACTIVE
Facility Status Data: 04/21/2017
Well Type: STORMWATER DRAINAGE WELL
Injection Well Latitude: 28:22:52
Well EPA Number: FLSCD4818095
Injection Well Longitude: 81:34:33.1
Well Status: ACTIVE
Injection Interval Begin-End: Not reported
Depth: Not reported
Complete Date: Not reported
Date Injection Well Plugged: Not reported
MIT Date: Not reported
Start Date: Not reported
District: CD

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

B4
NNW
1/2-1
0.503 mi.
2655 ft.
WALT DISNEY WORLD CAR CARE CTR
1000 CAR CARE DR
BAY LAKE, FL 32830
Site 1 of 8 in cluster B

LUST
LAST
UST
AST
U001364352
N/A

CLEANUP SITES
Financial Assurance

LUST:

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: STATE
Facility Id: 8622537
Facility Status: OPEN
Facility Type: C - Fuel user/Non-retail
Facility Phone: (407)590-5089
Facility Cleanup Rank: 4637
District: Central District
Lat/Long (dms): 28 23 31.5078999 / 81 34 29.2877000
Section: 2
Township: 24S
Range: 27E
Feature: Not reported
Method: AGPS
Datum: 0
Score: 11
Score Effective Date: 2009-05-20 00:00:00
Score When Ranked: 31
Operator: Mark Bacchetta
Name Update: Not reported
Address Update: 2025-01-16 00:00:00

Petroleum Cleanup PCT Facility Score:

Facility Cleanup Status: ONGO - ONGOING
Contact: KIM RUSH
Contact Company: WALT DISNEY WORLD PARKS & RESORTS US
Contact Address: PO BOX 10000
Contact City/State/Zip: Orlando, FL 32830
Phone: (407)451-1518
Bad Address Ind: N
State: FL
Zip: 32830
Score: 11
Score Effective Date: 2009-05-20 00:00:00
Related Party ID: 23375
Primary RP Role: ACCOUNT OWNER
RP Begin Date: 1986-02-05
RP Zip: 1000
RP Extension: Not reported

Discharge Cleanup Summary:

Discharge Date: 4/9/1996
PCT Discharge Combined: Not reported
Cleanup Required: R - CLEANUP REQUIRED
Discharge Cleanup Status: NFA - NFA COMPLETE
Disch Cleanup Status Date: 2/12/1998
Cleanup Work Status: COMPLETED
Information Source: D - DISCHARGE NOTIFICATION
Other Source Description: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Eligibility Indicator:	I - INELIGIBLE
Site Manager:	THORNTON_K
Site Mgr End Date:	4/16/2007
Tank Office:	PCLP48 - ORANGE COUNTY ENVIRONMENTAL PROTECTION DIV
Discharge Date:	10/10/1988
PCT Discharge Combined:	Not reported
Cleanup Required:	R - CLEANUP REQUIRED
Discharge Cleanup Status:	RA - RA ONGOING
Disch Cleanup Status Date:	9/10/1993
Cleanup Work Status:	ACTIVE
Information Source:	E - EDI
Other Source Description:	Not reported
Eligibility Indicator:	E - ELIGIBLE
Site Manager:	TAYLOR_DT
Site Mgr End Date:	Not reported
Tank Office:	PCLP48 - ORANGE COUNTY ENVIRONMENTAL PROTECTION DIV
Discharge Date:	10/27/1997
PCT Discharge Combined:	Not reported
Cleanup Required:	R - CLEANUP REQUIRED
Discharge Cleanup Status:	RA - RA ONGOING
Disch Cleanup Status Date:	8/7/2024
Cleanup Work Status:	ACTIVE
Information Source:	D - DISCHARGE NOTIFICATION
Other Source Description:	Not reported
Eligibility Indicator:	E - ELIGIBLE
Site Manager:	TAYLOR_DT
Site Mgr End Date:	Not reported
Tank Office:	PCLP48 - ORANGE COUNTY ENVIRONMENTAL PROTECTION DIV
Discharge Date:	12/2/1994
PCT Discharge Combined:	Not reported
Cleanup Required:	N - NO CLEANUP REQUIRED
Discharge Cleanup Status:	NREQ - CLEANUP NOT REQUIRED
Disch Cleanup Status Date:	8/18/2004
Cleanup Work Status:	COMPLETED
Information Source:	D - DISCHARGE NOTIFICATION
Other Source Description:	Not reported
Eligibility Indicator:	I - INELIGIBLE
Site Manager:	DIN_SM
Site Mgr End Date:	8/23/2004
Tank Office:	PCLP48 - ORANGE COUNTY ENVIRONMENTAL PROTECTION DIV

Petroleum Cleanup Program Eligibility:

Facility ID:	8622537
Discharge Date:	10/10/1988
Pct Discharge Combined With:	Not reported
Cleanup Required:	R - CLEANUP REQUIRED
Discharge Cleanup Status:	RA - RA ONGOING
Disch Cleanup Status Date:	9/10/1993
Cleanup Work Status:	ACTIVE
Information Source:	E - EDI
Other Source Description:	Not reported
Application Received Date:	12/19/1988
Cleanup Program:	E - EARLY DETECTION INCENTIVE
Eligibility Status:	6/4/1990
Elig Status Date:	6/4/1990
Letter Of Intent Date:	12/19/1988
Redetermined:	No
Inspection Date:	3/11/2005

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Site Manager:	TAYLOR_DT
Site Mgr End Date:	Not reported
Tank Office:	PCLP48 - ORANGE COUNTY ENVIRONMENTAL PROTECTION DIV
Deductible Amount:	Not reported
Deductible Paid To Date:	0
Co-Pay Amount:	Not reported
Co-Pay Paid To Date:	0
Cap Amount:	0
Facility ID:	8622537
Discharge Date:	10/27/1997
Pct Discharge Combined With:	Not reported
Cleanup Required:	R - CLEANUP REQUIRED
Discharge Cleanup Status:	SA - SA ONGOING
Disch Cleanup Status Date:	5/17/2005
Cleanup Work Status:	ACTIVE
Information Source:	D - DISCHARGE NOTIFICATION
Other Source Description:	Not reported
Application Received Date:	6/17/2004
Cleanup Program:	P - PETROLEUM LIABILITY AND RESTORATION INSURANCE PROGRAM
Eligibility Status:	6/17/2004
Elig Status Date:	6/17/2004
Letter Of Intent Date:	Not reported
Redetermined:	No
Inspection Date:	Not reported
Site Manager:	TAYLOR_DT
Site Mgr End Date:	Not reported
Tank Office:	PCLP48 - ORANGE COUNTY ENVIRONMENTAL PROTECTION DIV
Deductible Amount:	10000
Deductible Paid To Date:	10000
Co-Pay Amount:	Not reported
Co-Pay Paid To Date:	0
Cap Amount:	300000
Facility ID:	8622537
Discharge Date:	12/2/1994
Pct Discharge Combined With:	Not reported
Cleanup Required:	N - NO CLEANUP REQUIRED
Discharge Cleanup Status:	NREQ - CLEANUP NOT REQUIRED
Disch Cleanup Status Date:	8/18/2004
Cleanup Work Status:	COMPLETED
Information Source:	D - DISCHARGE NOTIFICATION
Other Source Description:	Not reported
Application Received Date:	12/2/1994
Cleanup Program:	C - PETROLEUM CLEANUP PARTICIPATION PROGRAM
Eligibility Status:	8/28/2000
Elig Status Date:	8/28/2000
Letter Of Intent Date:	Not reported
Redetermined:	No
Inspection Date:	Not reported
Site Manager:	DIN_SM
Site Mgr End Date:	8/23/2004
Tank Office:	PCLP48 - ORANGE COUNTY ENVIRONMENTAL PROTECTION DIV
Deductible Amount:	Not reported
Deductible Paid To Date:	Not reported
Co-Pay Amount:	Not reported
Co-Pay Paid To Date:	Not reported
Cap Amount:	0
Facility ID:	8622537

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Discharge Date: 4/9/1996
Pct Discharge Combined With: Not reported
Cleanup Required: R - CLEANUP REQUIRED
Discharge Cleanup Status: NFA - NFA COMPLETE
Disch Cleanup Status Date: 2/12/1998
Cleanup Work Status: COMPLETED
Information Source: D - DISCHARGE NOTIFICATION
Other Source Description: Not reported
Application Received Date: 2/20/1997
Cleanup Program: C - PETROLEUM CLEANUP PARTICIPATION PROGRAM
Eligibility Status: 8/30/2000
Elig Status Date: 8/30/2000
Letter Of Intent Date: 11/13/1996
Redetermined: No
Inspection Date: 5/12/1990
Site Manager: THORNTON_K
Site Mgr End Date: 4/16/2007
Tank Office: PCLP48 - ORANGE COUNTY ENVIRONMENTAL PROTECTION DIV
Deductible Amount: Not reported
Deductible Paid To Date: Not reported
Co-Pay Amount: Not reported
Co-Pay Paid To Date: Not reported
Cap Amount: 0

Contaminated Media:

Discharge Date: 4/9/1996
Pct Discharge Combined With: Not reported
Cleanup Required: R - CLEANUP REQUIRED
Discharge Cleanup Status: NFA - NFA COMPLETE
Disch Cleanup Status Date: 2/12/1998
Cleanup Work Status: COMPLETED
Information Source: D - DISCHARGE NOTIFICATION
Other Source Description: Not reported
Elig Indicator: I - INELIGIBLE
Site Manager: THORNTON_K
Site Mgr End Date: 4/16/2007
Tank Office: PCLP48 - ORANGE COUNTY ENVIRON
Contaminated Drinking Wells: Not reported
Contaminated Monitoring Well: Not reported
Contaminated Soil: Not reported
Contaminated Surface Water: Not reported
Contaminated Ground Water: Not reported
Pollutant: B - Unleaded Gas
Pollutant Other Description: Not reported
Gallons Discharged: Not reported
Discharge Date: 10/10/1988
Pct Discharge Combined With: Not reported
Cleanup Required: R - CLEANUP REQUIRED
Discharge Cleanup Status: RA - RA ONGOING
Disch Cleanup Status Date: 9/10/1993
Cleanup Work Status: ACTIVE
Information Source: E - EDI
Other Source Description: Not reported
Elig Indicator: E - ELIGIBLE
Site Manager: TAYLOR_DT
Site Mgr End Date: Not reported
Tank Office: PCLP48 - ORANGE COUNTY ENVIRON
Contaminated Drinking Wells: 0

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Contaminated Monitoring Well:	Yes
Contaminated Soil:	Yes
Contaminated Surface Water:	No
Contaminated Ground Water:	Yes
Pollutant:	B - Unleaded Gas
Pollutant Other Description:	Not reported
Gallons Discharged:	Not reported
Discharge Date:	10/27/1997
Pct Discharge Combined With:	Not reported
Cleanup Required:	R - CLEANUP REQUIRED
Discharge Cleanup Status:	RA - RA ONGOING
Disch Cleanup Status Date:	8/7/2024
Cleanup Work Status:	ACTIVE
Information Source:	D - DISCHARGE NOTIFICATION
Other Source Description:	Not reported
Elig Indicator:	E - ELIGIBLE
Site Manager:	TAYLOR_DT
Site Mgr End Date:	Not reported
Tank Office:	PCLP48 - ORANGE COUNTY ENVIRON
Contaminated Drinking Wells:	Not reported
Contaminated Monitoring Well:	Not reported
Contaminated Soil:	Not reported
Contaminated Surface Water:	Not reported
Contaminated Ground Water:	Not reported
Pollutant:	D - Vehicular Diesel
Pollutant Other Description:	Not reported
Gallons Discharged:	Not reported
Discharge Date:	12/2/1994
Pct Discharge Combined With:	Not reported
Cleanup Required:	N - NO CLEANUP REQUIRED
Discharge Cleanup Status:	NREQ - CLEANUP NOT REQUIRED
Disch Cleanup Status Date:	8/18/2004
Cleanup Work Status:	COMPLETED
Information Source:	D - DISCHARGE NOTIFICATION
Other Source Description:	Not reported
Elig Indicator:	I - INELIGIBLE
Site Manager:	DIN_SM
Site Mgr End Date:	8/23/2004
Tank Office:	PCLP48 - ORANGE COUNTY ENVIRON
Contaminated Drinking Wells:	Not reported
Contaminated Monitoring Well:	Not reported
Contaminated Soil:	Not reported
Contaminated Surface Water:	Not reported
Contaminated Ground Water:	Not reported
Pollutant:	D - Vehicular Diesel
Pollutant Other Description:	Not reported
Gallons Discharged:	Not reported

Task Information:	
District:	CD
Facility ID:	8622537
Facility Status:	OPEN
Facility Type:	C - Fuel user/Non-retail -
County:	ORANGE
County ID:	48
Cleanup Eligibility Status:	I
Source Effective Date:	01-27-1998
Discharge Date:	04-09-1996

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Cleanup Required:	R - CLEANUP REQUIRED
Discharge Cleanup Status:	NFA - NFA COMPLETE
Disch Cleanup Status Date:	02-12-1998
SRC Action Type:	NFA - NO FURTHER ACTION
SRC Submit Date:	01-13-1998
SRC Review Date:	01-26-1998
SRC Completion Status:	A - APPROVED
SRC Issue Date:	02-12-1998
SRC Comment:	Not reported
Cleanup Work Status:	COMPLETED
Site Mgr:	THORNTON_K
Site Mgr End Date:	04-16-2007
Tank Office:	PCLP48 - Orange County
SR Task ID:	Not reported
SR Cleanup Responsible:	Not reported
SR Funding Eligibility Type:	Not reported
SR Actual Cost:	Not reported
SR Completion Date:	Not reported
SR Payment Date:	Not reported
SR Oral Date:	Not reported
SR Written Date:	Not reported
SR Soil Removal:	Not reported
SR Free Product Removal:	Not reported
SR Soil Tonnage Removed:	Not reported
SR Soil Treatment:	Not reported
SR Other Treatment:	Not reported
SR Alternate Proc Received Date:	Not reported
SR Alternate Procedure Status:	Not reported
SR Alternate Procedure Status Date:	Not reported
SR Alternate Procedure Comments:	Not reported
SA Task ID:	Not reported
SA Cleanup Responsible:	Not reported
SA Funding Eligibility Type:	Not reported
SA Actual Cost:	Not reported
SA Completion Date:	Not reported
SA Payment Date:	Not reported
RAP Task ID:	63951
RAP Cleanup Responsible ID:	Not reported
RAP Funding Eligibility Type:	Not reported
RAP Actual Cost:	Not reported
RAP Completion Date:	Not reported
RAP Payment Date:	Not reported
RAP Last Order Approved:	Not reported
RA Task ID:	83551
RA Cleanup Responsible:	RP - RESPONSIBLE PARTY
RA Funding Eligibility Type:	Not reported
RA Years to Complete:	0
RA Actual Cost:	Not reported
District:	CD
Facility ID:	8622537
Facility Status:	OPEN
Facility Type:	C - Fuel user/Non-retail -
County:	ORANGE
County ID:	48
Cleanup Eligibility Status:	E
Source Effective Date:	Not reported
Discharge Date:	10-10-1988

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Cleanup Required:	R - CLEANUP REQUIRED
Discharge Cleanup Status:	RA - RA ONGOING
Disch Cleanup Status Date:	09-10-1993
SRC Action Type:	Not reported
SRC Submit Date:	Not reported
SRC Review Date:	Not reported
SRC Completion Status:	Not reported
SRC Issue Date:	Not reported
SRC Comment:	Not reported
Cleanup Work Status:	INACTIVE
Site Mgr:	CIRIC_A
Site Mgr End Date:	11-30-2016
Tank Office:	PCTM5 - Team 5
SR Task ID:	20762
SR Cleanup Responsible:	Not reported
SR Funding Eligibility Type:	Not reported
SR Actual Cost:	\$147,482.81
SR Completion Date:	02-23-1989
SR Payment Date:	12-07-1992
SR Oral Date:	Not reported
SR Written Date:	Not reported
SR Soil Removal:	Y
SR Free Product Removal:	Y
SR Soil Tonnage Removed:	210
SR Soil Treatment:	Not reported
SR Other Treatment:	Not reported
SR Alternate Proc Received Date:	Not reported
SR Alternate Procedure Status:	Not reported
SR Alternate Procedure Status Date:	Not reported
SR Alternate Procedure Comments:	Not reported
SA Task ID:	20763
SA Cleanup Responsible:	Not reported
SA Funding Eligibility Type:	Not reported
SA Actual Cost:	Not reported
SA Completion Date:	01-17-1991
SA Payment Date:	Not reported
RAP Task ID:	20764
RAP Cleanup Responsible ID:	RP - RESPONSIBLE PARTY
RAP Funding Eligibility Type:	Not reported
RAP Actual Cost:	Not reported
RAP Completion Date:	06-24-1992
RAP Payment Date:	Not reported
RAP Last Order Approved:	1992-06-24 00:00:00
RA Task ID:	20765
RA Cleanup Responsible:	RP - RESPONSIBLE PARTY
RA Funding Eligibility Type:	Not reported
RA Years to Complete:	Not reported
RA Actual Cost:	Not reported
District:	CD
Facility ID:	8622537
Facility Status:	OPEN
Facility Type:	C - Fuel user/Non-retail -
County:	ORANGE
County ID:	48
Cleanup Eligibility Status:	E
Source Effective Date:	Not reported
Discharge Date:	10-27-1997

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
 EDR ID Number
 EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Cleanup Required:	R - CLEANUP REQUIRED
Discharge Cleanup Status:	SA - SA ONGOING
Disch Cleanup Status Date:	05-17-2005
SRC Action Type:	Not reported
SRC Submit Date:	Not reported
SRC Review Date:	Not reported
SRC Completion Status:	Not reported
SRC Issue Date:	Not reported
SRC Comment:	Not reported
Cleanup Work Status:	INACTIVE
Site Mgr:	CIRIC_A
Site Mgr End Date:	11-30-2016
Tank Office:	PCTM5 - Team 5
SR Task ID:	Not reported
SR Cleanup Responsible:	Not reported
SR Funding Eligibility Type:	Not reported
SR Actual Cost:	Not reported
SR Completion Date:	Not reported
SR Payment Date:	Not reported
SR Oral Date:	Not reported
SR Written Date:	Not reported
SR Soil Removal:	Not reported
SR Free Product Removal:	Not reported
SR Soil Tonnage Removed:	Not reported
SR Soil Treatment:	Not reported
SR Other Treatment:	Not reported
SR Alternate Proc Received Date:	Not reported
SR Alternate Procedure Status:	Not reported
SR Alternate Procedure Status Date:	Not reported
SR Alternate Procedure Comments:	Not reported
SA Task ID:	73684
SA Cleanup Responsible:	Not reported
SA Funding Eligibility Type:	Not reported
SA Actual Cost:	Not reported
SA Completion Date:	Not reported
SA Payment Date:	Not reported
RAP Task ID:	Not reported
RAP Cleanup Responsible ID:	Not reported
RAP Funding Eligibility Type:	Not reported
RAP Actual Cost:	Not reported
RAP Completion Date:	Not reported
RAP Payment Date:	Not reported
RAP Last Order Approved:	Not reported
RA Task ID:	Not reported
RA Cleanup Responsible:	Not reported
RA Funding Eligibility Type:	Not reported
RA Years to Complete:	Not reported
RA Actual Cost:	Not reported
District:	CD
Facility ID:	8622537
Facility Status:	OPEN
Facility Type:	C - Fuel user/Non-retail -
County:	ORANGE
County ID:	48
Cleanup Eligibility Status:	I
Source Effective Date:	Not reported
Discharge Date:	12-02-1994

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Cleanup Required:	N - NO CLEANUP REQUIRED
Discharge Cleanup Status:	NREQ - CLEANUP NOT REQUIRED
Disch Cleanup Status Date:	08-18-2004
SRC Action Type:	Not reported
SRC Submit Date:	Not reported
SRC Review Date:	Not reported
SRC Completion Status:	Not reported
SRC Issue Date:	Not reported
SRC Comment:	Not reported
Cleanup Work Status:	COMPLETED
Site Mgr:	DIN_SM
Site Mgr End Date:	08-23-2004
Tank Office:	PCLP48 - Orange County
SR Task ID:	Not reported
SR Cleanup Responsible:	Not reported
SR Funding Eligibility Type:	Not reported
SR Actual Cost:	Not reported
SR Completion Date:	Not reported
SR Payment Date:	Not reported
SR Oral Date:	Not reported
SR Written Date:	Not reported
SR Soil Removal:	Not reported
SR Free Product Removal:	Not reported
SR Soil Tonnage Removed:	Not reported
SR Soil Treatment:	Not reported
SR Other Treatment:	Not reported
SR Alternate Proc Received Date:	Not reported
SR Alternate Procedure Status:	Not reported
SR Alternate Procedure Status Date:	Not reported
SR Alternate Procedure Comments:	Not reported
SA Task ID:	Not reported
SA Cleanup Responsible:	Not reported
SA Funding Eligibility Type:	Not reported
SA Actual Cost:	Not reported
SA Completion Date:	Not reported
SA Payment Date:	Not reported
RAP Task ID:	Not reported
RAP Cleanup Responsible ID:	Not reported
RAP Funding Eligibility Type:	Not reported
RAP Actual Cost:	Not reported
RAP Completion Date:	Not reported
RAP Payment Date:	Not reported
RAP Last Order Approved:	Not reported
RA Task ID:	Not reported
RA Cleanup Responsible:	Not reported
RA Funding Eligibility Type:	Not reported
RA Years to Complete:	Not reported
RA Actual Cost:	Not reported

[Click here for Florida Oculus:](#)

LAST:

Name:	WALT DISNEY WORLD CAR CARE CTR
Address:	1000 CAR CARE DR
City,State,Zip:	BAY LAKE, FL 32830
Facility Id:	8622537
Placement:	AST UST

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Tank Contents: Waste Oil
Tank Size: 500
Latitude: 28 23'35"
Longitude: 81 34'31"

[Click here for Florida Oculus:](#)

UST:

Facility ID: 8622537
Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
Depco: P
Region: STATE
Positioning Method: AGPS
Latitude/Longitude: 28 23 35 / 81 34 31

UST:

Tank ID: 30
Tank Capacity: 12000
Tank Location: UNDERGROUND
Tank Status: A-Closed In Place
Status Date: 05/01/2007
Install Date: 6/1/1971
Substance: D
Content Description: Vehicular Diesel
Vessel Indicator: TANK
DEP Contractor: P

Owner:

Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address 2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip: Orlando, FL 32830
Owner Contact: KIM RUSH
Owner Phone: 4074511518

Construction:

Tank ID: 1
Construction Category: C
Construction Description: Steel

Tank ID: 1
Construction Category: I
Construction Description: Double wall

Tank ID: 1
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 1
Construction Category: N

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Description:	Flow shut-Off
Tank ID:	1
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	2
Construction Category:	C
Construction Description:	Steel
Tank ID:	2
Construction Category:	I
Construction Description:	Double wall
Tank ID:	2
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	2
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	2
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	2
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	3
Construction Category:	C
Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	5
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	5
Construction Category:	P
Construction Description:	Level gauges/alarms
Piping:	
Tank ID:	3
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	3
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	4
Piping Category:	C
Piping Description:	Fiberglass

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	4
Piping Category:	F
Piping Description:	Double wall
Tank ID:	4
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	4
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	5
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	5
Piping Category:	F
Piping Description:	Double wall
Tank ID:	5
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	5
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	2
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	2
Piping Category:	F
Piping Description:	Double wall
Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Monitoring:

Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID: 3
Petro Monitoring Category: 3
Monitoring Description: Electronic monitor pipe sumps

Tank ID: 3
Petro Monitoring Category: 5
Monitoring Description: Electronic monitor dispenser liners

Tank ID: 4
Petro Monitoring Category: G
Monitoring Description: Electronic line leak detector

Tank ID: 4
Petro Monitoring Category: L
Monitoring Description: Automatic tank gauging - USTs

Tank ID: 1
Petro Monitoring Category: F
Monitoring Description: Monitor dbl wall tank space

Tank ID: 1
Petro Monitoring Category: Q
Monitoring Description: Visual inspection of ASTs

Tank ID: 32
Tank Capacity: 4000
Tank Location: UNDERGROUND
Tank Status: B-Removed from Site
Status Date: 12/01/1997
Install Date: 6/1/1971
Substance: L
Content Description: Waste Oil
Vessel Indicator: TANK
DEP Contractor: P

Owner:
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address 2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip: Orlando, FL 32830
Owner Contact: KIM RUSH
Owner Phone: 4074511518

Construction:
Tank ID: 1
Construction Category: C
Construction Description: Steel

Tank ID: 1
Construction Category: I
Construction Description: Double wall

Tank ID: 1
Construction Category: M
Construction Description: Spill containment bucket

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	1
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	1
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	2
Construction Category:	C
Construction Description:	Steel
Tank ID:	2
Construction Category:	I
Construction Description:	Double wall
Tank ID:	2
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	2
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	2
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	2
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	3
Construction Category:	C
Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	5
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	5
Construction Category:	P
Construction Description:	Level gauges/alarms
Piping:	
Tank ID:	3
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	3
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	4

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	4
Piping Category:	F
Piping Description:	Double wall
Tank ID:	4
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	4
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	5
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	5
Piping Category:	F
Piping Description:	Double wall
Tank ID:	5
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	5
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	2
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	2
Piping Category:	F
Piping Description:	Double wall
Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs
Tank ID:	29
Tank Capacity:	12000
Tank Location:	UNDERGROUND
Tank Status:	A-Closed In Place
Status Date:	05/01/2007
Install Date:	6/1/1971
Substance:	B
Content Description:	Unleaded Gas
Vessel Indicator:	TANK
DEP Contractor:	P
Owner:	
Owner ID:	23375
Owner Name:	WALT DISNEY WORLD PARKS & RESORTS US
Owner Address:	PO BOX 10000
Owner Address 2:	ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip:	Orlando, FL 32830
Owner Contact:	KIM RUSH
Owner Phone:	4074511518
Construction:	
Tank ID:	1
Construction Category:	C
Construction Description:	Steel
Tank ID:	1
Construction Category:	I
Construction Description:	Double wall
Tank ID:	1

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	1
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	1
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	2
Construction Category:	C
Construction Description:	Steel
Tank ID:	2
Construction Category:	I
Construction Description:	Double wall
Tank ID:	2
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	2
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	2
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	2
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	3
Construction Category:	C
Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	5
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	5
Construction Category:	P
Construction Description:	Level gauges/alarms
Piping:	
Tank ID:	3
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	3
Piping Category:	K

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Description:	Dispenser liners
Tank ID:	4
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	4
Piping Category:	F
Piping Description:	Double wall
Tank ID:	4
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	4
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	5
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	5
Piping Category:	F
Piping Description:	Double wall
Tank ID:	5
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	5
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	2
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	2
Piping Category:	F
Piping Description:	Double wall
Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID: 3
Petro Monitoring Category: L
Monitoring Description: Automatic tank gauging - USTs

Tank ID: 3
Petro Monitoring Category: 3
Monitoring Description: Electronic monitor pipe sumps

Tank ID: 3
Petro Monitoring Category: 5
Monitoring Description: Electronic monitor dispenser liners

Tank ID: 4
Petro Monitoring Category: G
Monitoring Description: Electronic line leak detector

Tank ID: 4
Petro Monitoring Category: L
Monitoring Description: Automatic tank gauging - USTs

Tank ID: 1
Petro Monitoring Category: F
Monitoring Description: Monitor dbl wall tank space

Tank ID: 1
Petro Monitoring Category: Q
Monitoring Description: Visual inspection of ASTs

Tank ID: 28
Tank Capacity: 12000
Tank Location: UNDERGROUND
Tank Status: A-Closed In Place
Status Date: 05/01/2007
Install Date: 6/1/1971
Substance: D
Content Description: Vehicular Diesel
Vessel Indicator: TANK
DEP Contractor: P

Owner:
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address 2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip: Orlando, FL 32830
Owner Contact: KIM RUSH
Owner Phone: 4074511518

Construction:
Tank ID: 1
Construction Category: C
Construction Description: Steel

Tank ID: 1
Construction Category: I
Construction Description: Double wall

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	1
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	1
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	1
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	2
Construction Category:	C
Construction Description:	Steel
Tank ID:	2
Construction Category:	I
Construction Description:	Double wall
Tank ID:	2
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	2
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	2
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	2
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	3
Construction Category:	C
Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	5
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	5
Construction Category:	P
Construction Description:	Level gauges/alarms
Piping:	
Tank ID:	3
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	3

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	4
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	4
Piping Category:	F
Piping Description:	Double wall
Tank ID:	4
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	4
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	5
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	5
Piping Category:	F
Piping Description:	Double wall
Tank ID:	5
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	5
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	2
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	2
Piping Category:	F
Piping Description:	Double wall
Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs
Tank ID:	27
Tank Capacity:	12000
Tank Location:	UNDERGROUND
Tank Status:	A-Closed In Place
Status Date:	05/01/2007
Install Date:	6/1/1971
Substance:	D
Content Description:	Vehicular Diesel
Vessel Indicator:	TANK
DEP Contractor:	P
Owner:	
Owner ID:	23375
Owner Name:	WALT DISNEY WORLD PARKS & RESORTS US
Owner Address:	PO BOX 10000
Owner Address 2:	ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip:	Orlando, FL 32830
Owner Contact:	KIM RUSH
Owner Phone:	4074511518
Construction:	
Tank ID:	1
Construction Category:	C
Construction Description:	Steel
Tank ID:	1

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Construction Category:	I
Construction Description:	Double wall
Tank ID:	1
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	1
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	1
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	2
Construction Category:	C
Construction Description:	Steel
Tank ID:	2
Construction Category:	I
Construction Description:	Double wall
Tank ID:	2
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	2
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	2
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	2
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	3
Construction Category:	C
Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	5
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	5
Construction Category:	P
Construction Description:	Level gauges/alarms
Piping:	
Tank ID:	3
Piping Category:	J

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Description:	Pressurized piping system
Tank ID:	3
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	4
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	4
Piping Category:	F
Piping Description:	Double wall
Tank ID:	4
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	4
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	5
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	5
Piping Category:	F
Piping Description:	Double wall
Tank ID:	5
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	5
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	2
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	2
Piping Category:	F
Piping Description:	Double wall
Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs
Tank ID:	26
Tank Capacity:	12000
Tank Location:	UNDERGROUND
Tank Status:	A-Closed In Place
Status Date:	05/01/2007
Install Date:	6/1/1971
Substance:	D
Content Description:	Vehicular Diesel
Vessel Indicator:	TANK
DEP Contractor:	P
Owner:	
Owner ID:	23375
Owner Name:	WALT DISNEY WORLD PARKS & RESORTS US
Owner Address:	PO BOX 10000
Owner Address 2:	ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip:	Orlando, FL 32830
Owner Contact:	KIM RUSH
Owner Phone:	4074511518
Construction:	
Tank ID:	1
Construction Category:	C
Construction Description:	Steel

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	1
Construction Category:	I
Construction Description:	Double wall
Tank ID:	1
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	1
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	1
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	2
Construction Category:	C
Construction Description:	Steel
Tank ID:	2
Construction Category:	I
Construction Description:	Double wall
Tank ID:	2
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	2
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	2
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	2
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	3
Construction Category:	C
Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Construction Category: O
Construction Description: Tight fill

Tank ID: 3
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 4
Construction Category: C
Construction Description: Steel

Tank ID: 4
Construction Category: I
Construction Description: Double wall

Tank ID: 4
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 4
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 4
Construction Category: O
Construction Description: Tight fill

Tank ID: 4
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 5
Construction Category: C
Construction Description: Steel

Tank ID: 5
Construction Category: I
Construction Description: Double wall

Tank ID: 5
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 5
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 5
Construction Category: O
Construction Description: Tight fill

Tank ID: 5
Construction Category: P
Construction Description: Level gauges/alarms

Piping:
Tank ID: 3

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	3
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	4
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	4
Piping Category:	F
Piping Description:	Double wall
Tank ID:	4
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	4
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	5
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	5
Piping Category:	F
Piping Description:	Double wall
Tank ID:	5
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	5
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	2
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	2
Piping Category:	F
Piping Description:	Double wall
Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs
Tank ID:	25
Tank Capacity:	12000
Tank Location:	UNDERGROUND
Tank Status:	A-Closed In Place
Status Date:	05/01/2007
Install Date:	6/1/1971
Substance:	B
Content Description:	Unleaded Gas
Vessel Indicator:	TANK
DEP Contractor:	P
Owner:	
Owner ID:	23375
Owner Name:	WALT DISNEY WORLD PARKS & RESORTS US
Owner Address:	PO BOX 10000
Owner Address 2:	ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip:	Orlando, FL 32830
Owner Contact:	KIM RUSH
Owner Phone:	4074511518
Construction:	
Tank ID:	1

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Category:	C
Construction Description:	Steel
Tank ID:	1
Construction Category:	I
Construction Description:	Double wall
Tank ID:	1
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	1
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	1
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	2
Construction Category:	C
Construction Description:	Steel
Tank ID:	2
Construction Category:	I
Construction Description:	Double wall
Tank ID:	2
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	2
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	2
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	2
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	3
Construction Category:	C
Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	5
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	5
Construction Category:	P
Construction Description:	Level gauges/alarms

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping:

Tank ID: 3
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 3
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 4
Piping Category: C
Piping Description: Fiberglass

Tank ID: 4
Piping Category: F
Piping Description: Double wall

Tank ID: 4
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 4
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 5
Piping Category: C
Piping Description: Fiberglass

Tank ID: 5
Piping Category: F
Piping Description: Double wall

Tank ID: 5
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 5
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 2
Piping Category: C
Piping Description: Fiberglass

Tank ID: 2
Piping Category: F
Piping Description: Double wall

Tank ID: 2
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 2
Piping Category: K
Piping Description: Dispenser liners

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID: 3
Piping Category: C
Piping Description: Fiberglass

Tank ID: 3
Piping Category: F
Piping Description: Double wall

Tank ID: 1
Piping Category: A
Piping Description: Abv, no soil contact

Monitoring:

Tank ID: 4
Petro Monitoring Category: 3
Monitoring Description: Electronic monitor pipe sumps

Tank ID: 4
Petro Monitoring Category: 5
Monitoring Description: Electronic monitor dispenser liners

Tank ID: 5
Petro Monitoring Category: G
Monitoring Description: Electronic line leak detector

Tank ID: 5
Petro Monitoring Category: L
Monitoring Description: Automatic tank gauging - USTs

Tank ID: 5
Petro Monitoring Category: 3
Monitoring Description: Electronic monitor pipe sumps

Tank ID: 5
Petro Monitoring Category: 5
Monitoring Description: Electronic monitor dispenser liners

Tank ID: 1
Petro Monitoring Category: 3
Monitoring Description: Electronic monitor pipe sumps

Tank ID: 1
Petro Monitoring Category: 5
Monitoring Description: Electronic monitor dispenser liners

Tank ID: 2
Petro Monitoring Category: G
Monitoring Description: Electronic line leak detector

Tank ID: 2
Petro Monitoring Category: L
Monitoring Description: Automatic tank gauging - USTs

Tank ID: 2
Petro Monitoring Category: 3
Monitoring Description: Electronic monitor pipe sumps

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID: 2
Petro Monitoring Category: 5
Monitoring Description: Electronic monitor dispenser liners

Tank ID: 3
Petro Monitoring Category: G
Monitoring Description: Electronic line leak detector

Tank ID: 3
Petro Monitoring Category: L
Monitoring Description: Automatic tank gauging - USTs

Tank ID: 3
Petro Monitoring Category: 3
Monitoring Description: Electronic monitor pipe sumps

Tank ID: 3
Petro Monitoring Category: 5
Monitoring Description: Electronic monitor dispenser liners

Tank ID: 4
Petro Monitoring Category: G
Monitoring Description: Electronic line leak detector

Tank ID: 4
Petro Monitoring Category: L
Monitoring Description: Automatic tank gauging - USTs

Tank ID: 1
Petro Monitoring Category: F
Monitoring Description: Monitor dbl wall tank space

Tank ID: 1
Petro Monitoring Category: Q
Monitoring Description: Visual inspection of ASTs

Tank ID: 24
Tank Capacity: 12000
Tank Location: UNDERGROUND
Tank Status: A-Closed In Place
Status Date: 05/01/2007
Install Date: 6/1/1971
Substance: D
Content Description: Vehicular Diesel
Vessel Indicator: TANK
DEP Contractor: P

Owner:
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address 2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip: Orlando, FL 32830
Owner Contact: KIM RUSH
Owner Phone: 4074511518

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Construction:

Tank ID:	1
Construction Category:	C
Construction Description:	Steel
Tank ID:	1
Construction Category:	I
Construction Description:	Double wall
Tank ID:	1
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	1
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	1
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	2
Construction Category:	C
Construction Description:	Steel
Tank ID:	2
Construction Category:	I
Construction Description:	Double wall
Tank ID:	2
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	2
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	2
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	2
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	3
Construction Category:	C
Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	5
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	5

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Category:	P
Construction Description:	Level gauges/alarms
Piping:	
Tank ID:	3
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	3
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	4
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	4
Piping Category:	F
Piping Description:	Double wall
Tank ID:	4
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	4
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	5
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	5
Piping Category:	F
Piping Description:	Double wall
Tank ID:	5
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	5
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	2
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	2
Piping Category:	F
Piping Description:	Double wall
Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs
Tank ID:	23
Tank Capacity:	12000
Tank Location:	UNDERGROUND
Tank Status:	A-Closed In Place
Status Date:	05/01/2007
Install Date:	6/1/1971
Substance:	D
Content Description:	Vehicular Diesel
Vessel Indicator:	TANK
DEP Contractor:	P
Owner:	
Owner ID:	23375
Owner Name:	WALT DISNEY WORLD PARKS & RESORTS US
Owner Address:	PO BOX 10000
Owner Address 2:	ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip:	Orlando, FL 32830
Owner Contact:	KIM RUSH

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Owner Phone: 4074511518

Construction:

Tank ID: 1

Construction Category: C

Construction Description: Steel

Tank ID: 1

Construction Category: I

Construction Description: Double wall

Tank ID: 1

Construction Category: M

Construction Description: Spill containment bucket

Tank ID: 1

Construction Category: N

Construction Description: Flow shut-Off

Tank ID: 1

Construction Category: P

Construction Description: Level gauges/alarms

Tank ID: 2

Construction Category: C

Construction Description: Steel

Tank ID: 2

Construction Category: I

Construction Description: Double wall

Tank ID: 2

Construction Category: N

Construction Description: Flow shut-Off

Tank ID: 2

Construction Category: M

Construction Description: Spill containment bucket

Tank ID: 2

Construction Category: O

Construction Description: Tight fill

Tank ID: 2

Construction Category: P

Construction Description: Level gauges/alarms

Tank ID: 3

Construction Category: C

Construction Description: Steel

Tank ID: 3

Construction Category: I

Construction Description: Double wall

Tank ID: 3

Construction Category: M

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	5
Construction Category:	O
Construction Description:	Tight fill

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID: 5
Construction Category: P
Construction Description: Level gauges/alarms

Piping:

Tank ID: 3
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 3
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 4
Piping Category: C
Piping Description: Fiberglass

Tank ID: 4
Piping Category: F
Piping Description: Double wall

Tank ID: 4
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 4
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 5
Piping Category: C
Piping Description: Fiberglass

Tank ID: 5
Piping Category: F
Piping Description: Double wall

Tank ID: 5
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 5
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 2
Piping Category: C
Piping Description: Fiberglass

Tank ID: 2
Piping Category: F
Piping Description: Double wall

Tank ID: 2
Piping Category: J
Piping Description: Pressurized piping system

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs
Tank ID:	Not reported
Tank Capacity:	12000
Tank Location:	UNDERGROUND
Tank Status:	A-Closed In Place
Status Date:	05/01/2007
Install Date:	11/1/1988
Substance:	D
Content Description:	Vehicular Diesel
Vessel Indicator:	TANK
DEP Contractor:	P

Owner:

Owner ID:	23375
Owner Name:	WALT DISNEY WORLD PARKS & RESORTS US
Owner Address:	PO BOX 10000
Owner Address 2:	ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip:	Orlando, FL 32830

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Owner Contact:	KIM RUSH
Owner Phone:	4074511518
Construction:	
Tank ID:	1
Construction Category:	C
Construction Description:	Steel
Tank ID:	1
Construction Category:	I
Construction Description:	Double wall
Tank ID:	1
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	1
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	1
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	2
Construction Category:	C
Construction Description:	Steel
Tank ID:	2
Construction Category:	I
Construction Description:	Double wall
Tank ID:	2
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	2
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	2
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	2
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	3
Construction Category:	C
Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	5
Construction Category:	O

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Description:	Tight fill
Tank ID:	5
Construction Category:	P
Construction Description:	Level gauges/alarms
Piping:	
Tank ID:	3
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	3
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	4
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	4
Piping Category:	F
Piping Description:	Double wall
Tank ID:	4
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	4
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	5
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	5
Piping Category:	F
Piping Description:	Double wall
Tank ID:	5
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	5
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	2
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	2
Piping Category:	F
Piping Description:	Double wall
Tank ID:	2
Piping Category:	J

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Monitoring Description: Automatic tank gauging - USTs

Tank ID: 2

Petro Monitoring Category: 3

Monitoring Description: Electronic monitor pipe sumps

Tank ID: 2

Petro Monitoring Category: 5

Monitoring Description: Electronic monitor dispenser liners

Tank ID: 3

Petro Monitoring Category: G

Monitoring Description: Electronic line leak detector

Tank ID: 3

Petro Monitoring Category: L

Monitoring Description: Automatic tank gauging - USTs

Tank ID: 3

Petro Monitoring Category: 3

Monitoring Description: Electronic monitor pipe sumps

Tank ID: 3

Petro Monitoring Category: 5

Monitoring Description: Electronic monitor dispenser liners

Tank ID: 4

Petro Monitoring Category: G

Monitoring Description: Electronic line leak detector

Tank ID: 4

Petro Monitoring Category: L

Monitoring Description: Automatic tank gauging - USTs

Tank ID: 1

Petro Monitoring Category: F

Monitoring Description: Monitor dbl wall tank space

Tank ID: 1

Petro Monitoring Category: Q

Monitoring Description: Visual inspection of ASTs

Tank ID: 22

Tank Capacity: 12000

Tank Location: UNDERGROUND

Tank Status: B-Removed from Site

Status Date: 11/30/1988

Install Date: 6/1/1971

Substance: B

Content Description: Unleaded Gas

Vessel Indicator: TANK

DEP Contractor: P

Owner:

Owner ID: 23375

Owner Name: WALT DISNEY WORLD PARKS & RESORTS US

Owner Address: PO BOX 10000

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Owner Address 2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip: Orlando, FL 32830
Owner Contact: KIM RUSH
Owner Phone: 4074511518

Construction:

Tank ID: 1
Construction Category: C
Construction Description: Steel

Tank ID: 1
Construction Category: I
Construction Description: Double wall

Tank ID: 1
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 1
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 1
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 2
Construction Category: C
Construction Description: Steel

Tank ID: 2
Construction Category: I
Construction Description: Double wall

Tank ID: 2
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 2
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 2
Construction Category: O
Construction Description: Tight fill

Tank ID: 2
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 3
Construction Category: C
Construction Description: Steel

Tank ID: 3
Construction Category: I
Construction Description: Double wall

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	5

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Category: O
Construction Description: Tight fill

Tank ID: 5
Construction Category: P
Construction Description: Level gauges/alarms

Piping:
Tank ID: 3
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 3
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 4
Piping Category: C
Piping Description: Fiberglass

Tank ID: 4
Piping Category: F
Piping Description: Double wall

Tank ID: 4
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 4
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 5
Piping Category: C
Piping Description: Fiberglass

Tank ID: 5
Piping Category: F
Piping Description: Double wall

Tank ID: 5
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 5
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 2
Piping Category: C
Piping Description: Fiberglass

Tank ID: 2
Piping Category: F
Piping Description: Double wall

Tank ID: 2

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs
Tank ID:	5
Tank Capacity:	12000
Tank Location:	UNDERGROUND
Tank Status:	U-In Service
Status Date:	05/01/2007
Install Date:	5/1/2007
Substance:	B
Content Description:	Unleaded Gas
Vessel Indicator:	TANK
DEP Contractor:	P
Owner:	
Owner ID:	23375
Owner Name:	WALT DISNEY WORLD PARKS & RESORTS US

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Owner Address: PO BOX 10000
Owner Address 2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip: Orlando, FL 32830
Owner Contact: KIM RUSH
Owner Phone: 4074511518

Construction:

Tank ID: 1
Construction Category: C
Construction Description: Steel

Tank ID: 1
Construction Category: I
Construction Description: Double wall

Tank ID: 1
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 1
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 1
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 2
Construction Category: C
Construction Description: Steel

Tank ID: 2
Construction Category: I
Construction Description: Double wall

Tank ID: 2
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 2
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 2
Construction Category: O
Construction Description: Tight fill

Tank ID: 2
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 3
Construction Category: C
Construction Description: Steel

Tank ID: 3
Construction Category: I

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID: 5
Construction Category: O
Construction Description: Tight fill

Tank ID: 5
Construction Category: P
Construction Description: Level gauges/alarms

Piping:

Tank ID: 3
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 3
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 4
Piping Category: C
Piping Description: Fiberglass

Tank ID: 4
Piping Category: F
Piping Description: Double wall

Tank ID: 4
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 4
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 5
Piping Category: C
Piping Description: Fiberglass

Tank ID: 5
Piping Category: F
Piping Description: Double wall

Tank ID: 5
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 5
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 2
Piping Category: C
Piping Description: Fiberglass

Tank ID: 2
Piping Category: F
Piping Description: Double wall

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs
Tank ID:	4
Tank Capacity:	25000
Tank Location:	UNDERGROUND
Tank Status:	U-In Service
Status Date:	05/01/2007
Install Date:	5/1/2007
Substance:	D
Content Description:	Vehicular Diesel
Vessel Indicator:	TANK
DEP Contractor:	P
Owner:	
Owner ID:	23375

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address 2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip: Orlando, FL 32830
Owner Contact: KIM RUSH
Owner Phone: 4074511518

Construction:

Tank ID: 1
Construction Category: C
Construction Description: Steel

Tank ID: 1
Construction Category: I
Construction Description: Double wall

Tank ID: 1
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 1
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 1
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 2
Construction Category: C
Construction Description: Steel

Tank ID: 2
Construction Category: I
Construction Description: Double wall

Tank ID: 2
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 2
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 2
Construction Category: O
Construction Description: Tight fill

Tank ID: 2
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 3
Construction Category: C
Construction Description: Steel

Tank ID: 3

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Description: Flow shut-Off

Tank ID: 5
Construction Category: O
Construction Description: Tight fill

Tank ID: 5
Construction Category: P
Construction Description: Level gauges/alarms

Piping:

Tank ID: 3
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 3
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 4
Piping Category: C
Piping Description: Fiberglass

Tank ID: 4
Piping Category: F
Piping Description: Double wall

Tank ID: 4
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 4
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 5
Piping Category: C
Piping Description: Fiberglass

Tank ID: 5
Piping Category: F
Piping Description: Double wall

Tank ID: 5
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 5
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 2
Piping Category: C
Piping Description: Fiberglass

Tank ID: 2
Piping Category: F

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Description:	Double wall
Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs
Tank ID:	3
Tank Capacity:	25000
Tank Location:	UNDERGROUND
Tank Status:	U-In Service
Status Date:	05/01/2007
Install Date:	5/1/2007
Substance:	D
Content Description:	Vehicle Diesel
Vessel Indicator:	TANK
DEP Contractor:	P

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Owner:

Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address 2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip: Orlando, FL 32830
Owner Contact: KIM RUSH
Owner Phone: 4074511518

Construction:

Tank ID: 1
Construction Category: C
Construction Description: Steel

Tank ID: 1
Construction Category: I
Construction Description: Double wall

Tank ID: 1
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 1
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 1
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 2
Construction Category: C
Construction Description: Steel

Tank ID: 2
Construction Category: I
Construction Description: Double wall

Tank ID: 2
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 2
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 2
Construction Category: O
Construction Description: Tight fill

Tank ID: 2
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 3
Construction Category: C

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	5
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	5
Construction Category:	P
Construction Description:	Level gauges/alarms
Piping:	
Tank ID:	3
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	3
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	4
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	4
Piping Category:	F
Piping Description:	Double wall
Tank ID:	4
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	4
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	5
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	5
Piping Category:	F
Piping Description:	Double wall
Tank ID:	5
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	5
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	2
Piping Category:	C
Piping Description:	Fiberglass

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	2
Piping Category:	F
Piping Description:	Double wall
Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs
Tank ID:	1
Tank Capacity:	25000
Tank Location:	UNDERGROUND
Tank Status:	U-In Service
Status Date:	05/01/2007
Install Date:	5/1/2007
Substance:	D
Content Description:	Vehicular Diesel

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Vessel Indicator:	TANK
DEP Contractor:	P
Owner:	
Owner ID:	23375
Owner Name:	WALT DISNEY WORLD PARKS & RESORTS US
Owner Address:	PO BOX 10000
Owner Address 2:	ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip:	Orlando, FL 32830
Owner Contact:	KIM RUSH
Owner Phone:	4074511518
Construction:	
Tank ID:	1
Construction Category:	C
Construction Description:	Steel
Tank ID:	1
Construction Category:	I
Construction Description:	Double wall
Tank ID:	1
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	1
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	1
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	2
Construction Category:	C
Construction Description:	Steel
Tank ID:	2
Construction Category:	I
Construction Description:	Double wall
Tank ID:	2
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	2
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	2
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	2
Construction Category:	P
Construction Description:	Level gauges/alarms

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	3
Construction Category:	C
Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I
Construction Description:	Double wall
Tank ID:	5

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 5
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 5
Construction Category: O
Construction Description: Tight fill

Tank ID: 5
Construction Category: P
Construction Description: Level gauges/alarms

Piping:

Tank ID: 3
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 3
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 4
Piping Category: C
Piping Description: Fiberglass

Tank ID: 4
Piping Category: F
Piping Description: Double wall

Tank ID: 4
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 4
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 5
Piping Category: C
Piping Description: Fiberglass

Tank ID: 5
Piping Category: F
Piping Description: Double wall

Tank ID: 5
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 5
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 2

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	2
Piping Category:	F
Piping Description:	Double wall
Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs
Tank ID:	2
Tank Capacity:	25000
Tank Location:	UNDERGROUND
Tank Status:	U-In Service
Status Date:	05/01/2007

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Install Date: 5/1/2007
Substance: D
Content Description: Vehicular Diesel
Vessel Indicator: TANK
DEP Contractor: P

Owner:

Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address 2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip: Orlando, FL 32830
Owner Contact: KIM RUSH
Owner Phone: 4074511518

Construction:

Tank ID: 1
Construction Category: C
Construction Description: Steel

Tank ID: 1
Construction Category: I
Construction Description: Double wall

Tank ID: 1
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 1
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 1
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 2
Construction Category: C
Construction Description: Steel

Tank ID: 2
Construction Category: I
Construction Description: Double wall

Tank ID: 2
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 2
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 2
Construction Category: O
Construction Description: Tight fill

Tank ID: 2

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	3
Construction Category:	C
Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5
Construction Category:	I

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Construction Description:	Double wall
Tank ID:	5
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	5
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	5
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	5
Construction Category:	P
Construction Description:	Level gauges/alarms
Piping:	
Tank ID:	3
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	3
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	4
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	4
Piping Category:	F
Piping Description:	Double wall
Tank ID:	4
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	4
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	5
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	5
Piping Category:	F
Piping Description:	Double wall
Tank ID:	5
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	5
Piping Category:	K

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Piping Description:	Dispenser liners
Tank ID:	2
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	2
Piping Category:	F
Piping Description:	Double wall
Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

[Click here for Florida Oculus:](#)

AST:

Facility ID: 8622537
Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
Depco: P
Region: STATE
Positioning Method: AGPS
Latitude/Longitude: 28 23 35 / 81 34 31

Tank:

Tank ID: 33
Tank Capacity: 500
Tank Location: ABOVEGROUND
Tank Status: B-Removed from Site
Status Date: 06/20/2016
Install Date: 1/1/1995
Substance: L
Content Description: Waste Oil
Vessel Indicator: TANK
DEP Contractor: P

Piping:

Tank ID: 3
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 3
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 4
Piping Category: C
Piping Description: Fiberglass

Tank ID: 4
Piping Category: F
Piping Description: Double wall

Tank ID: 4
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 4
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 5
Piping Category: C
Piping Description: Fiberglass

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	5
Piping Category:	F
Piping Description:	Double wall
Tank ID:	5
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	5
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	2
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	2
Piping Category:	F
Piping Description:	Double wall
Tank ID:	2
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	2
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	3
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	3
Piping Category:	F
Piping Description:	Double wall
Tank ID:	1
Piping Category:	A
Piping Description:	Abv, no soil contact
Monitoring:	
Tank ID:	4
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	4
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	5
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	5
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Tank ID:	5
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	5
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	1
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	1
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	2
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	2
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	2
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	3
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	3
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	3
Petro Monitoring Category:	5
Monitoring Description:	Electronic monitor dispenser liners
Tank ID:	4
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	4
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	1
Petro Monitoring Category:	Q
Monitoring Description:	Visual inspection of ASTs
Owner:	
Owner ID:	23375
Owner Name:	WALT DISNEY WORLD PARKS & RESORTS US
Owner Address:	PO BOX 10000
Owner Address 2:	ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,State,Zip:	Orlando, FL 32830
Owner Contact:	KIM RUSH
Owner Phone:	4074511518
Construction:	
Tank ID:	1
Construction Category:	C
Construction Description:	Steel
Tank ID:	1
Construction Category:	I
Construction Description:	Double wall
Tank ID:	1
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	1
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	1
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	2
Construction Category:	C
Construction Description:	Steel
Tank ID:	2
Construction Category:	I
Construction Description:	Double wall
Tank ID:	2
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	2
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	2
Construction Category:	O
Construction Description:	Tight fill

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Tank ID:	2
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	3
Construction Category:	C
Construction Description:	Steel
Tank ID:	3
Construction Category:	I
Construction Description:	Double wall
Tank ID:	3
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	3
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	3
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	3
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	4
Construction Category:	C
Construction Description:	Steel
Tank ID:	4
Construction Category:	I
Construction Description:	Double wall
Tank ID:	4
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	4
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	4
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	4
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	5
Construction Category:	C
Construction Description:	Steel
Tank ID:	5

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Construction Category: I
Construction Description: Double wall

Tank ID: 5
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 5
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 5
Construction Category: O
Construction Description: Tight fill

Tank ID: 5
Construction Category: P
Construction Description: Level gauges/alarms

CLEANUP SITES:

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
DEP Cleanup Site Key: 80978106
Source Database Name: Storage Tank Contamination Monitoring
Source Database Id: 8622537
CPAC Program Area Id: TK
CLLC Cleanup Category Key: PETRO
RSC2 Remediation Status Key: ACTIVE
Data Load Date: 08/28/2024
OC3 Office Id: CD
Physical Address Line 2: Not reported
OIC Object Of Interest Id: FACIL
PC2 Proximity Id: EXACT
Calc Coordinates Accuracy Level Id: 4
CMC2 Coordinate Method Id: Digital Aerial Photography With Ground Control
DC4 Datum Id: North American Datum of 1983
VSC1 Verification Status: REVIEWED
Collect Username: BECKER_GT_1
Collect Date: 02/21/2018
Collect Affiliation: FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
Map Source: imagerywithroads
Map Source Scale: 4514
Interpolation Scale: Not reported
Verifier Username: BECKER_GT_1
Verifier Affiliation: FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
Verification Date: 02/21/2018
Verified Coordinate Method Id: Digital Aerial Photography With Ground Control
Source Database Name Code: STCM
CMC2 Coordinate Method ID Code: DPHO
DC4 Datum ID Code: NAD83
Verified Coordinate Method ID Code: DPHO
Comments: Not reported
Latitude/Longitude (deg/min/sec): 28 23 / 81 34

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

FL Financial Assurance 3:

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: ACE AMERICAN INSURANCE COMPANY
Effective Date: 06/16/2016
Expire Date: 06/16/2017
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: ACE AMERICAN INSURANCE COMPANY
Effective Date: 06/16/2017
Expire Date: 06/16/2018
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: ACE AMERICAN INSURANCE COMPANY

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Effective Date: Not reported
Expire Date: Not reported
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: ALAMEDA INSURANCE COMPANY
Effective Date: 03/31/2007
Expire Date: 03/31/2010
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: ARCH INSURANCE COMAPNY
Effective Date: 01/01/2015
Expire Date: 01/01/2016
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: ARCH INSURANCE COMPANY
Effective Date: 01/01/2016
Expire Date: 01/01/2017
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: ILLINOIS UNION INSURANCE COMPANY
Effective Date: 06/16/2018
Expire Date: 06/16/2019
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: ILLINOIS UNION INSURANCE COMPANY
Effective Date: 06/16/2019
Expire Date: 06/16/2020
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Finaincial Responsibility: INSURANCE
Insurance Company: ILLINOIS UNION INSURANCE COMPANY
Effective Date: 06/16/2020
Expire Date: 06/16/2021
Owner ID: 23375
Onwer Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Finaincial Responsibility: INSURANCE
Insurance Company: ILLINOIS UNION INSURANCE COMPANY
Effective Date: 06/16/2021
Expire Date: 06/16/2022
Owner ID: 23375
Onwer Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

U001364352

Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: ILLINOIS UNION INSURANCE COMPANY
Effective Date: 06/16/2022
Expire Date: 06/16/2023
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: ILLINOIS UNION INSURANCE COMPANY
Effective Date: 06/16/2023
Expire Date: 06/16/2024
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: SELF-INSURANCE - LETTER FROM CHIEF FINANCIAL OFFIC
Insurance Company: Not reported
Effective Date: 04/02/2013
Expire Date: 01/31/2014
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001364352

Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: SELF-INSURANCE - LETTER FROM CHIEF FINANCIAL OFFIC
Insurance Company: Not reported
Effective Date: 05/13/2010
Expire Date: 05/13/2011
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: SELF-INSURANCE - LETTER FROM CHIEF FINANCIAL OFFIC
Insurance Company: Not reported
Effective Date: 05/24/2011
Expire Date: 05/24/2012
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Region: 3
Facility ID: 8622537
Facility Phone: 4073905242
Facility Status: OPEN
Facility Type: C
Type Description: Fuel user/Non-retail
DEP CO: P
Financial Responsibility: SELF-INSURANCE - LETTER FROM CHIEF FINANCIAL OFFIC

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

U001364352

Insurance Company: Not reported
Effective Date: 09/29/2011
Expire Date: 01/29/2013
Owner ID: 23375
Owner Name: WALT DISNEY WORLD PARKS & RESORTS US
Owner Address: PO BOX 10000
Owner Address2: ATTN: MGR-ENVIRON CONTROL DEPT
Owner City,St,Zip: Orlando, FL 32830
Contact: KIM RUSH
Resp Party Phone: 4074511518

B5
NNW
1/2-1
0.503 mi.
2655 ft.

SPEEDWAY #46834-6899
1000 CAR CARE DR
LAKE BUENA VISTA, FL 32830

Site 2 of 8 in cluster B

LUST
UST
SPILLS
DWM CONTAM
Financial Assurance
NPDES

U001963255
N/A

LUST:

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: STATE
Facility Id: 9401665
Facility Status: OPEN
Facility Type: A - Retail Station
Facility Phone: (407)403-2995
Facility Cleanup Rank: Not reported
District: Central District
Lat/Long (dms): 28 23 35.9377 / 81 34 30.1831
Section: Not reported
Township: Not reported
Range: Not reported
Feature: Not reported
Method: AGPS
Datum: Not reported
Score: Not reported
Score Effective Date: 2015-06-12 00:00:00
Score When Ranked: Not reported
Operator: David Petersen
Name Update: 2024-10-30 00:00:00
Address Update: 2024-10-30 00:00:00

Petroleum Cleanup PCT Facility Score:

Facility Cleanup Status: NREQ - NOT REQUIRED
Contact: DAVID PETERSEN
Contact Company: SPEEDWAY LLC
Contact Address: PO BOX 711
Contact City/State/Zip: Dallas, TX 75221
Phone: (407)403-2995
Bad Address Ind: N
State: FL
Zip: 32830
Score: Not reported
Score Effective Date: 2015-06-12 00:00:00
Related Party ID: 71776
Primary RP Role: ACCOUNT OWNER
RP Begin Date: 2015-10-14

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

RP Zip:	711
RP Extension:	Not reported
Discharge Cleanup Summary:	
Discharge Date:	4/25/2015
PCT Discharge Combined:	Not reported
Cleanup Required:	N - NO CLEANUP REQUIRED
Discharge Cleanup Status:	NREQ - CLEANUP NOT REQUIRED
Disch Cleanup Status Date:	7/11/2017
Cleanup Work Status:	COMPLETED
Information Source:	D - DISCHARGE NOTIFICATION
Other Source Description:	Not reported
Eligibility Indicator:	I - INELIGIBLE
Site Manager:	VOLPE_NI
Site Mgr End Date:	7/11/2017
Tank Office:	PCLP48 - ORANGE COUNTY ENVIRONMENTAL PROTECTION DIV
Contaminated Media:	
Discharge Date:	4/25/2015
Pct Discharge Combined With:	Not reported
Cleanup Required:	N - NO CLEANUP REQUIRED
Discharge Cleanup Status:	NREQ - CLEANUP NOT REQUIRED
Disch Cleanup Status Date:	7/11/2017
Cleanup Work Status:	COMPLETED
Information Source:	D - DISCHARGE NOTIFICATION
Other Source Description:	Not reported
Elig Indicator:	I - INELIGIBLE
Site Manager:	VOLPE_NI
Site Mgr End Date:	7/11/2017
Tank Office:	PCLP48 - ORANGE COUNTY ENVIRON
Contaminated Drinking Wells:	Not reported
Contaminated Monitoring Well:	No
Contaminated Soil:	No
Contaminated Surface Water:	No
Contaminated Ground Water:	Yes
Pollutant:	D - Vehicular Diesel
Pollutant Other Description:	Not reported
Gallons Discharged:	50
Task Information:	
District:	CD
Facility ID:	9401665
Facility Status:	OPEN
Facility Type:	A - Retail Station -
County:	ORANGE
County ID:	48
Cleanup Eligibility Status:	I
Source Effective Date:	Not reported
Discharge Date:	04-25-2015
Cleanup Required:	N - NO CLEANUP REQUIRED
Discharge Cleanup Status:	NREQ - CLEANUP NOT REQUIRED
Disch Cleanup Status Date:	07-11-2017
SRC Action Type:	Not reported
SRC Submit Date:	Not reported
SRC Review Date:	Not reported
SRC Completion Status:	Not reported
SRC Issue Date:	Not reported
SRC Comment:	Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Cleanup Work Status:	COMPLETED
Site Mgr:	VOLPE_NI
Site Mgr End Date:	07-11-2017
Tank Office:	PCLP48 - Orange County
SR Task ID:	Not reported
SR Cleanup Responsible:	Not reported
SR Funding Eligibility Type:	Not reported
SR Actual Cost:	Not reported
SR Completion Date:	Not reported
SR Payment Date:	Not reported
SR Oral Date:	Not reported
SR Written Date:	Not reported
SR Soil Removal:	Not reported
SR Free Product Removal:	Not reported
SR Soil Tonnage Removed:	Not reported
SR Soil Treatment:	Not reported
SR Other Treatment:	Not reported
SR Alternate Proc Received Date:	Not reported
SR Alternate Procedure Status:	Not reported
SR Alternate Procedure Status Date:	Not reported
SR Alternate Procedure Comments:	Not reported
SA Task ID:	92320
SA Cleanup Responsible:	Not reported
SA Funding Eligibility Type:	Not reported
SA Actual Cost:	Not reported
SA Completion Date:	Not reported
SA Payment Date:	Not reported
RAP Task ID:	Not reported
RAP Cleanup Responsible ID:	Not reported
RAP Funding Eligibility Type:	Not reported
RAP Actual Cost:	Not reported
RAP Completion Date:	Not reported
RAP Payment Date:	Not reported
RAP Last Order Approved:	Not reported
RA Task ID:	Not reported
RA Cleanup Responsible:	Not reported
RA Funding Eligibility Type:	Not reported
RA Years to Complete:	Not reported
RA Actual Cost:	Not reported

[Click here for Florida Oculus:](#)

UST:	
Facility ID:	9401665
Name:	SPEEDWAY #46834-6899
Address:	1000 CAR CARE DR
City,State,Zip:	LAKE BUENA VISTA, FL 32830
Facility Phone:	4074032995
Facility Status:	OPEN
Facility Type:	A
Type Description:	Retail Station
Depco:	P
Region:	STATE
Positioning Method:	AGPS
Latitude/Longitude:	28 23 35 / 81 34 31

UST:

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Tank ID: 6
Tank Capacity: 20000
Tank Location: UNDERGROUND
Tank Status: U-In Service
Status Date: 09/01/2006
Install Date: 9/1/2006
Substance: B
Content Description: Unleaded Gas
Vessel Indicator: TANK
DEP Contractor: P

Owner:

Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address 2: GASOLINE DEPT 0148
Owner City,State,Zip: Dallas, TX 75221
Owner Contact: DAVID PETERSEN
Owner Phone: 4074032995

Construction:

Tank ID: 8
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 8
Construction Category: I
Construction Description: Double wall

Tank ID: 8
Construction Category: O
Construction Description: Tight fill

Tank ID: 8
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 6
Construction Category: E
Construction Description: Fiberglass

Tank ID: 6
Construction Category: A
Construction Description: Ball check valve

Tank ID: 6
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 6
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 6
Construction Category: I
Construction Description: Double wall

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Tank ID:	6
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	6
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	7
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	7
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	7
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	7
Construction Category:	I
Construction Description:	Double wall
Tank ID:	7
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	7
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	L
Construction Description:	Compartmented
Tank ID:	8
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	8
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	8
Construction Category:	M
Construction Description:	Spill containment bucket
Piping:	
Tank ID:	8
Piping Category:	C
Piping Description:	Fiberglass

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Tank ID:	8
Piping Category:	F
Piping Description:	Double wall
Tank ID:	8
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	8
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	6
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	6
Piping Category:	F
Piping Description:	Double wall
Tank ID:	6
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	6
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	7
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	7
Piping Category:	F
Piping Description:	Double wall
Tank ID:	7
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	7
Piping Category:	K
Piping Description:	Dispenser liners
Monitoring:	
Tank ID:	7
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	7
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	7
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Tank ID:	7
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	8
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	8
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	8
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	8
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	8
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	6
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	6
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	6
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	6
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	6
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	7
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	1
Tank Capacity:	10000
Tank Location:	UNDERGROUND
Tank Status:	B-Removed from Site
Status Date:	09/21/2006
Install Date:	9/1/1994
Substance:	B
Content Description:	Unleaded Gas

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Vessel Indicator:	TANK
DEP Contractor:	P
Owner:	
Owner ID:	71776
Owner Name:	SPEEDWAY LLC
Owner Address:	PO BOX 711
Owner Address 2:	GASOLINE DEPT 0148
Owner City,State,Zip:	Dallas, TX 75221
Owner Contact:	DAVID PETERSEN
Owner Phone:	4074032995
Construction:	
Tank ID:	8
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	8
Construction Category:	I
Construction Description:	Double wall
Tank ID:	8
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	8
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	6
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	6
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	6
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	6
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	6
Construction Category:	I
Construction Description:	Double wall
Tank ID:	6
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	6
Construction Category:	P
Construction Description:	Level gauges/alarms

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Tank ID:	7
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	7
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	7
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	7
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	7
Construction Category:	I
Construction Description:	Double wall
Tank ID:	7
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	7
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	L
Construction Description:	Compartmented
Tank ID:	8
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	8
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	8
Construction Category:	M
Construction Description:	Spill containment bucket
Piping:	
Tank ID:	8
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	8
Piping Category:	F
Piping Description:	Double wall
Tank ID:	8
Piping Category:	J
Piping Description:	Pressurized piping system

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Tank ID:	8
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	6
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	6
Piping Category:	F
Piping Description:	Double wall
Tank ID:	6
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	6
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	7
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	7
Piping Category:	F
Piping Description:	Double wall
Tank ID:	7
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	7
Piping Category:	K
Piping Description:	Dispenser liners
Monitoring:	
Tank ID:	7
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	7
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	7
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	7
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	8
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Tank ID:	8
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	8
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	8
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	8
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	6
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	6
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	6
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	6
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	6
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	7
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	2
Tank Capacity:	8000
Tank Location:	UNDERGROUND
Tank Status:	B-Removed from Site
Status Date:	09/21/2006
Install Date:	9/1/1994
Substance:	B
Content Description:	Unleaded Gas
Vessel Indicator:	TANK
DEP Contractor:	P
Owner:	
Owner ID:	71776
Owner Name:	SPEEDWAY LLC
Owner Address:	PO BOX 711
Owner Address 2:	GASOLINE DEPT 0148
Owner City,State,Zip:	Dallas, TX 75221

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Owner Contact: DAVID PETERSEN
Owner Phone: 4074032995

Construction:

Tank ID: 8
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 8
Construction Category: I
Construction Description: Double wall

Tank ID: 8
Construction Category: O
Construction Description: Tight fill

Tank ID: 8
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 6
Construction Category: E
Construction Description: Fiberglass

Tank ID: 6
Construction Category: A
Construction Description: Ball check valve

Tank ID: 6
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 6
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 6
Construction Category: I
Construction Description: Double wall

Tank ID: 6
Construction Category: O
Construction Description: Tight fill

Tank ID: 6
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 7
Construction Category: E
Construction Description: Fiberglass

Tank ID: 7
Construction Category: A
Construction Description: Ball check valve

Tank ID: 7

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	7
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	7
Construction Category:	I
Construction Description:	Double wall
Tank ID:	7
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	7
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	L
Construction Description:	Compartmented
Tank ID:	8
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	8
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	8
Construction Category:	M
Construction Description:	Spill containment bucket
Piping:	
Tank ID:	8
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	8
Piping Category:	F
Piping Description:	Double wall
Tank ID:	8
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	8
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	6
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	6

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Piping Category: F
Piping Description: Double wall

Tank ID: 6
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 6
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 7
Piping Category: C
Piping Description: Fiberglass

Tank ID: 7
Piping Category: F
Piping Description: Double wall

Tank ID: 7
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 7
Piping Category: K
Piping Description: Dispenser liners

Monitoring:
Tank ID: 7
Petro Monitoring Category: G
Monitoring Description: Electronic line leak detector

Tank ID: 7
Petro Monitoring Category: F
Monitoring Description: Monitor dbl wall tank space

Tank ID: 7
Petro Monitoring Category: 1
Monitoring Description: Continuous electronic sensing

Tank ID: 7
Petro Monitoring Category: 3
Monitoring Description: Electronic monitor pipe sumps

Tank ID: 8
Petro Monitoring Category: L
Monitoring Description: Automatic tank gauging - USTs

Tank ID: 8
Petro Monitoring Category: G
Monitoring Description: Electronic line leak detector

Tank ID: 8
Petro Monitoring Category: F
Monitoring Description: Monitor dbl wall tank space

Tank ID: 8

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	8
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	6
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	6
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	6
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	6
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	6
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	7
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	3
Tank Capacity:	8000
Tank Location:	UNDERGROUND
Tank Status:	B-Removed from Site
Status Date:	09/21/2006
Install Date:	9/1/1994
Substance:	B
Content Description:	Unleaded Gas
Vessel Indicator:	TANK
DEP Contractor:	P
Owner:	
Owner ID:	71776
Owner Name:	SPEEDWAY LLC
Owner Address:	PO BOX 711
Owner Address 2:	GASOLINE DEPT 0148
Owner City,State,Zip:	Dallas, TX 75221
Owner Contact:	DAVID PETERSEN
Owner Phone:	4074032995
Construction:	
Tank ID:	8
Construction Category:	N
Construction Description:	Flow shut-Off

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Tank ID:	8
Construction Category:	I
Construction Description:	Double wall
Tank ID:	8
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	8
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	6
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	6
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	6
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	6
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	6
Construction Category:	I
Construction Description:	Double wall
Tank ID:	6
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	6
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	7
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	7
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	7
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	7

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Construction Category:	I
Construction Description:	Double wall
Tank ID:	7
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	7
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	L
Construction Description:	Compartmented
Tank ID:	8
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	8
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	8
Construction Category:	M
Construction Description:	Spill containment bucket
Piping:	
Tank ID:	8
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	8
Piping Category:	F
Piping Description:	Double wall
Tank ID:	8
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	8
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	6
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	6
Piping Category:	F
Piping Description:	Double wall
Tank ID:	6
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	6

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	7
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	7
Piping Category:	F
Piping Description:	Double wall
Tank ID:	7
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	7
Piping Category:	K
Piping Description:	Dispenser liners
Monitoring:	
Tank ID:	7
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	7
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	7
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	7
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	8
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	8
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	8
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	8
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	8
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	6

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	6
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	6
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	6
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	6
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	7
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	4
Tank Capacity:	8000
Tank Location:	UNDERGROUND
Tank Status:	B-Removed from Site
Status Date:	09/21/2006
Install Date:	9/1/1994
Substance:	B
Content Description:	Unleaded Gas
Vessel Indicator:	TANK
DEP Contractor:	P
Owner:	
Owner ID:	71776
Owner Name:	SPEEDWAY LLC
Owner Address:	PO BOX 711
Owner Address 2:	GASOLINE DEPT 0148
Owner City,State,Zip:	Dallas, TX 75221
Owner Contact:	DAVID PETERSEN
Owner Phone:	4074032995
Construction:	
Tank ID:	8
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	8
Construction Category:	I
Construction Description:	Double wall
Tank ID:	8
Construction Category:	O
Construction Description:	Tight fill

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Tank ID:	8
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	6
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	6
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	6
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	6
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	6
Construction Category:	I
Construction Description:	Double wall
Tank ID:	6
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	6
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	7
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	7
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	7
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	7
Construction Category:	I
Construction Description:	Double wall
Tank ID:	7
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	7

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)

EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 7
Construction Category: L
Construction Description: Compartmented

Tank ID: 8
Construction Category: E
Construction Description: Fiberglass

Tank ID: 8
Construction Category: A
Construction Description: Ball check valve

Tank ID: 8
Construction Category: M
Construction Description: Spill containment bucket

Piping:

Tank ID: 8
Piping Category: C
Piping Description: Fiberglass

Tank ID: 8
Piping Category: F
Piping Description: Double wall

Tank ID: 8
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 8
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 6
Piping Category: C
Piping Description: Fiberglass

Tank ID: 6
Piping Category: F
Piping Description: Double wall

Tank ID: 6
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 6
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 7
Piping Category: C
Piping Description: Fiberglass

Tank ID: 7

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Piping Category:	F
Piping Description:	Double wall
Tank ID:	7
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	7
Piping Category:	K
Piping Description:	Dispenser liners
Monitoring:	
Tank ID:	7
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	7
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	7
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	7
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	8
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	8
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	8
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	8
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	8
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	6
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	6
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	6

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Petro Monitoring Category: F
Monitoring Description: Monitor dbl wall tank space

Tank ID: 6
Petro Monitoring Category: 1
Monitoring Description: Continuous electronic sensing

Tank ID: 6
Petro Monitoring Category: 3
Monitoring Description: Electronic monitor pipe sumps

Tank ID: 7
Petro Monitoring Category: L
Monitoring Description: Automatic tank gauging - USTs

Tank ID: 5
Tank Capacity: 8000
Tank Location: UNDERGROUND
Tank Status: B-Removed from Site
Status Date: 09/21/2006
Install Date: 9/1/1994
Substance: D
Content Description: Vehicular Diesel
Vessel Indicator: TANK
DEP Contractor: P

Owner:

Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address 2: GASOLINE DEPT 0148
Owner City,State,Zip: Dallas, TX 75221
Owner Contact: DAVID PETERSEN
Owner Phone: 4074032995

Construction:

Tank ID: 8
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 8
Construction Category: I
Construction Description: Double wall

Tank ID: 8
Construction Category: O
Construction Description: Tight fill

Tank ID: 8
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 6
Construction Category: E
Construction Description: Fiberglass

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Tank ID:	6
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	6
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	6
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	6
Construction Category:	I
Construction Description:	Double wall
Tank ID:	6
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	6
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	7
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	7
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	7
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	7
Construction Category:	I
Construction Description:	Double wall
Tank ID:	7
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	7
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	L
Construction Description:	Compartmented
Tank ID:	8

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Construction Category: E
Construction Description: Fiberglass

Tank ID: 8
Construction Category: A
Construction Description: Ball check valve

Tank ID: 8
Construction Category: M
Construction Description: Spill containment bucket

Piping:

Tank ID: 8
Piping Category: C
Piping Description: Fiberglass

Tank ID: 8
Piping Category: F
Piping Description: Double wall

Tank ID: 8
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 8
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 6
Piping Category: C
Piping Description: Fiberglass

Tank ID: 6
Piping Category: F
Piping Description: Double wall

Tank ID: 6
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 6
Piping Category: K
Piping Description: Dispenser liners

Tank ID: 7
Piping Category: C
Piping Description: Fiberglass

Tank ID: 7
Piping Category: F
Piping Description: Double wall

Tank ID: 7
Piping Category: J
Piping Description: Pressurized piping system

Tank ID: 7

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Piping Category:	K
Piping Description:	Dispenser liners
Monitoring:	
Tank ID:	7
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	7
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	7
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	7
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	8
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	8
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	8
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	8
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	8
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	6
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	6
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	6
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	6
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	6

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Petro Monitoring Category: 3
Monitoring Description: Electronic monitor pipe sumps

Tank ID: 7
Petro Monitoring Category: L
Monitoring Description: Automatic tank gauging - USTs

Tank ID: 8
Tank Capacity: 20000
Tank Location: UNDERGROUND
Tank Status: U-In Service
Status Date: 09/01/2006
Install Date: 9/1/2006
Substance: D
Content Description: Vehicular Diesel
Vessel Indicator: TANK
DEP Contractor: P

Owner:
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address 2: GASOLINE DEPT 0148
Owner City,State,Zip: Dallas, TX 75221
Owner Contact: DAVID PETERSEN
Owner Phone: 4074032995

Construction:
Tank ID: 8
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 8
Construction Category: I
Construction Description: Double wall

Tank ID: 8
Construction Category: O
Construction Description: Tight fill

Tank ID: 8
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 6
Construction Category: E
Construction Description: Fiberglass

Tank ID: 6
Construction Category: A
Construction Description: Ball check valve

Tank ID: 6
Construction Category: M
Construction Description: Spill containment bucket

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Tank ID:	6
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	6
Construction Category:	I
Construction Description:	Double wall
Tank ID:	6
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	6
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	7
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	7
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	7
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	7
Construction Category:	I
Construction Description:	Double wall
Tank ID:	7
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	7
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	L
Construction Description:	Compartmented
Tank ID:	8
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	8
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	8

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Construction Category:	M
Construction Description:	Spill containment bucket
Piping:	
Tank ID:	8
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	8
Piping Category:	F
Piping Description:	Double wall
Tank ID:	8
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	8
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	6
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	6
Piping Category:	F
Piping Description:	Double wall
Tank ID:	6
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	6
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	7
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	7
Piping Category:	F
Piping Description:	Double wall
Tank ID:	7
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	7
Piping Category:	K
Piping Description:	Dispenser liners
Monitoring:	
Tank ID:	7
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Tank ID:	7
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	7
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	7
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	8
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	8
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	8
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	8
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	8
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	6
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	6
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	6
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	6
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	6
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	7
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Tank ID: 7
Tank Capacity: 20000
Tank Location: UNDERGROUND
Tank Status: U-In Service
Status Date: 09/01/2006
Install Date: 9/1/2006
Substance: B
Content Description: Unleaded Gas
Vessel Indicator: TANK
DEP Contractor: P

Owner:

Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address 2: GASOLINE DEPT 0148
Owner City,State,Zip: Dallas, TX 75221
Owner Contact: DAVID PETERSEN
Owner Phone: 4074032995

Construction:

Tank ID: 8
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 8
Construction Category: I
Construction Description: Double wall

Tank ID: 8
Construction Category: O
Construction Description: Tight fill

Tank ID: 8
Construction Category: P
Construction Description: Level gauges/alarms

Tank ID: 6
Construction Category: E
Construction Description: Fiberglass

Tank ID: 6
Construction Category: A
Construction Description: Ball check valve

Tank ID: 6
Construction Category: M
Construction Description: Spill containment bucket

Tank ID: 6
Construction Category: N
Construction Description: Flow shut-Off

Tank ID: 6
Construction Category: I
Construction Description: Double wall

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Tank ID:	6
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	6
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	7
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	7
Construction Category:	M
Construction Description:	Spill containment bucket
Tank ID:	7
Construction Category:	N
Construction Description:	Flow shut-Off
Tank ID:	7
Construction Category:	I
Construction Description:	Double wall
Tank ID:	7
Construction Category:	O
Construction Description:	Tight fill
Tank ID:	7
Construction Category:	P
Construction Description:	Level gauges/alarms
Tank ID:	7
Construction Category:	L
Construction Description:	Compartmented
Tank ID:	8
Construction Category:	E
Construction Description:	Fiberglass
Tank ID:	8
Construction Category:	A
Construction Description:	Ball check valve
Tank ID:	8
Construction Category:	M
Construction Description:	Spill containment bucket
Piping:	
Tank ID:	8
Piping Category:	C
Piping Description:	Fiberglass

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Tank ID:	8
Piping Category:	F
Piping Description:	Double wall
Tank ID:	8
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	8
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	6
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	6
Piping Category:	F
Piping Description:	Double wall
Tank ID:	6
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	6
Piping Category:	K
Piping Description:	Dispenser liners
Tank ID:	7
Piping Category:	C
Piping Description:	Fiberglass
Tank ID:	7
Piping Category:	F
Piping Description:	Double wall
Tank ID:	7
Piping Category:	J
Piping Description:	Pressurized piping system
Tank ID:	7
Piping Category:	K
Piping Description:	Dispenser liners
Monitoring:	
Tank ID:	7
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	7
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	7
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Tank ID:	7
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	8
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	8
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	8
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	8
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	8
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	6
Petro Monitoring Category:	G
Monitoring Description:	Electronic line leak detector
Tank ID:	6
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs
Tank ID:	6
Petro Monitoring Category:	F
Monitoring Description:	Monitor dbl wall tank space
Tank ID:	6
Petro Monitoring Category:	1
Monitoring Description:	Continuous electronic sensing
Tank ID:	6
Petro Monitoring Category:	3
Monitoring Description:	Electronic monitor pipe sumps
Tank ID:	7
Petro Monitoring Category:	L
Monitoring Description:	Automatic tank gauging - USTs

[Click here for Florida Oculus:](#)

SPILLS:

Name:	Not reported
Address:	1000 CAR CARE LANE
City,State,Zip:	LAKE BUENA VISTA, FL
OHMIT Incident Number:	52842

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Incident Legacy:	Not reported
On-Scene Response:	No
Criminal Indicator:	No
Hurricane Indicator:	No
Incident Date:	04/25/2015
Incident Status:	Closed
Incident Report Date:	04/25/2015
Pollutant:	Diesel fuel
Pollutants Category:	Petroleum
Substance Spilled:	Diesel fuel
Amount Spilled (Gallons):	50.00
Pollutant - Unit Measure:	gallon
Incident Party Name:	Cardno
Description:	Inland
Incident Party Name:	Cardno
Description:	Inland
Incident Party Name:	Cardno
Description:	Inland
Incident Party Name:	Cardno
Description:	Inland
Incident Party Name:	Cardno
Description:	Inland
Incident Party Name:	NRC
Description:	Inland
Incident Party Name:	NRC
Description:	Inland
Incident Party Name:	NRC
Description:	Inland
Incident Party Name:	NRC
Description:	Inland
Incident Party Name:	NRC
Description:	Inland
Incident Party Name:	Petrotech Southeast, Inc.
Description:	Inland
Incident Party Name:	Petrotech Southeast, Inc.
Description:	Inland
Incident Party Name:	Petrotech Southeast, Inc.
Description:	Inland
Incident Party Name:	Petrotech Southeast, Inc.
Description:	Inland
Incident Party Name:	Petrotech Southeast, Inc.
Description:	Inland

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Incident Party Name:	Southwest Florida Water Management District
Description:	Inland
Incident Party Name:	Southwest Florida Water Management District
Description:	Inland
Incident Party Name:	Southwest Florida Water Management District
Description:	Inland
Incident Party Name:	Southwest Florida Water Management District
Description:	Inland
Incident Party Name:	Southwest Florida Water Management District
Description:	Inland
Incident Party Name:	Speedway # 6899
Description:	Inland
Incident Party Name:	Speedway # 6899
Description:	Inland
Incident Party Name:	Speedway # 6899
Description:	Inland
Incident Party Name:	Speedway # 6899
Description:	Inland
Incident Party Name:	Speedway # 6899
Description:	Inland
Incident Party Name:	Speedway # 6899
Description:	Inland
Incident Party Name:	Speedway # 6899
Description:	Inland
Incident Party Name:	Speedway # 6899
Description:	Inland
Incident Party Name:	Walt Disney World
Description:	Inland
Incident Party Name:	Walt Disney World
Description:	Inland
Incident Party Name:	Walt Disney World
Description:	Inland
Incident Party Name:	Walt Disney World
Description:	Inland

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Incident Party Name:	Walt Disney World
Description:	Inland
Incident Party Name:	Walt Disney World
Description:	Inland
Incident Party Name:	Walt Disney World
Description:	Inland
Incident Party Name:	Walt Disney World
Description:	Inland
Incident Party Name:	Walt Disney World
Description:	Inland
Incident Party Name:	Walt Disney World
Description:	Inland
Incident Party Name:	Walt Disney World
Description:	Inland
Incident Party Name:	Walt Disney World
Description:	Inland
Incident Party Name:	Walt Disney World
Description:	Inland

DWM CONTAM:

Name:	SPEEDWAY #6899
Address:	1000 CAR CARE DR
City,State,Zip:	LAKE BUENA VISTA, FL
Program Site Id:	9401665
Lat DD:	28
Lat MM:	23
Lat SS:	35
Long DD:	81
Long MM:	34
Long SS:	31
Office/ District:	CD
Program Area:	PETROLEUM
Priority Score:	Not reported
Datum:	Not reported
Method:	AGPS
Facility Status:	CLOSED-STCM
Facility Type:	Not reported
Score Effective Date:	Not reported
Score When Ranked:	Not reported
Rank:	Not reported
Operator:	Not reported
Phone:	Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Name Changed: Not reported
Addr Changed: Not reported
Related Party ID: Not reported
Primary RP Role: Not reported
RP Begin Date: Not reported
RP Name: Not reported
RP Address1: Not reported
RP Address2: Not reported
RP City: Not reported
RP State: Not reported
RP Zip5: Not reported
RP Zip4: Not reported
Contact: Not reported
RP Phone: Not reported
RP Extension: Not reported
Site Manager: Not reported

FL Financial Assurance 3:

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: 3
Facility ID: 9401665
Facility Phone: 4074032995
Facility Status: OPEN
Facility Type: A
Type Description: Retail Station
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: IRONSHORE SPECIALTY INSURANCE COMPANY
Effective Date: 12/18/2021
Expire Date: 12/18/2023
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address2: GASOLINE DEPT 0148
Owner City,St,Zip: Dallas, TX 75221
Contact: DAVID PETERSEN
Resp Party Phone: 4074032995

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: 3
Facility ID: 9401665
Facility Phone: 4074032995
Facility Status: OPEN
Facility Type: A
Type Description: Retail Station
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: LIBERTY MUTUAL INSURANCE COMPANY
Effective Date: 01/01/2019
Expire Date: 12/31/2019
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Owner Address2: GASOLINE DEPT 0148
Owner City,St,Zip: Dallas, TX 75221
Contact: DAVID PETERSEN
Resp Party Phone: 4074032995

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: 3
Facility ID: 9401665
Facility Phone: 4074032995
Facility Status: OPEN
Facility Type: A
Type Description: Retail Station
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: LIBERTY MUTUAL INSURANCE COMPANY
Effective Date: 01/01/2020
Expire Date: 12/31/2020
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address2: GASOLINE DEPT 0148
Owner City,St,Zip: Dallas, TX 75221
Contact: DAVID PETERSEN
Resp Party Phone: 4074032995

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: 3
Facility ID: 9401665
Facility Phone: 4074032995
Facility Status: OPEN
Facility Type: A
Type Description: Retail Station
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: LIBERTY MUTUAL INSURANCE COMPANY
Effective Date: 01/01/2021
Expire Date: 12/31/2021
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address2: GASOLINE DEPT 0148
Owner City,St,Zip: Dallas, TX 75221
Contact: DAVID PETERSEN
Resp Party Phone: 4074032995

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: 3
Facility ID: 9401665
Facility Phone: 4074032995
Facility Status: OPEN
Facility Type: A

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Type Description: Retail Station
DEP CO: P
Financial Responsibility: INSURANCE
Insurance Company: TRAVELERS
Effective Date: 01/01/2015
Expire Date: 12/31/2015
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address2: GASOLINE DEPT 0148
Owner City,St,Zip: Dallas, TX 75221
Contact: DAVID PETERSEN
Resp Party Phone: 4074032995

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: 3
Facility ID: 9401665
Facility Phone: 4074032995
Facility Status: OPEN
Facility Type: A
Type Description: Retail Station
DEP CO: P
Financial Responsibility: SELF-INSURANCE - LETTER FROM CHIEF FINANCIAL OFFIC
Insurance Company: Not reported
Effective Date: 04/29/2010
Expire Date: 04/30/2011
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address2: GASOLINE DEPT 0148
Owner City,St,Zip: Dallas, TX 75221
Contact: DAVID PETERSEN
Resp Party Phone: 4074032995

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: 3
Facility ID: 9401665
Facility Phone: 4074032995
Facility Status: OPEN
Facility Type: A
Type Description: Retail Station
DEP CO: P
Financial Responsibility: SELF-INSURANCE - LETTER FROM CHIEF FINANCIAL OFFIC
Insurance Company: Not reported
Effective Date: 04/30/2009
Expire Date: 04/30/2010
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address2: GASOLINE DEPT 0148
Owner City,St,Zip: Dallas, TX 75221
Contact: DAVID PETERSEN
Resp Party Phone: 4074032995

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: 3
Facility ID: 9401665
Facility Phone: 4074032995
Facility Status: OPEN
Facility Type: A
Type Description: Retail Station
DEP CO: P
Financial Responsibility: SELF-INSURANCE - LETTER FROM CHIEF FINANCIAL OFFIC
Insurance Company: Not reported
Effective Date: 04/30/2011
Expire Date: 04/30/2012
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address2: GASOLINE DEPT 0148
Owner City,St,Zip: Dallas, TX 75221
Contact: DAVID PETERSEN
Resp Party Phone: 4074032995

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: 3
Facility ID: 9401665
Facility Phone: 4074032995
Facility Status: OPEN
Facility Type: A
Type Description: Retail Station
DEP CO: P
Financial Responsibility: SELF-INSURANCE - LETTER FROM CHIEF FINANCIAL OFFIC
Insurance Company: Not reported
Effective Date: 04/30/2013
Expire Date: 04/29/2014
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address2: GASOLINE DEPT 0148
Owner City,St,Zip: Dallas, TX 75221
Contact: DAVID PETERSEN
Resp Party Phone: 4074032995

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: 3
Facility ID: 9401665
Facility Phone: 4074032995
Facility Status: OPEN
Facility Type: A
Type Description: Retail Station
DEP CO: P
Financial Responsibility: SELF-INSURANCE - LETTER FROM CHIEF FINANCIAL OFFIC
Insurance Company: Not reported
Effective Date: 04/30/2014

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #46834-6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001963255

Expire Date: 04/29/2015
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address2: GASOLINE DEPT 0148
Owner City,St,Zip: Dallas, TX 75221
Contact: DAVID PETERSEN
Resp Party Phone: 4074032995

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: 3
Facility ID: 9401665
Facility Phone: 4074032995
Facility Status: OPEN
Facility Type: A
Type Description: Retail Station
DEP CO: P
Financial Responsibility: SURETY BOND
Insurance Company: LIBERTY MUTUAL
Effective Date: 01/01/2017
Expire Date: 12/31/2017
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address2: GASOLINE DEPT 0148
Owner City,St,Zip: Dallas, TX 75221
Contact: DAVID PETERSEN
Resp Party Phone: 4074032995

Name: SPEEDWAY #46834-6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Region: 3
Facility ID: 9401665
Facility Phone: 4074032995
Facility Status: OPEN
Facility Type: A
Type Description: Retail Station
DEP CO: P
Financial Responsibility: SURETY BOND
Insurance Company: LIBERTY MUTUAL
Effective Date: 11/01/2015
Expire Date: 12/31/2016
Owner ID: 71776
Owner Name: SPEEDWAY LLC
Owner Address: PO BOX 711
Owner Address2: GASOLINE DEPT 0148
Owner City,St,Zip: Dallas, TX 75221
Contact: DAVID PETERSEN
Resp Party Phone: 4074032995

WASTEWATER:

Name: RCID WORLD DRIVE EXTENSION (CONTRACT#C004129)
Address: 1000 CAR CARE LN
City,State,Zip: LAKE BUENA VISTA, FL

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

Facility ID: FLR20BC58
Facility Type: Construction Generic Dewatering
Status: Active - Existing, permitted facility/site for which effluent, reclaimed water or wastewater residual discharge into the environment and/or monitoring is taking place.

District Office: TLST
NPDES Permitted Site: Not reported
Environmental Interest: Not reported
Owner Type: Unknown
Permit Capacity: Not reported
Party Name: Erik Johnson, EHS Mgr
Company Name: Superior Construction Company Southeast, LLC
RP Address: 7072 Business Park Blvd N
RP Address 2: Not reported
RP City,Stat,Zip: Jacksonville FL 32256-2749
Telephone: 9042924240
Email: ejohnson@superiorse.com
Issue Date: 12/30/2016
Effective Date: 12/30/2016
Expiration Date: 12/29/2021
DOC Description: Generic Permit
Latitude Degrees: 28
Latitude Minutes: 23
Latitude Seconds: 39.3
Longitude Degrees: 81
Longitude Minutes: 34
Longitude Seconds: 16.46
Treatment: Not reported
Decode For Fstatus: Active
Cell Phone: Not reported
Permit Type: Not reported
Major Minor Discharge: Not reported
Nature of Business: Not reported

Name: RCID WORLD DRIVE AT BUENA VISTA DRIVE MODIFICATION
Address: 1000 CAR CARE LN
City,State,Zip: LAKE BUENA VISTA, FL
Facility ID: FLR10QW32
Facility Type: Construction Stormwater GP
Status: Active - Existing, permitted facility/site for which effluent, reclaimed water or wastewater residual discharge into the environment and/or monitoring is taking place.

District Office: TLST
NPDES Permitted Site: Not reported
Environmental Interest: Not reported
Owner Type: Unknown
Permit Capacity: Not reported
Party Name: Damon Cottingham, PMTE
Company Name: Southland Construction, Inc
RP Address: 172 W Fourth St
RP Address 2: Not reported
RP City,Stat,Zip: Apopka FL 32703
Telephone: 4078899844
Email: damonc@southlandconstruction.com
Issue Date: 03/11/2017
Effective Date: 03/11/2017
Expiration Date: 03/10/2022

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SPEEDWAY #46834-6899 (Continued)

U001963255

DOC Description: Generic Permit
Latitude Degrees: 28
Latitude Minutes: 21
Latitude Seconds: 48.6
Longitude Degrees: 81
Longitude Minutes: 33
Longitude Seconds: 57.1
Treatment: Not reported
Decode For Fstatus: Active
Cell Phone: Not reported
Permit Type: Not reported
Major Minor Discharge: Not reported
Nature of Business: Not reported

Name: CAR CARE UTILITY
Address: 1000 CAR CARE DR. #C
City,State,Zip: LAKE BUENA VISTA, FL
Facility ID: FLG073445
Facility Type: Dewatering GP
Status: Active - Existing, permitted facility/site for which effluent, reclaimed water or wastewater residual discharge into the environment and/or monitoring is taking place.

District Office: CD
NPDES Permitted Site: Yes
Environmental Interest: Industrial Wastewater Program
Owner Type: Private
Permit Capacity: -
Party Name: Scott Justice
Company Name: Walt Disney Parks and Resorts US Inc
RP Address: Po Box 10000
RP Address 2: -
RP City,Stat,Zip: Lake Buena Vista, FL 32830 1000
Telephone: 4078281739
Email: scott.a.justice@disney.com
Issue Date: 08/03/2022
Effective Date: 08/03/2022
Expiration Date: 08/02/2027
DOC Description: Not reported
Latitude Degrees: Not reported
Latitude Minutes: Not reported
Latitude Seconds: Not reported
Longitude Degrees: Not reported
Longitude Minutes: Not reported
Longitude Seconds: Not reported
Treatment: -
Decode For Fstatus: Active
Cell Phone: -
Permit Type: Generic Permit
Major Minor Discharge: MI
Nature of Business: -

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

B6
NNW
1/2-1
0.503 mi.
2655 ft.

WALT DISNEY WORLD CAR CARE CTR
1000 CAR CARE CENTER DR
ORLANDO, FL 0

UST FINDER
UST FINDER RELEASE

EDR ID Number
EPA ID Number

1028229512
N/A

Site 3 of 8 in cluster B

UST FINDER:

Object ID: 83279
Facility ID: FL8622537
Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE CENTER DR
City,State,Zip: ORLANDO, FL 32830
Address Match Type: Not reported
Open USTs: 5
Closed USTs: 11
TOS USTs: 0
Population 1500ft: 0
Private Wells 1500ft: 0
Within 100yr Floodplain: No
Land Use: Developed, High Intensity
Within SPA: No
SPA PWS Facility ID: Not reported
SPA Water Type: Not reported
SPA Facility Type: Not reported
SPA HUC12: Not reported
Within WHPA: No
WHPA PWS Facility ID: Not reported
WHPA Water Type: Not reported
WHPA Facility Type: Not reported
WHPA HUC12: Not reported
Facility Status: Open UST(s)
Date of Last Inspection: Not reported
EPA Region: 4
Tribe: Not reported
Coordinate Source: State
X Coord: -81.57527778
Y Coord: 28.3930555600001
Latitude: 28.39305556
Longitude: -81.57527778

UST FINDER:

Object ID: 197976
Facility ID: FL8622537
Tank ID: FL8622537-1
Tank Status: Open
Installation Date: 2007/05/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 25000
Substances: Vehicular Diesel
Tank Wall Type: Not reported

Object ID: 197977
Facility ID: FL8622537
Tank ID: FL8622537-2
Tank Status: Open
Installation Date: 2007/05/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 25000
Substances: Vehicular Diesel
Tank Wall Type: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

1028229512

Object ID: 197978
Facility ID: FL8622537
Tank ID: FL8622537-3
Tank Status: Open
Installation Date: 2007/05/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 25000
Substances: Vehicular Diesel
Tank Wall Type: Not reported

Object ID: 197979
Facility ID: FL8622537
Tank ID: FL8622537-4
Tank Status: Open
Installation Date: 2007/05/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 25000
Substances: Vehicular Diesel
Tank Wall Type: Not reported

Object ID: 197980
Facility ID: FL8622537
Tank ID: FL8622537-5
Tank Status: Open
Installation Date: 2007/05/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 12000
Substances: Unleaded Gas
Tank Wall Type: Not reported

Object ID: 217859
Facility ID: FL8622537
Tank ID: FL8622537-22R1
Tank Status: Closed
Installation Date: 1988/11/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 12000
Substances: Vehicular Diesel
Tank Wall Type: Not reported

Object ID: 267705
Facility ID: FL8622537
Tank ID: FL8622537-22
Tank Status: Closed
Installation Date: 1971/06/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 12000
Substances: Unleaded Gas
Tank Wall Type: Not reported

Object ID: 267706
Facility ID: FL8622537
Tank ID: FL8622537-23
Tank Status: Closed
Installation Date: 1971/06/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 12000

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

1028229512

Substances:	Vehicular Diesel
Tank Wall Type:	Not reported
Object ID:	267707
Facility ID:	FL8622537
Tank ID:	FL8622537-24
Tank Status:	Closed
Installation Date:	1971/06/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Vehicular Diesel
Tank Wall Type:	Not reported
Object ID:	267708
Facility ID:	FL8622537
Tank ID:	FL8622537-25
Tank Status:	Closed
Installation Date:	1971/06/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Unleaded Gas
Tank Wall Type:	Not reported
Object ID:	267709
Facility ID:	FL8622537
Tank ID:	FL8622537-26
Tank Status:	Closed
Installation Date:	1971/06/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Vehicular Diesel
Tank Wall Type:	Not reported
Object ID:	267710
Facility ID:	FL8622537
Tank ID:	FL8622537-27
Tank Status:	Closed
Installation Date:	1971/06/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Vehicular Diesel
Tank Wall Type:	Not reported
Object ID:	267711
Facility ID:	FL8622537
Tank ID:	FL8622537-28
Tank Status:	Closed
Installation Date:	1971/06/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Vehicular Diesel
Tank Wall Type:	Not reported
Object ID:	267712
Facility ID:	FL8622537
Tank ID:	FL8622537-29
Tank Status:	Closed

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

1028229512

Installation Date: 1971/06/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 12000
Substances: Unleaded Gas
Tank Wall Type: Not reported

Object ID: 267713
Facility ID: FL8622537
Tank ID: FL8622537-30
Tank Status: Closed
Installation Date: 1971/06/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 12000
Substances: Vehicular Diesel
Tank Wall Type: Not reported

Object ID: 267714
Facility ID: FL8622537
Tank ID: FL8622537-32
Tank Status: Closed
Installation Date: 1971/06/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Waste Oil
Tank Wall Type: Not reported

UST FINDER RELEASE:

Object ID: 111064
Facility ID: FL8622537
Lust ID: FL29347
Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE CENTER DR
City,State,Zip: ORLANDO, FL 0
Address Match Type: Not reported
Reported Date: 1988/10/10 16:00:00+00
Status: Open
Substance: Not reported
Population within 1500ft: 0
Domestic Wells within 1500ft: 0
Land Use: Developed, High Intensity
Within SPA: No
SPA PWS Facility ID: Not reported
SPA Water Type: Not reported
SPA Facility Type: Not reported
SPA HUC12: Not reported
Within WHPA: No
WHPA PWS Facility ID: Not reported
WHPA Water Type: Not reported
WHPA Facility Type: Not reported
WHPA HUC12: Not reported
Within 100yr Floodplain: No
Tribe: Not reported
EPA Region: 4
NFA Letter 1: Not reported
NFA Letter 2: Not reported
NFA Letter 3: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

1028229512

NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-81.57528
Y Coord:	28.39306
Latitude:	28.3930599999999
Longitude:	-81.57528
Object ID:	111065
Facility ID:	FL8622537
Lust ID:	FL12628
Name:	WALT DISNEY WORLD CAR CARE CTR
Address:	1000 CAR CARE CENTER DR
City,State,Zip:	ORLANDO, FL 0
Address Match Type:	Not reported
Reported Date:	1994/12/02 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	0
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	4
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-81.57528
Y Coord:	28.39306
Latitude:	28.3930599999999
Longitude:	-81.57528
Object ID:	111066
Facility ID:	FL8622537
Lust ID:	FL11062
Name:	WALT DISNEY WORLD CAR CARE CTR
Address:	1000 CAR CARE CENTER DR
City,State,Zip:	ORLANDO, FL 0
Address Match Type:	Not reported
Reported Date:	1996/04/09 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	0
Domestic Wells within 1500ft:	0

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

WALT DISNEY WORLD CAR CARE CTR (Continued)

1028229512

Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	4
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-81.57528
Y Coord:	28.39306
Latitude:	28.3930599999999
Longitude:	-81.57528
Object ID:	111067
Facility ID:	FL8622537
Lust ID:	FL9580
Name:	WALT DISNEY WORLD CAR CARE CTR
Address:	1000 CAR CARE CENTER DR
City,State,Zip:	ORLANDO, FL 0
Address Match Type:	Not reported
Reported Date:	1997/10/27 15:59:59+00
Status:	Open
Substance:	Not reported
Population within 1500ft:	0
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	4
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

1028229512

X Coord: -81.57528
Y Coord: 28.39306
Latitude: 28.3930599999999
Longitude: -81.57528

B7
NNW
1/2-1
0.503 mi.
2655 ft.

SPEEDWAY #6899
1000 CAR CARE DR
LAKE BUENA VISTA, FL 32830
Site 4 of 8 in cluster B

UST FINDER
UST FINDER RELEASE

1028251115
N/A

UST FINDER:
Object ID: 78692
Facility ID: FL9401665
Name: SPEEDWAY #6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830
Address Match Type: Not reported
Open USTs: 3
Closed USTs: 5
TOS USTs: 0
Population 1500ft: 0
Private Wells 1500ft: 0
Within 100yr Floodplain: No
Land Use: Developed, High Intensity
Within SPA: No
SPA PWS Facility ID: Not reported
SPA Water Type: Not reported
SPA Facility Type: Not reported
SPA HUC12: Not reported
Within WHPA: No
WHPA PWS Facility ID: Not reported
WHPA Water Type: Not reported
WHPA Facility Type: Not reported
WHPA HUC12: Not reported
Facility Status: Open UST(s)
Date of Last Inspection: Not reported
EPA Region: 4
Tribe: Not reported
Coordinate Source: State
X Coord: -81.57527778
Y Coord: 28.3930555600001
Latitude: 28.39305556
Longitude: -81.57527778

UST FINDER:
Object ID: 198609
Facility ID: FL9401665
Tank ID: FL9401665-6
Tank Status: Open
Installation Date: 2006/09/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 20000
Substances: Unleaded Gas
Tank Wall Type: Not reported

Object ID: 198610
Facility ID: FL9401665

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

1028251115

Tank ID: FL9401665-7
Tank Status: Open
Installation Date: 2006/09/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 20000
Substances: Unleaded Gas
Tank Wall Type: Not reported

Object ID: 198611
Facility ID: FL9401665
Tank ID: FL9401665-8
Tank Status: Open
Installation Date: 2006/09/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 20000
Substances: Vehicular Diesel
Tank Wall Type: Not reported

Object ID: 208572
Facility ID: FL9401665
Tank ID: FL9401665-1
Tank Status: Closed
Installation Date: 1994/09/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 10000
Substances: Unleaded Gas
Tank Wall Type: Not reported

Object ID: 208573
Facility ID: FL9401665
Tank ID: FL9401665-2
Tank Status: Closed
Installation Date: 1994/09/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 8000
Substances: Unleaded Gas
Tank Wall Type: Not reported

Object ID: 208574
Facility ID: FL9401665
Tank ID: FL9401665-3
Tank Status: Closed
Installation Date: 1994/09/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 8000
Substances: Unleaded Gas
Tank Wall Type: Not reported

Object ID: 208575
Facility ID: FL9401665
Tank ID: FL9401665-4
Tank Status: Closed
Installation Date: 1994/09/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 8000
Substances: Unleaded Gas
Tank Wall Type: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

SPEEDWAY #6899 (Continued)

EDR ID Number
EPA ID Number

Database(s)

1028251115

Object ID: 208576
Facility ID: FL9401665
Tank ID: FL9401665-5
Tank Status: Closed
Installation Date: 1994/09/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 8000
Substances: Vehicular Diesel
Tank Wall Type: Not reported

UST FINDER RELEASE:

Object ID: 111068
Facility ID: FL9401665
Lust ID: FL571
Name: SPEEDWAY #6899
Address: 1000 CAR CARE DR
City,State,Zip: LAKE BUENA VISTA, FL 0
Address Match Type: Not reported
Reported Date: 2015/04/25 15:59:59+00
Status: No Further Action
Substance: Not reported
Population within 1500ft: 0
Domestic Wells within 1500ft: 0
Land Use: Developed, High Intensity
Within SPA: No
SPA PWS Facility ID: Not reported
SPA Water Type: Not reported
SPA Facility Type: Not reported
SPA HUC12: Not reported
Within WHPA: No
WHPA PWS Facility ID: Not reported
WHPA Water Type: Not reported
WHPA Facility Type: Not reported
WHPA HUC12: Not reported
Within 100yr Floodplain: No
Tribe: Not reported
EPA Region: 4
NFA Letter 1: Not reported
NFA Letter 2: Not reported
NFA Letter 3: Not reported
NFA Letter 4: Not reported
Closed With Residual Contaminate: Not reported
Coordinate Source: State
X Coord: -81.57528
Y Coord: 28.39306
Latitude: 28.3930599999999
Longitude: -81.57528

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

	Site	Database(s)	EDR ID Number EPA ID Number
B8 NNW 1/2-1 0.503 mi. 2655 ft.	SPEEDWAY 1000 CAR CARE DR W ORLANDO, FL 32830 Site 5 of 8 in cluster B HAZ WASTE: Facility ID: 75654 Name: SPEEDWAY Address: 1000 CAR CARE DR W City,State,Zip: ORLANDO, FL 32830 County: ORANGE Telephone: (0)- Email: na Status: I - INACTIVE - DOES NOT GENERATE WASTE Generator Status: N - NOT A HAZARDOUS WASTE GENERATOR EPA ID: FLR000005827 Other ID: DIST 1 Old Facility ID: 4825425 SIC: 5541 - RETAIL TRADE - GASOLINE SERVICE STATIONS Verified: X - ESQG VERIFICATION Verified Date: 02/25/2022 Hazardous Waste LBS/YEAR: 0 Wastes: 0	HAZ WASTE	S130176951 N/A
B9 NNW 1/2-1 0.503 mi. 2655 ft.	WALT DISNEY WORLD CAR CARE CTR 1000 CAR CARE DR BAY LAKE, FL 32830 Site 6 of 8 in cluster B DWM CONTAM: Name: WALT DISNEY WORLD CAR CARE CTR Address: 1000 CAR CARE DR City,State,Zip: BAY LAKE, FL 32830 Program Site Id: 8622537 Lat DD: 28 Lat MM: 23 Lat SS: 35 Long DD: 81 Long MM: 34 Long SS: 31 Office/ District: CD Program Area: PETROLEUM Priority Score: Not reported Datum: 0 Method: AGPS Facility Status: CLOSED-STCM Facility Type: C - Fuel user/Non-retail Score Effective Date: 2009-05-20 00:00:00 Score When Ranked: 31 Rank: 4637 Operator: Not reported Phone: Not reported Name Changed: Not reported Addr Changed: Not reported Related Party ID: 23375 Primary RP Role: ACCOUNT OWNER RP Begin Date: 2/5/1986 RP Name: WALT DISNEY WORLD PARKS & RESORTS US	DWM CONTAM	S125959239 N/A

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

S125959239

RP Address1: PO BOX 10000
RP Address2: ATTN: MGR-ENVIRON CONTROL DEPT
RP City: ORLANDO
RP State: FL
RP Zip5: 1000
RP Zip4: 32830
Contact: JOSE GARRIDO | CLARK QUACKENBUSH 407-701-7561
RP Phone: (407)390-5242
RP Extension: Not reported
Site Manager: Not reported

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Program Site Id: 8622537
Lat DD: 28
Lat MM: 23
Lat SS: 35
Long DD: 81
Long MM: 34
Long SS: 31
Office/ District: CD
Program Area: PETROLEUM
Priority Score: Not reported
Datum: 0
Method: AGPS
Facility Status: OPEN-STCM
Facility Type: C - Fuel user/Non-retail
Score Effective Date: 2009-05-20 00:00:00
Score When Ranked: 31
Rank: 4637
Operator: Not reported
Phone: Not reported
Name Changed: Not reported
Addr Changed: Not reported
Related Party ID: 23375
Primary RP Role: ACCOUNT OWNER
RP Begin Date: 2/5/1986
RP Name: WALT DISNEY WORLD PARKS & RESORTS US
RP Address1: PO BOX 10000
RP Address2: ATTN: MGR-ENVIRON CONTROL DEPT
RP City: ORLANDO
RP State: FL
RP Zip5: 1000
RP Zip4: 32830
Contact: JOSE GARRIDO | CLARK QUACKENBUSH 407-701-7561
RP Phone: (407)390-5242
RP Extension: Not reported
Site Manager: TAYLOR_DT

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Program Site Id: 8622537
Lat DD: 28
Lat MM: 23
Lat SS: 35

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

S125959239

Long DD: 81
Long MM: 34
Long SS: 31
Office/ District: CD
Program Area: PETROLEUM
Priority Score: Not reported
Datum: 0
Method: AGPS
Facility Status: OPEN-STCM
Facility Type: C - Fuel user/Non-retail
Score Effective Date: 2009-05-20 00:00:00
Score When Ranked: 31
Rank: 4637
Operator: Not reported
Phone: Not reported
Name Changed: Not reported
Addr Changed: Not reported
Related Party ID: 23375
Primary RP Role: ACCOUNT OWNER
RP Begin Date: 2/5/1986
RP Name: WALT DISNEY WORLD PARKS & RESORTS US
RP Address1: PO BOX 10000
RP Address2: ATTN: MGR-ENVIRON CONTROL DEPT
RP City: ORLANDO
RP State: FL
RP Zip5: 1000
RP Zip4: 32830
Contact: JOSE GARRIDO | CLARK QUACKENBUSH 407-701-7561
RP Phone: (407)390-5242
RP Extension: Not reported
Site Manager: TAYLOR_DT

Name: WALT DISNEY WORLD CAR CARE CTR
Address: 1000 CAR CARE DR
City,State,Zip: BAY LAKE, FL 32830
Program Site Id: 8622537
Lat DD: 28
Lat MM: 23
Lat SS: 35
Long DD: 81
Long MM: 34
Long SS: 31
Office/ District: CD
Program Area: PETROLEUM
Priority Score: Not reported
Datum: 0
Method: AGPS
Facility Status: CLOSED-STCM
Facility Type: C - Fuel user/Non-retail
Score Effective Date: 2009-05-20 00:00:00
Score When Ranked: 31
Rank: 4637
Operator: Not reported
Phone: Not reported
Name Changed: Not reported
Addr Changed: Not reported
Related Party ID: 23375

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD CAR CARE CTR (Continued)

EDR ID Number
EPA ID Number

Database(s)

S125959239

Primary RP Role: ACCOUNT OWNER
RP Begin Date: 2/5/1986
RP Name: WALT DISNEY WORLD PARKS & RESORTS US
RP Address1: PO BOX 10000
RP Address2: ATTN: MGR-ENVIRON CONTROL DEPT
RP City: ORLANDO
RP State: FL
RP Zip5: 1000
RP Zip4: 32830
Contact: JOSE GARRIDO | CLARK QUACKENBUSH 407-701-7561
RP Phone: (407)390-5242
RP Extension: Not reported
Site Manager: Not reported

B10 EXXON RAS #40194
NNW 1000 W CARCARE DR
1/2-1 LAKE BUENA VISTA, FL 32830
0.503 mi.
2655 ft.

RCRA-VSQG 1001023633
FINDS FLR000005827
ECHO

Site 7 of 8 in cluster B

RCRA Listings:

Date Form Received by Agency: 20000323
Handler Name: Exxon Ras #40194
Handler Address: 1000 W Carcare Dr
Handler City,State,Zip: LAKE BUENA VISTA, FL 32830-0000
EPA ID: FLR000005827
Contact Name: CAROLYN JONES
Contact Address: PO BOX 4552
Contact City,State,Zip: HOUSTON, TX 77210-4552
Contact Telephone: 713-656-9075
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: WASTE ADMIN
EPA Region: 04
Land Type: Not reported
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: FI
State District: CD
Mailing Address: PO BOX 4552
Mailing City,State,Zip: HOUSTON, TX 77210-4552
Owner Name: Alda Pool
Owner Type: Private
Operator Name: Not reported
Operator Type: Not reported
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No
Small Quantity On-Site Burner Exemption: No
Smelting Melting and Refining Furnace Exemption: No
Underground Injection Control: No
Off-Site Waste Receipt: No

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

EXXON RAS #40194 (Continued)

EDR ID Number
EPA ID Number

1001023633

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170117
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	EXXONMOBIL OIL CORP
Legal Status:	Private
Date Became Current:	20010517
Date Ended Current:	Not reported
Owner/Operator Address:	3225 GALLOWES RD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	EXXONMOBIL OIL CORP
Legal Status:	Private
Date Became Current:	20010517

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

EXXON RAS #40194 (Continued)

EDR ID Number
EPA ID Number

Database(s)

1001023633

Date Ended Current: Not reported
Owner/Operator Address: 3225 GALLOWS RD
Owner/Operator City,State,Zip: FAIRFAX, VA 22037
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ALDA POOL
Legal Status: Private
Date Became Current: 20000323
Date Ended Current: 20010517
Owner/Operator Address: PO BOX 2180
Owner/Operator City,State,Zip: HOUSTON, TX 77252-2180
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20000323
Handler Name: EXXON RAS #40194
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator)

State District Owner: FI
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

Evaluations: No Evaluations Found

FINDS:

Registry ID: 110005629775

[Click Here for FRS Facility Detail Report:](#)

Environmental Interest/Information System:

The Florida Integrated Environmental System Today (FIESTA) Data Maintenance (FDM) System maintains entity, environmental interest, and affiliation data.
The Resource Conservation and Recovery Act Information System

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

EXXON RAS #40194 (Continued)

EDR ID Number
EPA ID Number

1001023633

(RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

The FINDS: database may contain additional details for this site.
Please contact your EDR Account Executive for more information

ECHO:

Envid: 1001023633
Registry ID: 110005629775

[DFR URL:](#)

Name: EXXON RAS #40194
Address: 1000 W CARCARE DR
City,State,Zip: LAKE BUENA VISTA, FL 32830

B11 HESS EXPRESS 2573000
NNW 1000 CAR CARE LN
1/2-1 LAKE BUENA VISTA, FL 32830
0.503 mi.
2655 ft.

EDR Hist Auto 1020268714
N/A

Site 8 of 8 in cluster B

EDR Hist Auto

Year:	Name:	Type:
2006	HESS CORPORATION	Gasoline Service Stations
2007	HESS CORPORATION	Gasoline Service Stations
2008	HESS CORPORATION	Gasoline Service Stations
2012	HESS EXPRESS 2573000	Gasoline Service Stations
2013	HESS EXPRESS 2573000	Gasoline Service Stations
2014	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2014	HESS EXPRESS 2573000	Gasoline Service Stations
2014	HESS CORPORATION	Gasoline Service Stations

C12 WALT DISNEY WORLD SPEEDWAY
North 3450 N WORLD DR
1/2-1 BAY LAKE, FL 32830
0.675 mi.
3563 ft.

AST A100098727
N/A

Site 1 of 2 in cluster C

AST:

Facility ID: 9700221
Name: WALT DISNEY WORLD SPEEDWAY
Address: 3450 N WORLD DR
City,State,Zip: BAY LAKE, FL 32830
Facility Phone: 4079390130
Facility Status: CLOSED
Facility Type: C
Type Description: Fuel user/Non-retail
Depco: P
Region: STATE
Positioning Method: AGPS
Latitude/Longitude: 28 23 81 / 81 34 80

Tank:

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

WALT DISNEY WORLD SPEEDWAY (Continued)

EDR ID Number
EPA ID Number

Database(s)

A100098727

Tank ID: 1
Tank Capacity: 10000
Tank Location: ABOVEGROUND
Tank Status: B-Removed from Site
Status Date: 08/25/2015
Install Date: 2/1/1997
Substance: A
Content Description: Leaded Gas
Vessel Indicator: TANK
DEP Contractor: P

Owner:
Owner ID: 71452
Owner Name: WALT DISNEY WORLD
Owner Address: 3450 N WORLD DR
Owner Address 2: ATTN: STORAGE TANK REGIS
Owner City,State,Zip: BAY LAKE, FL 32830
Owner Contact: Not reported
Owner Phone: Not reported

C13
North
1/2-1
0.675 mi.
3563 ft.

RICHARD PETTY DRIVING EXPERIENCE
3450 N WORLD DRIVE
ORLANDO, FL 32830

Site 2 of 2 in cluster C

RCRA NonGen / NLR
FINDS
ECHO

1005441877
FLR000072587

RCRA Listings:
Date Form Received by Agency: 20170919
Handler Name: Richard Petty Driving Experience
Handler Address: 3450 N World Dr
Handler City,State,Zip: ORLANDO, FL 32830-0000
EPA ID: FLR000072587
Contact Name: TOREN PETERSON
Contact Address: PO BOX 10043
Contact City,State,Zip: LAKE BUENA VISTA, FL 32830-0043
Contact Telephone: 407-939-0130
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: VP
EPA Region: 04
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: FI
State District: CD
Mailing Address: PO BOX 10043
Mailing City,State,Zip: LAKE BUENA VISTA, FL 32830-0043
Owner Name: Richar Petty Driving Experience
Owner Type: Private
Operator Name: Not reported
Operator Type: Not reported
Short-Term Generator Activity: No
Importer Activity: No

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

RICHARD PETTY DRIVING EXPERIENCE (Continued)

EDR ID Number
EPA ID Number

1005441877

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180223
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RICHAR PETTY DRIVING EXPERIENCE
Legal Status:	Private
Date Became Current:	20020620
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 10043
Owner/Operator City,State,Zip:	LAKE BUENA VISTA, FL 32830
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

RICHARD PETTY DRIVING EXPERIENCE (Continued)

1005441877

Owner/Operator Indicator: Owner
Owner/Operator Name: RICHAR PETTY DRIVING EXPERIENCE
Legal Status: Private
Date Became Current: 20020620
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 10043
Owner/Operator City,State,Zip: LAKE BUENA VISTA, FL 32830-4300
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: RICHAR PETTY DRIVING EXPERIENCE
Legal Status: Private
Date Became Current: 20020620
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 10043
Owner/Operator City,State,Zip: LAKE BUENA VISTA, FL 32830
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20010904
Handler Name: RICHARD PETTY DRIVING EXPERIENCE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: FI
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20170919
Handler Name: RICHARD PETTY DRIVING EXPERIENCE
Federal Waste Generator Description: Not a generator, verified
State District Owner: FI
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010206
Handler Name: RICHARD PETTY DRIVING EXPERIENCE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: FI
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

RICHARD PETTY DRIVING EXPERIENCE (Continued)

1005441877

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found
--------------	----------------------

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20010904
Actual Return to Compliance Date:	20011217
Return to Compliance Qualifier:	Unverifiable
Violation Responsible Agency:	State

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

PRELIMINARY MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

RICHARD PETTY DRIVING EXPERIENCE (Continued)

1005441877

Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20011101
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	JEW
Evaluation Responsible Sub-Organization:	CD
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20010904
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	JEW
Evaluation Responsible Sub-Organization:	CD
Actual Return to Compliance Date:	20011217
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

PRELIMINARY MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RICHARD PETTY DRIVING EXPERIENCE (Continued)

1005441877

FINDS:

Registry ID: 110012585871

[Click Here for FRS Facility Detail Report:](#)

Environmental Interest/Information System:

The Florida Integrated Environmental System Today (FIESTA) Data Maintenance (FDM) System maintains entity, environmental interest, and affiliation data.

The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

The FINDS: database may contain additional details for this site.
Please contact your EDR Account Executive for more information

ECHO:

Envid: 1005441877
Registry ID: 110012585871

[DFR URL:](#)

Name: RICHARD PETTY DRIVING EXPERIENCE
Address: 3450 N WORLD DRIVE
City,State,Zip: ORLANDO, FL 32830

Count: 0 records

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
NO SITES FOUND					