



2026 SINGAPORE GRAND PRIX

09 - 11 October 2026

From	The FIA Formula 1 Technical Delegate	Document	68
To	The Stewards	Date	11 October 2026
		Time	00:17

Technical Delegate's Report

Before the Qualifying practice session:

It was confirmed for all cars that the gear ratios used during the remainder of this Competition belong to the gear ratios declared to the FIA technical delegate at or before the first Competition of the 2026 Championship.

During the Qualifying practice session:

Car numbers 12, 03, 06, 55, 30, 18, 14, 87, 43 and 11 were weighed.

The weight distribution was checked on car numbers 12, 03, 06, 55, 30, 18, 14, 87, 43 and 11.

The following aerodynamic component or bodywork areas were checked on car number 55:

- | | |
|----------------------------|-------------------|
| - Floor Body | - Article C3.5.1 |
| - Floor Foot | - Article C3.5.2 |
| - Floor Sidewall | - Article C3.5.3 |
| - Floor Board | - Article C3.5.5 |
| - Floor Bib | - Article C3.5.6 |
| - Floor Corner | - Article C3.5.10 |
| - Nose | - Article C3.7.1 |
| - Forward Chassis | - Article C3.7.2 |
| - Mid Chassis | - Article C3.7.3 |
| - Roll Hoop | - Article C3.7.4 |
| - Mirror | - Article C3.7.5 |
| - Sidepod | - Article C3.8.1 |
| - Engine Cover | - Article C3.8.2 |
| - Tail | - Article C3.9.1 |
| - Front Wing Profiles | - Article C3.10.1 |
| - Front Wing Endplate body | - Article C3.10.2 |

- Front Wing Outboard Footplate - Article C3.10.3
- Front Wing Inboard Footplate - Article C3.10.4
- Front Wing Endplate Diveplane - Article C3.10.5
- Rear Wing Profiles - Article C3.11.1
- Rear Wing Endplate Body - Article C3.11.2
- Rear Wing Aux. Components - Article C3.11.7

The tyre starting pressures of all cars during the qualifying sessions were checked.

After the Qualifying practice session:

Car numbers 81, 01, 63, 12, 03, 16, 44, 41, 30 and 10 were weighed.

The following aerodynamic component or bodywork areas were checked on car numbers 01, 16 and 41:

- Floor Body - Article C3.5.1
- Floor Foot - Article C3.5.2
- Floor Sidewall - Article C3.5.3
- Floor Board - Article C3.5.5
- Floor Bib - Article C3.5.6
- Floor Corner - Article C3.5.10
- Nose - Article C3.7.1
- Forward Chassis - Article C3.7.2
- Mid Chassis - Article C3.7.3
- Roll Hoop - Article C3.7.4
- Mirror - Article C3.7.5
- Sidepod - Article C3.8.1
- Engine Cover - Article C3.8.2
- Tail - Article C3.9.1
- Front Wing Profiles - Article C3.10.1
- Front Wing Endplate body - Article C3.10.2
- Front Wing Outboard Footplate - Article C3.10.3
- Front Wing Inboard Footplate - Article C3.10.4
- Front Wing Endplate Diveplane - Article C3.10.5
- Rear Wing Profiles - Article C3.11.1
- Rear Wing Endplate Body - Article C3.11.2
- Rear Wing Aux. Components - Article C3.11.7

The fuel pressure of all cars during the qualifying session was checked.

The logged pressure within the engine cooling system during the qualifying session was checked on all cars .

The engine high rev limit bands were checked on all cars.

Fuel flow meter calibration checksums were checked on all cars.

The instantaneous fuel energy flow of all cars was checked.

The partial load fuel energy flow of all cars was checked.

The fuel temperature of all cars was checked.

The plenum temperature was checked on all cars.

The engine intake air pressure of all cars was checked.

The maximum turbocharger speed was checked on all cars.

The PU and MGU-K power reduction rates were checked on all cars.

The DC sensor temperatures were checked on all cars.

The on-track ES state of charge was checked on all cars.

The ERS recharge limits were checked on all cars.

The maximum MGU-K power limits were checked on all cars.

The maximum MGU-K speed was checked on all cars.

The torque coordinator demands were checked on all cars.

The torque control was checked on all cars.

Torque sensor software version checks have been carried out on all cars.

Torque sensor calibration checks have been carried out on all cars.

The session type has been confirmed for all cars.

Chassis FIA checksum was checked on all cars taking part in the qualifying sessions.

The rear brakes pressure control was checked on car numbers 01, 23, 27 and 77.

The steering wheel of all cars has been checked.

Custom software version checks have been carried out on all cars.

SECU software version checks have been carried out on all cars.

The TPMS coverage was checked on car numbers and .

The maximum front wing adjuster system transition time was checked on all cars.

The maximum rear wing adjuster system transition time was checked on all cars.

The tyres used by all drivers during the sessions today have been checked.

The tyres cold pressure was checked on car numbers 12 and 10.

The following SECU software versions have been used by the teams during the qualifying sessions:

Team	FIA Standard ECU system version
McLaren Mastercard F1 Team	SR1838
Mercedes-AMG PETRONAS Formula One Team	SR1838
Oracle Red Bull Racing	SR1838
Scuderia Ferrari HP	SR1838
Atlassian Williams Racing	SR1838
VISA Cash App Racing Bulls Formula One Team	SR1838
Aston Martin Aramco Formula One Team	SR1838
TGR Haas F1 Team	SR1838
Audi Revolut F1 Team	SR1838
BWT Alpine Formula One Team	SR1838
Cadillac Formula 1 Team	SR1838

All the above items were found to be in compliance with the 2026 FIA Formula One Technical Regulations.

Jo Bauer

The FIA Formula 1 Technical Delegate