

Drone Inspection Report

Mission Summary

Report Generated	2026-07-19 16:14:05
Mission Duration	9.2 minutes
Total Waypoints	14
Total Detections	75
car	48
truck	27

Vehicle Telemetry (at report time)

Parameter	Value
Position	47.397971°, 8.546164°
Altitude	0.1 m
Heading	118.5°
Ground Speed	0.0 m/s
Battery	100% (16.2V)
Flight Mode	HOLD
Armed	No
GPS	10 satellites (3D Fix)
SITL Connected	Yes

Detection Log

#	Class	Conf	Latitude	Longitude	Alt (m)
DET-001	car	0.92	47.398008	8.546184	13.2
DET-002	car	0.92	47.397797	8.545939	19.3
DET-003	car	0.92	47.397649	8.545633	19.7
DET-004	car	0.92	47.397499	8.545314	19.8
DET-005	car	0.92	47.397352	8.545001	19.7
DET-006	car	0.92	47.397200	8.544677	19.8
DET-007	car	0.92	47.397055	8.544370	19.8
DET-008	truck	0.92	47.397092	8.544182	19.7
DET-009	truck	0.92	47.397172	8.544248	19.7

DET-010	car	0.92	47.397383	8.544183	19.7
DET-011	car	0.92	47.397640	8.544185	19.7
DET-012	car	0.92	47.397896	8.544188	19.7
DET-013	car	0.92	47.398152	8.544190	19.7
DET-014	car	0.92	47.398393	8.544190	19.7
DET-015	truck	0.92	47.398445	8.544344	19.7
DET-016	truck	0.92	47.398375	8.544431	19.7
DET-017	car	0.92	47.398472	8.544667	19.8
DET-018	truck	0.92	47.398366	8.544708	19.7
DET-019	truck	0.92	47.398308	8.544604	19.8
DET-020	car	0.92	47.398088	8.544745	19.7
DET-021	car	0.92	47.397835	8.544747	19.7
DET-022	car	0.92	47.397581	8.544748	19.7
DET-023	car	0.92	47.397332	8.544747	19.7
DET-024	car	0.92	47.397088	8.544745	19.7
DET-025	truck	0.92	47.397034	8.544591	19.7
DET-026	truck	0.92	47.397013	8.544821	19.7
DET-027	car	0.92	47.397121	8.545070	19.7
DET-028	truck	0.92	47.397018	8.545106	19.7
DET-029	truck	0.92	47.397201	8.545134	19.6
DET-030	truck	0.92	47.397451	8.545136	19.7
DET-031	car	0.92	47.397692	8.544984	19.8
DET-032	car	0.92	47.397950	8.544986	19.8
DET-033	car	0.92	47.398190	8.544987	19.7
DET-034	car	0.92	47.398409	8.544987	19.7
DET-035	truck	0.92	47.398445	8.545142	19.7
DET-036	truck	0.92	47.398375	8.545230	19.7
DET-037	car	0.92	47.398472	8.545463	19.7
DET-038	truck	0.92	47.398366	8.545509	19.8
DET-039	truck	0.92	47.398307	8.545406	19.8
DET-040	car	0.92	47.398086	8.545543	19.7
DET-041	car	0.92	47.397818	8.545544	19.7
DET-042	car	0.92	47.397564	8.545545	19.7
DET-043	car	0.92	47.397301	8.545545	19.8
DET-044	car	0.92	47.397081	8.545542	19.7
DET-045	truck	0.92	47.397034	8.545388	19.7
DET-046	truck	0.92	47.397013	8.545636	19.7
DET-047	car	0.92	47.397120	8.545870	19.8

DET-048	truck	0.92	47.397016	8.545903	19.8
DET-049	car	0.92	47.397184	8.545776	19.7
DET-050	car	0.92	47.397433	8.545778	19.7
DET-051	car	0.92	47.397692	8.545780	19.7
DET-052	car	0.92	47.397959	8.545781	19.7
DET-053	car	0.92	47.398213	8.545784	19.7
DET-054	car	0.92	47.398421	8.545785	19.7
DET-055	truck	0.92	47.398443	8.545941	19.7
DET-056	truck	0.92	47.398373	8.546026	19.7
DET-057	car	0.92	47.398473	8.546264	19.7
DET-058	truck	0.92	47.398370	8.546305	19.7
DET-059	truck	0.92	47.398308	8.546201	19.7
DET-060	car	0.92	47.398090	8.546334	19.7
DET-061	car	0.92	47.397825	8.546335	19.7
DET-062	car	0.92	47.397560	8.546337	19.7
DET-063	car	0.92	47.397294	8.546338	19.7
DET-064	car	0.92	47.397076	8.546339	19.7
DET-065	truck	0.92	47.397033	8.546190	19.7
DET-066	truck	0.92	47.397017	8.546446	19.7
DET-067	car	0.92	47.397121	8.546667	19.7
DET-068	truck	0.92	47.397015	8.546703	19.7
DET-069	truck	0.92	47.397201	8.546736	19.8
DET-070	car	0.92	47.397449	8.546580	19.7
DET-071	car	0.92	47.397714	8.546579	19.7
DET-072	car	0.92	47.397981	8.546577	19.7
DET-073	car	0.92	47.398235	8.546575	19.7
DET-074	car	0.92	47.398426	8.546574	19.7
DET-075	truck	0.92	47.398443	8.546730	19.7

Report generated by Drone Inspector — Simulation