

Visual Inspection



Serial No.	512033	Work Order	
Device Name	31-90-CPPA-XF-KT14A	Date	08/19/2014
Tag No.	KT14A.30.EN	Manufacture	ABB LIMITED

• Visual Inspection Test Instrument Information

Humidity (%)		Ambient Temp. (Celcius)	
Oil Temp. (Celcius)	40	Oil Temp. Max (Celcius)	60
Winding Temp.HV (Celcius)	40	Winding Temp.HV Max (Celcius)	60
Winding Temp.LV (Celcius)		Winding Temp.LV Max (Celcius)	
Service Tap	6		

• Transformer Load Data Record

Active Power (kVA)		Current (A)	
Reactive Power (kVAr)		Voltage (V)	
Real Power (kW)			

• Porcelain Condition Checking

Visual Inspection Item	Condition	Remark
HV bushing	Normal	
Neutral bushing (HV Side)	Normal	
LV bushing	Normal	
Neutral bushing (LV Side)	Not Available	
Lightning & Surge Arrester	Normal	

• Leakage/Gasket Oil Checking

Visual Inspection Item	Condition	Remark
Maintank	Normal	
Conservator tank	Normal	
Radiator	Normal	
HV bushing	Normal	
Neutral bushing	Normal	
LV bushing	Normal	
Pipe line	Normal	
Inlet/outlet & sampling valve	Normal	
Isolate valve	Normal	
Drain& filtering valve	Normal	
Radiator valve	Normal	
BCT terminal / box	Not Available	
Buchholz relay	Normal	
Pressure relief	Normal	

Responsibility	Tested By	Tested By	Witnessed By
Company	TIS Engineering and Service Co.,Ltd.		
Name	Mr.Anusit Sara		
Signature			
Date	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy

Visual Inspection



Serial No.		Work Order	
Device Name		Date	
Tag No.		Manufacture	

• Oil Level Checking

Visual Inspection Item	Condition	Remark
Oil level for Main tank	Normal	
Oil level for OLTC tank	Normal	

• Oil and Winding Temperature

Visual Inspection Item	Condition	Remark
Oil temperature indicator	Normal	
Oil temperature switch	Normal	
HV Winding temperature indicator	Normal	
HV Winding temperature switch	Normal	
LV Winding temperature indicator	Not Available	
LV Winding temperature switch	Not Available	

• Power Transformer Self-Protection

Visual Inspection Item	Condition	Remark
Buchholz relay	Normal	
Pressure relief device	Normal	
Sudden pressure device	Not Available	
Rapid pressure device	Not Available	
Rubber bag detector	Not Available	
OLTC Oil surge relay	Normal	
OLTC Pressure relief device	Normal	
OLTC Oil Filter pressure	Normal	

• Surface Painting Checking

Visual Inspection Item	Condition	Remark
Surface painting Main Tank	Normal	
Surface painting Radiator fins	Normal	

• Foundation Condition Checking

Visual Inspection Item	Condition	Remark
Foundation condition	Normal	

Responsibility	Tested By	Tested By	Witnessed By
Company			
Name			
Signature			
Date			

Visual Inspection



Serial No.		Work Order	
Device Name		Date	
Tag No.		Manufacture	

• Earthing Connection Checking

Visual Inspection Item	Condition	Remark
Transformer Earthing connection	Normal	
Fence Earthing connection	Normal	
Neutral Ground Resistance (NGR)	Not Available	
NGR Resistance measurement[Ohm]	Not Available	
Ground Resistance measurement[Ohm]	Not Available	

Dehydrating Breather Checking

Visual Inspection Item	Condition	Remark
Main Conservator Tank	Normal	
OLTC. Tank	Normal	
LV Bushing terminals box	Not Available	

• Terminal Box Checking

Visual Inspection Item	Condition	Remark
Physical condition	Not Available	
Terminal and wiring / cable	Not Available	

• All Bolt and Nut Connection Checking

Visual Inspection Item	Condition	Remark
Bolt/nut connection	Normal	

• Cooling System Operation

Visual Inspection Item	Condition	Remark
Cooling fans	Normal	
Cooling fans panel	Normal	
Operation test cooling fans	Normal	
Condition of cooling pump	Not Available	
Operation test cooling pump	Not Available	

Responsibility	Tested By	Tested By	Witnessed By
Company			
Name			
Signature			
Date			

Visual Inspection



Serial No.		Work Order	
Device Name		Date	
Tag No.		Manufacture	

• OLTC

Visual Inspection Item	Condition	Remark
Condition of OLTC. Panel	Normal	
Operation counter	Normal	
Inspection for Motor drive unit	Normal	
Proper step-by-step operation	Normal	
Proper operation of hand crank	Normal	
Proper hand crank interlock	Normal	
Indication and counter operation	Normal	
Oil filter unit operation test and record pressure	Normal	
Phase A:	bar	
Phase B:	bar	
Phase C:	bar	

• Local Control Panel Operation

Visual Inspection Item	Condition	Remark
Physical condition	Normal	
Check all alarm annunciator	Normal	
Lamp test	Normal	
Condition space heater	Normal	
Condition of lighting	Normal	

• Visual Inspection Conclusion Result

Visual Inspection Item	Condition	Remark
Transformer Inspection Result	Normal	
Bushing Inspection Result	Normal	
Arrester Inspection Result	Normal	
OLTC Inspection Result	Normal	

• Others

Responsibility	Tested By	Tested By	Witnessed By
Company			
Name			
Signature			
Date			

Visual Inspection



Serial No.		Work Order	
Device Name		Date	
Tag No.		Manufacture	

File 1 : Browser	Change Picture		
	Choose File	No file chosen	

File 2 : Browser	Change Picture		
	Choose File	No file chosen	

Responsibility	Tested By	Tested By	Witnessed By
Company			
Name			
Signature			
Date			

Visual Inspection



Serial No.		Work Order	
Device Name		Date	
Tag No.		Manufacture	

File 3 : Browser	Change Picture		
	Choose File	No file chosen	

File 4 : Browser	Change Picture		
	Choose File	No file chosen	

Responsibility	Tested By	Tested By	Witnessed By
Company			
Name			
Signature			
Date			

Visual Inspection



Serial No.		Work Order	
Device Name		Date	
Tag No.		Manufacture	

File 5 : Browser	Change Picture		
	Choose File	No file chosen	

File 6 : Browser	Change Picture		
	Choose File	No file chosen	

Responsibility	Tested By	Tested By	Witnessed By
Company			
Name			
Signature			
Date			