


PUMP TEST REPORT

Invoice Number:	
Customer:	Madorido
Job Number:	

Fabrication		Hydraulic Test	
Pump Model:	PS 0.75KW	Date of Test:	2025-03-17
Serial Number:	2101 001 - 25	Duration of Test:	1
Impeller Diameter:	1	Test Medium:	1
Assembled By:	tester1	Tested By:	tester1

Details			
Motor Size:	1	Frequency:	1
Motor Speed:	1	Pump Housing:	1
Motor Volts:	1	Pump Connection:	1
Motor Enclosure:	1	Suction:	1
Mechanical Seal:	1	Discharge:	1
		Flush Arrangement:	No
Test Results			
Test 1	17912	2.85	6.19
Test 2	12050	3.05	5.52
Test 3	8078	3.05	5.2
Test 4	4089	3.05	4.87
Test 5	0	3.05	4.74



Approval	
Approved By:	1
Date:	2025-03-17