

Date: 2024-08-20

Typed cover text references the scanned maintenance note below.

The image contains material maintenance values and approval evidence.

SCANNED IMAGE NOTE - MATERIAL CONTENT

Tach 1500.5 - Magneto replaced

Signed: Image-only Mechanic