



Water leak under kitchen sink

Urgent


In Progress

6722 S Ridgeland Ave · Unit 3S

Edit Request

More

Update Status



Overview

Request #	Reported	Category	Responsibility	Target completion	Assigned to
MNT-2026-0047	Jul 30, 2026 · 9:42 AM	Plumbing	Association	Aug 1, 2026	Emma Owusu

Issue description

Water is collecting beneath the kitchen sink when the faucet is used. The cabinet base is damp.

Property & Reporter

TEST – 6722 S Ridgeland
Unit 3S

Mary Jones
Owner

Email
mary.jones@example.com

Phone
(312) 555-0187

Permission to enter
Yes, with prior notice

Pets present
No

Vendor & Cost

TEST – ABC Plumbing
Carlos Diaz

Scheduled
Jul 31 · 1:00–3:00 PM

Estimate
\$425.00

Approval
Not required

Message Vendor

Reassign

Add Note

Send Update

Request Approval

Mark Work Complete

Activity

Messages

Files

- Vendor marked job In Progress
Jul 31, 2026 · 9:25 AM
GHL workflow
CD
- Appointment confirmed
Jul 31, 2026 · 9:24 AM
GHL workflow
CD
- Request assigned to ABC Plumbing
Jul 31, 2026 · 9:20 AM
GHL workflow
EO
- Triage completed by Emma Owusu
Jul 30, 2026 · 10:15 AM
EO
- Request submitted by Mary Jones
Jul 30, 2026 · 9:42 AM
MJ

View all activity