



Product Specifications



P552819

LUBE FILTER, SPIN-ON FULL FLOW

About Donaldson P552819

The P552819 is designed to maintain oil cleanliness and protect engines from wear-causing contaminants. It captures impurities that accumulate during operation, supporting extended oil life and efficient lubrication while delivering cleaner fluids to your engine components. Built with durable components and tested for consistent filtration performance, it provides dependable protection across a wide range of operating conditions.

Attributes

Outer Diameter	93 mm (3.66 inch)
Thread Size	1-12 UN
Length	136 mm (5.35 inch)
Gasket OD	71 mm (2.80 inch)
Gasket ID	61 mm (2.40 inch)
Efficiency 50%	20 micron
Efficiency Test Std	ISO 4572
Anti-Drainback Valve	Yes
Bypass Valve	Yes

Bypass Valve Setting LR	1.3 bar (19 psi)
Bypass Valve Setting HR	1.6 bar (23 psi)
Media Type	Cellulose
Collapse Burst	6.9 bar (100 psi)
Type	Full-Flow
Style	Spin-On

Other Information

UPC Code	742330044247
----------	--------------

The information contained herein is general in nature and may not reflect actual information regarding the part at time of shipment. Parts may originate in more than one country – the actual country of origin and HS Code will be reflected on the Commercial Invoice(s) that accompanies the goods.