

Quality Control Report — Batch 2024-B

Houston TX — Line 3 · Inspection date April 19, 2026

Summary

Batch ID	2024-B
Plant / Line	Houston TX — Line 3
Inspection Date	April 19, 2026
Units Inspected	2,400
Units Passed	2,381
Units Held	19
Pass Rate	99.20%
Hold Status	Partial Hold — pending re-inspection
Inspector	M. Alvarez (INS-7041)

Defect Breakdown

Defect Code	Description	Units Affected	Action
DEF-12	Surface crack (cosmetic)	12	Hold for re-inspection
DEF-07	Dimensional variance > 0.5%	7	Hold for re-inspection

Recommendation

Release 2,381 passing units for shipment. Route 19 held units through secondary inspection Monday AM. Overall defect rate (0.79%) is within our 1.00% internal threshold.