


Uncorrected Pinax
In-water SVP Exact axial
Range Error vs Pixel Noise (all pipelines)



Dome, 5 mm off (no correction)
Range Error vs Pixel Noise (corrected only)

