
Calibration 1996–2009
mean -1.8 m, RMS 18.9 m, 69/88 beyond ±0.5 m/yr
Buxton
Avon
Tri-Village
Buxton Groin
Avon Pier
Avon Shoals
Wimble Shoals
Rodanthe Pier
Residual (m)
observed − model
GIS domain (south → north)
Model too landward: a missing source
Model too seaward: a missing sink
±0.5 m/yr × run length (±6.5 m calibration)