

# Scrap Note Damage Fixture

Date 1/03/2024

S.No.	Part No.	Customer	Fixture Photo	Damage Area Snap	REMARKS
1	FNK28458	Ashok Leyland		 Gap Between Blocks	SCRAP
2	FNK08858	Ashok Leyland		 End Block Broken	SCRAP
4	552343507706	TATA		 Both Side End Block Broken Gap Between Blocks	SCRAP
5	FNK00855	Ashok Leyland		 Vertical Block Broken	SCRAP
6	554543805814	TATA		 Gap Between Blocks Gap Between The Joints	SCRAP









Rohit

Adi

Signature

# Scrap Note Damage Fixture

Date = 7/03/2024

S.No.	Part No.	Customer	Fixture Photo	Damage Area Snap	REMARKS
7	573750115814	TATA		 Cutting Plate Broken	SCRAP
8	253414605897	TATA		 Both End Block Broken	SCRAP
9	FNK00955	Ashok Leyland		 Cutting Plate Broken	SCRAP
10	FXZ00299	Ashok Leyland		 Cutting Plate Broken	SCRAP
Prepared by:-			VERIFIED BY:-	APPROVED BY:-	

New fixture Received.