



# 1GCNCPEH7EZ321203

Generated on: 01/25/2024

---

**Please remember, you are restricted from using this information for:**

**Employment Screening:**

You may not use this information when evaluating a person for employment, reassignment, promotion, or retention

**Hiring of Household Workers:**

Including, but not limited to, nannies and domestic workers

**Tenant Screening**

Including, but not limited to, leasing a residential or commercial space

**Educational Qualification:**

Including, but not limited to, a person's qualifications for an educational program or scholarship

**Credit or Insurance:**

Accessing the risk of existing credit obligations of an individual and/or determining eligibility for issuing credit or insurance

**Business Transactions Initiated by an Individual Customer:**

Reviewing a personal customer account to determine whether the person continues to meet the terms of the account

Using this information in these ways violates both our [Terms & Conditions](#) and the law, and can lead to possible criminal penalties. We take this very seriously, and reserve the right to terminate user accounts and/or report violators to law enforcement as appropriate.

**Disclaimer:** The information contained in any report and on our website is not necessarily 100% accurate, complete or up to date, nor a substitute for your own due diligence. Our data comes from a wide variety of sources, but some municipalities and jurisdictions are slow to report and digitize their data, so we cannot guarantee or warrant full accuracy of ALL search results. BeenVerified's mission is to give people easy and affordable access to public record information, but BeenVerified, Inc. does not provide private investigator services or consumer reports, and is not a consumer reporting agency per the [Fair Credit Reporting Act](#). **You may not use** our site or service or the information provided to make decisions about employment, admission, consumer credit, insurance, tenant screening or any other purpose that would require FCRA compliance. For more information governing permitted and prohibited uses, please review our ["Do's & Don'ts"](#) and our [Terms & Conditions](#).

Copyright © 2024 BeenVerified, Inc. LLC. All Rights Reserved.

## Table of Contents

Table of Contents	2
Overview	3
Possible Photos	3
Vehicle Specs	3
Possible Sale Listings	4
Possible Accidents	5
Salvage Records	5
Possible Theft Records	5
Title Records	5
Title Brands	6
Possible Recalls	7
Possible Market Value Range	15
Ownership Costs	15
Possible Equipment	16
Possible Warranties	29

# 1GCNCPEH7EZ321203

2014 Chevrolet Silverado 1500

## Overview

This report was run on 01/25/2024 22:03:31. To check for updates, please rerun the report or turn on monitoring.		
✓	NO accidents found!	
✓	NO salvage records found!	
✓	NO theft records found!	
!	1 title record found	
✓	No title brands found!	
!	8 recalls found	
No previous lease records on this vehicle found		
32 sale listings found		
Last reported color: Silver Ice Metallic		
Last reported mileage: 98694 in 01/2024		

## Possible Photos

39 | Photos Found

Please log into your BeenVerified, Inc. account to view photos for this report.

## Vehicle Specs

22 | Vehicle Specs Found

#	Name	Value
---	------	-------

1	Year	2014
2	Make	Chevrolet
3	Model	Silverado 1500
4	Type	Regular Cab
5	Trim	Work Truck
6	Fuel Type	E85
7	Gross Weight	6700 lbs
8	Curb Weight	4567 lbs
9	Overall Length	224.4 inches
10	Overall Height	73.5 inches
11	Overall Width	80 inches
12	Doors	2
13	Standard Seating	3
14	Highway Mileage	24 miles/gallon
15	City Mileage	18 miles/gallon
16	Transmission Type	Automatic
17	Transmission Gears	6
18	Driven Wheels	4x2
19	MSRP	\$25,965
20	Delivery Charges	\$1,095
21	Installed Color	Silver Ice Metallic
22	Color Code	GAN

## Possible Sale Listings

**32** | Sale Listings Found

#	Date	Type	Listing Price	Seller Name	Seller Location
1	01/24/2024		\$13,995	Good Motor Company	Grand Rapids, MI
2	01/17/2024		\$14,500	Good Motor Company	Grand Rapids, MI
3	01/10/2024		\$14,500	Good Motor Company	Grand Rapids, MI
4	11/16/2023		\$14,995	Good Motor Company	Grand Rapids, MI
5	11/08/2023		\$15,795	Good Motor Company	Grand Rapids, MI
6	11/07/2023		\$14,995	Good Motor Company	Grand Rapids, MI
7	11/07/2023		\$15,995	Good Motor Company	Grand Rapids, MI
8	11/02/2023		\$16,595	Good Motor Company	Grand Rapids, MI
9	10/26/2023		\$16,595	Good Motor Company	Grand Rapids, MI
10	10/25/2023		\$16,995	Good Motor Company	Grand Rapids, MI
11	10/06/2023		\$16,995	Private Seller	

12	09/25/2023	\$15,595	Private Seller	
13	09/23/2023	\$15,595	Good Motor Company	Grand Rapids, MI
14	09/23/2023	\$15,995	Private Seller	
15	09/20/2023	\$15,995	Good Motor Company	Grand Rapids, MI
16	08/09/2023	\$16,595	Good Motor Company	Grand Rapids, MI
17	07/17/2023	\$16,595	Private Seller	
18	07/15/2023	\$16,995	Private Seller	
19	06/23/2023	N/A	Private Seller	
20	06/22/2023	N/A	Good Motor Company	Grand Rapids, MI
21	02/20/2022	\$19,996	Mayse Automotive Group, Inc.	Aurora, MO
22	12/27/2021	\$19,996	Mayse Automotive Group, Inc.	Aurora, MO
23	12/19/2021	\$19,996	Mayse Automotive Group	Aurora, MO
24	12/18/2021	\$19,996	Mayse Automotive Group	Aurora, MO
25	12/12/2021	\$19,996	Mayse Automotive Group	Aurora, MO
26	12/11/2021	\$19,996	Mayse Automotive Group	Aurora, MO
27	12/11/2021	\$19,996	Mayse Automotive Group	Aurora, MO
28	12/09/2021	\$19,996	Mayse Automotive Group	Aurora, MO
29	12/02/2021	\$19,996	Mayse Automotive Group, Inc.	Aurora, MO
30	01/23/2015	\$26,060	reliable chevrolet	
31	01/15/2015	\$20,996	reliable chevrolet geo	
32	01/06/2015	\$17,996	reliable chevrolet geo	

## Possible Accidents

0 | Accidents Found

## Salvage Records

0 | Salvage Records Found

## Possible Theft Records

0 | Theft Records Found

## Title Records

1 | Title Record Found

Source: NMVTIS

### Title 1

Title Issue Date	State	Status	Mileage (M)	VIN
------------------	-------	--------	-------------	-----

04/26/2022	AR	Current	77737	1GCNCPEH7EZ321203
06/23/2020	MO	Historical		1GCNCPEH7EZ321203
04/17/2015	MO	Historical	14	1GCNCPEH7EZ321203

## How to Request a State Vehicle Record

### Arkansas

Arkansas is under the federal Driver's Privacy Protection Act and will not give out information belonging to someone else. If you need information from when you owned the vehicle you may send in a written request along with a copy of your driver's license to request the information. Your request must contain the following:

- Vehicle specifics such as description of vehicle, VIN, license plate number or name with address for an alpha search.
- Reason for requesting the information.
- Fees are \$1.00 for owner/lien holder information and \$1.00 for each copy of documents requested such as bill of sale, contracts, etc.

By Mail:

Arkansas Office of Motor Vehicles Records Unit, Room 1100

P. O. Box 1272

Little Rock, AR 72203

By Phone: 501.682.4692

By Email: MVInformation@dfa.arkansas.gov

### Missouri

If you are the owner of record on the Missouri title, you may purchase a title and/or registration motor vehicle record by completing request form 5499 Missouri Department of Revenue. Form and fee may be submitted by visiting a Missouri Motor Vehicle licensing office. Office listing and business information may be found at Missouri Department of Revenue.

By Mail:

Missouri Department of Revenue, Motor Vehicle Bureau-Record Center

PO Box 2048

Jefferson City, MO 65105-2048

By E-Mail mvrecords@dor.mo.gov

Vehicle owner will receive documentation containing requested owner, vehicle, lien, and/or registration information; however, this documentation may not be used in place of the Missouri title for transfer of ownership. For information on obtaining a duplicate Missouri title, visit Missouri Department of Revenue Missing Titles/Applying for a Duplicate Title. If you are the not owner of record on the Missouri title, Missouri record information may be requested by submitting the request form and fee for each record. If personal information is requested, the requestor will submit Request for Form 5091 - Request for Motor Vehicle Records with Personal Information. When no personal information is requested, the completion of formForm 4803 - Request for Information (mo.gov) is required. Refer to form for fee assessment.

Public Records Request Review - Prior to release, public record requests are reviewed for permissible uses allowable by federal and state laws. DOL will either provide you with the record information you seek or notification in writing with an explanation that prevents release of the record you seek.

## Title Brands

**0** | Title Brands Found

Source: NMVTIS

### The following are all possible brands applied on this vehicle

- |                |                   |                         |
|----------------|-------------------|-------------------------|
| ✓ Clear        | ✓ Warranty Return | ✓ Manufacturer Buy Back |
| ✓ Flood damage | ✓ Antique         | ✓ Former Rental         |
| ✓ Fire damage  | ✓ Classic         | ✓ Salvage--Stolen       |

✓ Hail damage	✓ Agricultural Vehicle	✓ Salvage--Reasons Other Than Damage or Stolen
✓ Salt water damage	✓ Logging Vehicle	✓ Disclosed Damage
✓ Vandalism	✓ Street Rod	✓ Prior Non-Repairable / Repaired
✓ Kit	✓ Vehicle Contains Reissued VIN	✓ Crushed
✓ Dismantled	✓ Replica	✓ Inoperable Vehicle
✓ Junk	✓ Totaled	✓ Hazardous Substance Contaminated Vehicle
✓ Rebuilt	✓ Owner Retained	✓ Export Only Vehicle
✓ Reconstructed	✓ Reserved	✓ Actual
✓ Salvage--Damage or Not Specified	✓ Memorandum Copy	✓ Not Actual
✓ Test Vehicle	✓ Reserved	✓ Not Actual - Odometer tampering verified
✓ Refurbished	✓ Recovered Theft	✓ Exempt from Odometer Disclosure
✓ Collision	✓ Undisclosed Lien	✓ Exceeds Mechanical Limits
✓ Reserved	✓ Prior Owner Retained	✓ Odometer may be Altered
✓ Salvage Retention	✓ Vehicle Non-conformity Uncorrected	✓ Odometer Replaced
✓ Prior Taxi	✓ Vehicle Non-conformity Corrected	✓ Reading at Time of Renewal
✓ Prior Police	✓ Vehicle Safety Defect Uncorrected	✓ Odometer Discrepancy
✓ Original Taxi	✓ Vehicle Safety Defect Corrected	✓ Call Title Division
✓ Original Police	✓ VIN replaced by a new state assigned VIN	✓ Rectify Previous Exceeds Mechanical Limits Brand
✓ Re-manufactured	✓ Gray Market	✓ Pending Junk Automobile
✓ Reserved	✓ Gray Market	✓ Junk Automobile

## Possible Recalls

**8** | Recalls Found

**Components:** Seat Belt Anchor Pretensioner Cable

**Report  
Receipt Date:** 05/19/2020

**Status:** Open

**NHTSA  
Campaign:** NotAvailable

**Severity  
Code:** Unknown

**Recall Type:** Campaign

**Parts Cost:**

**Labor:**

**Summary:** Certain 2014-2017 model year Chevrolet Silverado and GMC Sierra vehicles, may have a condition where, if a driver repeatedly sits on the seat belt cable cover located at the base of the driver's seat when entering the vehicle, it may cause the seat belt pretensioner to bend sharply over the seat side shield. If this continues to occur over an extended period of time, which is very rare, the seat belt pretensioner cable may fatigue and eventually separate, which could reduce the effectiveness of the vehicle's seat belts. Before any damage occurs to the pretensioner cable itself, signs of wear will be visible on the pretensioner cable cover where it has been repeatedly bent over the seat side shield. This special coverage covers the condition described above for a period of 12 years or 180,000 miles (290,000 km), whichever occurs first, from the date the vehicle was originally placed in service, regardless of ownership.

**Consequence:**

**Remedy:** Dealers are to replace the pretensioner and side shield for all customers that experience a broken pretensioner cable or come to a dealership with excessive wear on the cable sleeve. The repairs will be made at no charge to the customer.

**Notes:**

**State:** Available

**Reason Not  
Available:**

**Refresh Date:** 01/26/2024

**OEM Recall  
Number:** N192289390



---

**Components:** Brake Assist Decreased Due to Vacuum Loss

**Report** 04/10/2019

**Receipt Date:**

**Status:** Open

**NHTSA Campaign:** NotAvailable

**Severity Code:** Unknown

**Recall Type:** Campaign

**Parts Cost:** \$108.06

**Labor:** 3.5 Hours

**Summary:** Some 2014 – 2018 model year GM vehicles may have a condition where customers may experience increased brake pedal effort, hard brake pedal, and/or potentially increased stopping distance. The condition is more prevalent at low speed when softly applying the brakes. The engine mounted mechanical vacuum pump output may decrease over time decreasing the amount of vacuum/power brake assist. Failure to follow recommended oil change intervals could contribute to this condition. The Driver's Information Center, (DIC) "Service brake assist" alert will activate 2-5 minutes after the vacuum level drops, and a Diagnostic Trouble Code, (DTC) will also be set. Even where this condition occurs, the hydraulic brake system remains functional but may require additional pedal force. This special coverage covers the condition described above for a period of 10 years or 150,000 miles (240,000 km), whichever occurs first, from the date the vehicle was originally placed in service, regardless of ownership.

**Consequence:**

**Remedy:** Dealers are to replace the vacuum pump and vacuum pump belt. The repairs will be made at no charge to the customer.

**Notes:**

**State:** Available

**Reason Not Available:**

**Refresh Date:** 01/26/2024

**OEM Recall Number:** N182202780

<b>Components:</b>	Frontal Airbag and Pretensioner Non Deploy
<b>Report Receipt Date:</b>	09/08/2016
<b>Status:</b>	Closed
<b>NHTSA Campaign:</b>	16V651
<b>Severity Code:</b>	Critical
<b>Recall Type:</b>	Safety
<b>Parts Cost:</b>	\$287.86
<b>Labor:</b>	1.2 Hours
<b>Summary:</b>	General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2014-2017 model year Chevrolet Silverado LD, GMC Sierra LD, Buick Encore, Chevrolet Trax, Chevrolet Caprice Police, and Chevrolet Corvette vehicles, 2014-2016 model year Buick Lacrosse, Chevrolet Spark EV, and Chevrolet SS vehicles and 2015-2017 model year Chevrolet Silverado HD, GMC Sierra HD, GMC Yukon, GMC Yukon XL, Cadillac Escalade Cadillac Escalade ESV, Chevrolet Suburban, and Chevrolet Tahoe vehicles. The sensing and diagnostic module (SDM) in these vehicles, which controls airbag and pretensioner deployment, contains a software defect which may prevent the deployment of frontal airbags and pretensioners in certain rare circumstances. If the frontal airbags and seatbelt pretensioners do not deploy when required, there is an increased risk of injury to occupants in a crash.
<b>Consequence:</b>	If the frontal airbags and seatbelt pretensioners do not deploy when required, there is an increased risk of injury to occupants in a crash.
<b>Remedy:</b>	Reprogram the SDM with new software that eliminates this defect. In vehicles with any previous deployment events recorded in the SDM, dealers will replace the existing SDM with a new SDM prior to programming and setup. Note: Before replacing the SDM, any airbag related Diagnostic Trouble Codes should be identified, diagnosed, and corrected prior to SDM replacement. Faulty SIR components in need of replacement are unrelated to this safety recall and are not covered under the terms of this safety recall.
<b>Notes:</b>	
<b>State:</b>	Available
<b>Reason Not Available:</b>	
<b>Refresh Date:</b>	01/26/2024
<b>OEM Recall Number:</b>	2016007

---

**Components:** SEATBELT LAP ANCHOR TENSIONER CABLE

**Report  
Receipt Date:** 04/11/2016

**Status:** Closed

**NHTSA  
Campaign:** 16V209

**Severity  
Code:** Critical

**Recall Type:** Safety

**Parts Cost:**

**Labor:**

**Summary:** General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2014–2015 model year Chevrolet Silverado 1500 and GMC Sierra 1500 vehicles. The flexible steel cable that connects the driver's seat belt to the outboard side of the seat (the "tensioner cable") can fatigue and separate over time as a result of occupant movement into the driver's seat.

**Consequence:** In a crash, a fatigued tensioner cable could break, reducing the effectiveness of the vehicle's seat belts increasing the risk of injury to the driver.

**Remedy:** For used and customer vehicles, dealers will enlarge the side shield opening, install a pusher bracket on the tensioner, and if necessary, replace the tensioner assembly free of charge.

**Notes:**

**State:** Available

**Reason Not  
Available:**

**Refresh Date:** 01/26/2024

**OEM Recall  
Number:** N150822

<b>Components:</b>	Loss of Steering Assist
<b>Report Receipt Date:</b>	08/07/2017
<b>Status:</b>	Closed
<b>NHTSA Campaign:</b>	17V414
<b>Severity Code:</b>	Critical
<b>Recall Type:</b>	Safety
<b>Parts Cost:</b>	
<b>Labor:</b>	
<b>Summary:</b>	General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2014 model year Chevrolet Silverado LD and GMC Sierra LD vehicles. These vehicles may experience a temporary loss of electric power steering (EPS) assist followed by a sudden return of EPS assist, particularly during low-speed turning maneuvers. The loss and sudden return of EPS assist typically happens within a 1 second period and is caused by an electrical/software issue. If EPS assist is lost and suddenly returned, the driver could lose temporary control of the steering wheel, increasing the risk of a crash.
<b>Consequence:</b>	If EPS assist is lost and suddenly returned, the driver could lose temporary control of the steering wheel, increasing the risk of a crash.
<b>Remedy:</b>	Dealers will perform a reflash of the EPS module software.
<b>Notes:</b>	
<b>State:</b>	Available
<b>Reason Not Available:</b>	
<b>Refresh Date:</b>	01/26/2024
<b>OEM Recall Number:</b>	N172085440

---

<b>Components:</b>	BASE RADIO LOCK UP
<b>Report Receipt Date:</b>	06/05/2014
<b>Status:</b>	Closed
<b>NHTSA Campaign:</b>	14V301
<b>Severity Code:</b>	Critical
<b>Recall Type:</b>	Safety
<b>Parts Cost:</b>	
<b>Labor:</b>	
<b>Summary:</b>	General Motors has decided that certain 2014 MY Chevrolet Silverado LD, 2015 MY Chevrolet Silverado HD, Tahoe, Suburban and 2014 MY GMC Sierra LD, 2015 MY GMC Sierra HD vehicles equipped with a base radio and an internal amplifier (IO3 & (UQ3/UQ5)) may fail to conform to Federal Motor Vehicle Safety Standards 114 Theft protection and Rollaway Protection, and 208 Occupant Crash Protection. On these vehicles, the radio may become inoperative, causing a no-chime condition. There would not be an audible warning if the key is in the ignition and the driver's door is opened, and there would not be a seat belt audible warning if a front outboard seat belt is not buckled. Radio and chime functions are not restored until the battery is disconnected and reconnected.
<b>Consequence:</b>	Loss of the seat belt audible warning may increase the likelihood that a front outboard occupant is unbelted, increasing the risk of injury in a crash. Loss of an audible warning when a key is left in the ignition may increase the risk of vehicle theft.
<b>Remedy:</b>	Dealers are to reflash the base radio with updated software. This service will be performed for you at no charge.
<b>Notes:</b>	
<b>State:</b>	Available
<b>Reason Not Available:</b>	
<b>Refresh Date:</b>	01/26/2024
<b>OEM Recall Number:</b>	N140315

---

<b>Components:</b>	Increased Brake Pedal Effort
<b>Report Receipt Date:</b>	09/06/2019
<b>Status:</b>	Closed
<b>NHTSA Campaign:</b>	19V645
<b>Severity Code:</b>	Critical
<b>Recall Type:</b>	Safety
<b>Parts Cost:</b>	
<b>Labor:</b>	
<b>Summary:</b>	General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2014-2018 model year Cadillac Escalade, Chevrolet Silverado, Chevrolet Suburban, Chevrolet Tahoe, GMC Sierra, and GMC Yukon vehicles. In some circumstances, these vehicle may have a condition in which the engine-mounted mechanical vacuum pump output may decrease over time, decreasing the amount of vacuum/power brake assist.
<b>Consequence:</b>	.
<b>Remedy:</b>	Dealers will reprogram the electronic brake control module with a new calibration that will improve how the system utilizes the hydraulic brake boost assist function when vacuum assist is depleted.
<b>Notes:</b>	
<b>State:</b>	Available
<b>Reason Not Available:</b>	
<b>Refresh Date:</b>	01/26/2024
<b>OEM Recall Number:</b>	N192268490

**Components:** Driver's Front Seat Belt Anchor Pretensioner

**Report  
Receipt Date:** 06/25/2018

**Status:** Closed

**NHTSA  
Campaign:** NotAvailable

**Severity  
Code:** Unknown

**Recall Type:** Campaign

**Parts Cost:**

**Labor:**

**Summary:** On certain 2014-2015 model year Chevrolet Silverado LD and GMC Sierra LD vehicles, if a driver repeatedly sits on the seat belt cable cover located at the base of the driver's seat when entering the vehicle, it may cause the seat belt pretensioner to bend sharply over the seat side shield. If this continues to occur over an extended period of time, which is very rare, the seat belt pretensioner cable may fatigue and eventually separate, which could reduce the effectiveness of the vehicle's seat belts. Before any damage occurs to the pretensioner cable itself, signs of wear will be visible on the pretensioner cable cover where it has been repeatedly bent over the seat side shield. This special coverage covers the condition described above for a period of 10 years or 150,000 miles (240,000 km), whichever occurs first, from the date the vehicle was originally placed in service, regardless of ownership.

**Consequence:**

**Remedy:** Dealers are to replace the pretensioner and side shield for all customers that experience a broken pretensioner cable or come to a dealership with excessive wear on the cable sleeve. The repairs will be made at no charge to the customer.

**Notes:**

**State:** Available

**Reason Not  
Available:**

**Refresh Date:** 01/26/2024

**OEM Recall  
Number:** N172131700

## Possible Market Value Range

**0** | Market Values Found

## Ownership Costs

**5** | Ownership Costs Found

	Year 1	Year 2	Year 3	Year 4	Year 5
Depreciation	\$1,460	\$1,306	\$1,223	\$1,146	\$990
Insurance	\$1,741	\$1,748	\$1,846	\$1,969	\$1,957
Fuel	\$1,980	\$1,977	\$2,089	\$2,239	\$2,247
Maintenance	\$2,735	\$1,903	\$1,155	\$1,285	\$2,222
Repairs	\$1,102	\$1,213	\$1,414	\$1,575	\$1,730
Taxes & fees	N/A	N/A	N/A	N/A	N/A

## Possible Equipment

**472** | Equipments Found

#	Group	Name	Value	Availability
1	Comfort and Convenience	Drivers foot rest	Yes	
2	Comfort and Convenience	Cargo area light	Yes	
3	Comfort and Convenience	Day/night rearview mirror	Yes	
4	Comfort and Convenience	Headlight control	Yes	
5	Comfort and Convenience	Headlight control	Yes	
6	Comfort and Convenience	Service interval indicator	Yes	
7	Comfort and Convenience	Easy entry	Yes	
8	Comfort and Convenience	Coming home device	Yes	
9	Comfort and Convenience	Memorized adjustment	0	
10	Comfort and Convenience	Air conditioning	Manual	
11	Comfort and Convenience	Air conditioning	1	
12	Comfort and Convenience	Air conditioning	Yes	
13	Comfort and Convenience	Headlight control	Yes	
14	Comfort and Convenience	Power locks	Yes	
15	Comfort and Convenience	Power locks	Key	
16	Comfort and Convenience	Computer	Yes	
17	Comfort and Convenience	Cruise control	Yes	
18	Comfort and Convenience	Cruise control	Yes	
19	Comfort and Convenience	Power locks	Yes	
20	Comfort and Convenience	Computer	Yes	
21	Comfort and Convenience	Spare wheel	Fullsize	
22	Comfort and Convenience	Spare wheel	Steel	



23	Comfort and Convenience	Headlight control	Yes
24	Comfort and Convenience	Computer	Yes
25	Comfort and Convenience	Spare wheel	Under body
26	Comfort and Convenience	Spare wheel	Yes
27	Dimensions	Weights	3300
28	Dimensions	Weights	956.2
29	Dimensions	Weights	1496.9
30	Dimensions	Cargo area dimensions	Manufacturer's own
31	Dimensions	Weights	3039
32	Dimensions	Weights	6700
33	Dimensions	Weights	2108
34	Dimensions	Weights	3950
35	Dimensions	Weights	Yes
36	Dimensions	Weights	Manufacturer's own
37	Dimensions	Weights	2071.6
38	Dimensions	Weights	4567
39	Dimensions	Weights	1791.7
40	Dimensions	Cargo area dimensions	538.5
41	Dimensions	Cargo area dimensions	97.8
42	Dimensions	Cargo area dimensions	2484.1
43	Dimensions	Cargo area dimensions	76.3
44	Dimensions	Cargo area dimensions	2160.6
45	Dimensions	Cargo area dimensions	21.2
46	Dimensions	Cargo area dimensions	35.9
47	Dimensions	Cargo area dimensions	51
48	Dimensions	Cargo area dimensions	1295.4
49	Dimensions	Cargo area dimensions	Yes
50	Dimensions	Cargo area dimensions	911.9
51	Dimensions	Cargo area dimensions	64.6
52	Dimensions	Cargo area dimensions	1640.8
53	Dimensions	External dimensions	Yes
54	Dimensions	Internal dimensions	42.4
55	Dimensions	Internal dimensions	1077
56	Dimensions	External dimensions	1717
57	Dimensions	External dimensions	133

58	Dimensions	External dimensions	3378.2
59	Dimensions	Internal dimensions	60.7
60	Dimensions	Internal dimensions	66
61	Dimensions	Internal dimensions	1676.4
62	Dimensions	Internal dimensions	Yes
63	Dimensions	Internal dimensions	1542.5
64	Dimensions	Internal dimensions	45.3
65	Dimensions	Internal dimensions	1149.9
66	Dimensions	External dimensions	210.8
67	Dimensions	External dimensions	224.4
68	Dimensions	External dimensions	5699.8
69	Dimensions	External dimensions	68.8
70	Dimensions	External dimensions	1747.5
71	Dimensions	External dimensions	8.3
72	Dimensions	External dimensions	73.5
73	Dimensions	External dimensions	80
74	Dimensions	External dimensions	2032
75	Dimensions	External dimensions	67.6
76	Dimensions	External dimensions	1866.9
77	Dimensions	External dimensions	224.4
78	Dimensions	External dimensions	5699.8
79	Engine	Power	SAE
80	Engine	Power	3900
81	Engine	Power	5300
82	Engine	Engine	Aluminum
83	Engine	Engine	6
84	Engine	Engine	V
85	Engine	Power	285
86	Engine	Performance	Yes
87	Engine	Performance	7.4
88	Engine	Power	414
89	Engine	Power	305
90	Engine	Power	213
91	Engine	Engine	3.9
92	Engine	Engine	Yes
93	Engine	Engine	Yes
94	Engine	Engine	3.6

95	Engine	Engine	4.3
96	Engine	Engine	OHV
97	Engine	Engine	Yes
98	Engine	Engine	Aluminum
99	Engine	Engine	11
100	Engine	Engine	4300
101	Engine	Engine	Longitudinal
102	Engine	Engine	2
103	Engine	Engine	EcoTec3
104	Engine	Fuel tank	Yes
105	Engine	Fuel tank	Yes
106	Engine	Fuel tank	34
107	Engine	Auxiliary oil cooler	Yes
108	Engine	Fuel tank	Main
109	Engine	Fuel tank	
110	Engine	Fuel system	Gasoline direct injection
111	Engine	Fuel tanks	Unleaded
112	Engine	Fuel tanks	Main
113	Engine	Emission control level	LEV II
114	Engine	Cylinder shutdown	Yes
115	Engine	Fuel system	Yes
116	Engine	Fuel	E85
117	Engine	Fuel	Regular unleaded
118	Engine	Fuel	Yes
119	Engine	Additional fuel types	Yes
120	Engine	Additional fuel types	Yes
121	Engine	Additional fuel types	E85
122	Engine	Secondary power	330
123	Engine	Secondary power	297 HP
124	Engine	Secondary power	297 HP
125	Engine	Fuel	E85
126	Engine	Secondary power	Yes
127	Engine	Secondary power	448
128	Exterior	Tires	70
129	Exterior	Tires	70
130	Exterior	Tires	S
131	Exterior	Tires	10.0

132	Exterior	Tires	S
133	Exterior	Tires	Front
134	Exterior	Tires	17
135	Exterior	Tires	Rear
136	Exterior	Tires	2
137	Exterior	Tires	2
138	Exterior	Tires	10.0
139	Exterior	Door mirrors	Yes
140	Exterior	Door mirrors	Black
141	Exterior	Door mirrors	Yes
142	Exterior	Door mirrors	Passenger
143	Exterior	Door mirrors	Driver
144	Exterior	Tires	Yes
145	Exterior	Tires	Yes
146	Exterior	Tires	AS
147	Exterior	Door mirrors	Black
148	Exterior	Tires	AS
149	Exterior	Door mirrors/cameras	Black
150	Exterior	Door mirrors/cameras	Black
151	Exterior	Door mirrors/cameras	Yes
152	Exterior	Paint	Clearcoat
153	Exterior	Door mirrors/cameras	Yes
154	Exterior	Exhaust pipe	Yes
155	Exterior	Exhaust pipe	Mono
156	Exterior	Non-corrosive body	Alloy
157	Exterior	Non-corrosive body	Full
158	Exterior	Non-corrosive body	Yes
159	Exterior	Paint	Yes
160	Exterior	Exterior door handles	Yes
161	Exterior	Exterior door handles	Black
162	Exterior	Rear axle	Yes
163	Exterior	Tires	17
164	Exterior	Center high mount stop light	Yes
165	Exterior	Headlights	yes
166	Exterior	Headlights	Complex surface
167	Exterior	Headlights	yes
168	Exterior	Headlights	Yes

169	Exterior	Headlights	yes
170	Exterior	Bumpers	Yes
171	Exterior	Bumpers	Black
172	Exterior	Bumpers	Yes
173	Exterior	Bumpers	Rear
174	Exterior	Bumpers	Front
175	Exterior	Windshield wipers	Yes
176	Exterior	Disc brakes	4
177	Exterior	Windshield wipers	Variable intermittent
178	Exterior	Bumpers	Black
179	Exterior	Cargo doors	Tailgate
180	Exterior	Bumpers	Yes
181	Exterior	Trailer towing preparation	Yes
182	Exterior	Trailer towing preparation	IV
183	Exterior	Trailer towing preparation	Yes
184	Exterior	Swing away mirrors	Yes
185	Exterior	Pickup bed	Drop-in
186	Exterior	Rear door	Tailgate
187	Exterior	Bumpers	Yes
188	Exterior	Rear door	Yes
189	Exterior	Grille	Yes
190	Exterior	Grille	Black
191	Exterior	Wheels	2
192	Exterior	Wheels	2
193	Exterior	Wheels	Hub
194	Exterior	Wheels	431.8
195	Exterior	Wheels	431.8
196	Exterior	Wheels	17
197	Exterior	Wheels	17
198	Exterior	Wheels	Steel
199	Exterior	Wheels	8
200	Exterior	Wheels	8
201	Exterior	Wheels	Yes
202	Exterior	Pickup bed	Yes
203	Exterior	Pickup bed	98
204	Exterior	Pickup bed	Straight side
205	Exterior	Disc brakes	4

206	Exterior	Disc brakes	Yes
207	Exterior	Wheels	Yes
208	Exterior	Wheels	Yes
209	Exterior	Wheels	Yes
210	Exterior	Wheels	Yes
211	Exterior	Wheels	Yes
212	Exterior	Rear window	Fixed
213	Exterior	Rear window	Yes
214	Exterior	Day time running lights	Yes
215	Exterior	Electrically foldable mirrors	Manual
216	Exterior	Electrically foldable mirrors	Manual
217	Exterior	Doors	Driver
218	Exterior	Doors	Passenger
219	Exterior	Doors	Yes
220	Exterior	Doors	Yes
221	Exterior	Doors	Yes
222	Fuel Economy	Secondary fuel economy	16
223	Fuel Economy	Secondary fuel economy	15
224	Fuel Economy	Secondary fuel economy	12
225	Fuel Economy	Secondary fuel economy	Yes
226	Fuel Economy	Fuel economy	12
227	Fuel Economy	Fuel economy	18
228	Fuel Economy	Fuel economy	13
229	Fuel Economy	Secondary fuel economy	15
230	Fuel Economy	Secondary fuel economy	14
231	Fuel Economy	Secondary fuel economy	17
232	Fuel Economy	Secondary fuel economy	16
233	Fuel Economy	Secondary fuel economy	20
234	Fuel Economy	Secondary fuel economy	12
235	Fuel Economy	Secondary fuel economy	20
236	Fuel Economy	Fuel economy	20
237	Fuel Economy	Fuel tank	Main
238	Fuel Economy	Fuel economy	24
239	Fuel Economy	Fuel tank	Main
240	Fuel Economy	Fuel tank	34
241	Fuel Economy	Fuel economy	10
242	Fuel Economy	Fuel economy	24

243	Fuel Economy	Fuel economy	10
244	Fuel Economy	Fuel economy	18
245	Fuel Economy	Fuel economy	13
246	General	VinOptions Updated Date	20240122
247	General	Chrome Autodata Style Id	357124
248	General	Body style	2
249	General	Body style	224.4
250	General	Body style	2
251	Infotainment	Telematics	Yes
252	Infotainment	Connection to ext.entertainment devices	Yes
253	Infotainment	Multi-function display screen	4.20
254	Infotainment	Internet connection	Yes
255	Infotainment	Apps control	Yes
256	Infotainment	Built-in Apps	OnStar RemoteLink
257	Infotainment	Telematics	Yes
258	Infotainment	Connection to ext.entertainment devices	Yes
259	Infotainment	Audio system	Yes
260	Infotainment	Audio system	Yes
261	Infotainment	Speakers	Yes
262	Infotainment	Audio system	Yes
263	Infotainment	Speakers	4
264	Infotainment	Antenna	Yes
265	Infotainment	Audio system	AM/FM stereo
266	Infotainment	Audio system	Yes
267	Infotainment	Built-in Apps	Yes
268	Infotainment	Mobile phone	Bluetooth
269	Infotainment	Mobile phone	Yes
270	Infotainment	Bluetooth	Yes
271	Infotainment	Bluetooth	Bluetooth
272	Infotainment	Telematics	Yes
273	Infotainment	Bluetooth	Yes
274	Infotainment	Bluetooth	Yes
275	Infotainment	Voice activating system	Yes
276	Infotainment	Audio system	Chevrolet MyLink
277	Infotainment	Apps control	OnStar RemoteLink
278	Infotainment	Mobile Integration	Yes

279	Infotainment	Audio system	Yes
280	Infotainment	Voice activating system	Chevrolet MyLink
281	Infotainment	Voice activating system	Yes
282	Infotainment	Audio system	Chevrolet MyLink
283	Interior	Console	Mini
284	Interior	Luxury trim	None
285	Interior	Luxury trim	None
286	Interior	Luxury trim	None
287	Interior	Console	Yes
288	Interior	Console	Overhead
289	Interior	Luxury trim	Yes
290	Interior	Vanity mirror	Passenger
291	Interior	Water temperature	Yes
292	Interior	Water temperature	Yes
293	Interior	Instrument panel	Yes
294	Interior	Instrument panel	Analog
295	Interior	Interior Code	H2R
296	Interior	Floor mats	Yes
297	Interior	Floor mats	Carpet front
298	Interior	Fourth row seats	Yes
299	Interior	Fourth row seats	Fixed
300	Interior	Reading lights	Front
301	Interior	Glove compartment	Yes
302	Interior	Vanity mirror	Yes
303	Interior	Reading lights	Yes
304	Interior	Glove compartment	Yes
305	Interior	Oil pressure	Yes
306	Interior	Instrument panel	Yes
307	Interior	Glove compartment	Yes
308	Interior	Oil pressure	Yes
309	Interior	Front seat	Yes
310	Interior	Front seat	yes
311	Interior	Front seat	yes
312	Interior	Front seat	Yes
313	Interior	Front seat	Yes
314	Interior	Front seat	Manual
315	Interior	Front seat center armrest	Yes



316	Interior	Odometer	Yes
317	Interior	Door pockets/bins	Yes
318	Interior	Front seat	Manual
319	Interior	Ashtray	Yes
320	Interior	Front seat center armrest	Yes
321	Interior	Seat upholstery	Cloth
322	Interior	Luxury inner roof upholstery	Yes
323	Interior	Luxury inner roof upholstery	Cloth
324	Interior	Seat upholstery	Cloth
325	Interior	Seat upholstery	Yes
326	Interior	Seat upholstery	Yes
327	Interior	Front seat	Yes
328	Interior	Front seat	Manual
329	Interior	Front seat	Manual
330	Interior	Front seat	Split-bench
331	Interior	Front seat	Manual
332	Interior	Front seat	Yes
333	Interior	Steering wheel	Yes
334	Interior	Tachometer	Yes
335	Interior	Clock	In-radio display
336	Interior	Steering wheel	Urethane
337	Interior	Steering wheel	Yes
338	Interior	Steering wheel	Yes
339	Interior	Cup holders	Yes
340	Interior	Cup holders	Yes
341	Interior	12v power outlet	2
342	Interior	Luxury trim	None
343	Interior	Variable panel light	Yes
344	Interior	Cup holders	Front seats
345	Interior	Door pockets/bins	Yes
346	Interior	Courtesy lights	Yes
347	Interior	Door pockets/bins	Yes
348	Interior	Clock	Yes
349	Interior	Door pockets/bins	Yes
350	Interior	Seating	Yes
351	Interior	Seating	3
352	Interior	Floor covering	Carpet

353	Interior	Floor covering	Yes
354	Interior	Courtesy lights	Yes
355	Price & Cost	Base MSRP Discount	4
356	Price & Cost	Base MSRP	25965
357	Price & Cost	Delivery Charges	1095
358	Price & Cost	As Configured MSRP	27800
359	Price & Cost	As Configured Invoice	26541.2
360	Price & Cost	As Configured Dealer	25707.2
361	Safety and Driver Assist	Low fuel level warning	Yes
362	Safety and Driver Assist	Low coolant level warning	Yes
363	Safety and Driver Assist	Stability control	StabiliTrak w/Proactive Roll Avoidance
364	Safety and Driver Assist	Low tire pressure indicator	Yes
365	Safety and Driver Assist	Front airbag	Yes
366	Safety and Driver Assist	Electronic traction control	Yes
367	Safety and Driver Assist	Low tire pressure indicator	Yes
368	Safety and Driver Assist	Low washer fluid level warning	Yes
369	Safety and Driver Assist	Hill holder	Yes
370	Safety and Driver Assist	Anti collision system	Yes
371	Safety and Driver Assist	Door reinforcement	Yes
372	Safety and Driver Assist	Key-in-ignition warning sound	Yes
373	Safety and Driver Assist	Front seat belts	Front
374	Safety and Driver Assist	Head restraints	Yes
375	Safety and Driver Assist	Front seat belts	Yes
376	Safety and Driver Assist	Front seat belts	Yes
377	Safety and Driver Assist	Immobilizer	Yes
378	Safety and Driver Assist	Rear seat belts	Yes
379	Safety and Driver Assist	ABS	4-wheel
380	Safety and Driver Assist	Low oil level warning	Yes
381	Safety and Driver Assist	Rear seat belts	Lap
382	Safety and Driver Assist	Side curtain airbag	Front and rear
383	Safety and Driver Assist	Side curtain airbag	Front
384	Safety and Driver Assist	Headlight on warning sound	Yes
385	Safety and Driver Assist	Trailer stability program	Yes
386	Safety and Driver Assist	Head restraints	Front seats
387	Safety and Driver Assist	Airbags	Yes
388	Safety and Driver Assist	ABS	Yes
389	Safety and Driver Assist	Door ajar warning	Yes

390	Safety and Driver Assist	Airbags	Yes
391	Safety and Driver Assist	Roll stability control	Yes
392	Safety and Driver Assist	Side airbag	Yes
393	Safety and Driver Assist	Stability control	Yes
394	Safety and Driver Assist	Side airbag	Front
395	Safety and Driver Assist	Side airbag	Yes
396	Safety and Driver Assist	Power steering	Yes
397	Safety and Driver Assist	Power steering	Electric power-assist
398	Safety and Driver Assist	Head restraints	yes
399	Safety and Driver Assist	Power steering	Yes
400	Safety and Driver Assist	Brake assist system	Yes
401	Safety and Driver Assist	Front airbag	yes
402	Safety and Driver Assist	Front airbag	yes
403	Safety and Driver Assist	Front airbag	Yes
404	Safety and Driver Assist	Front airbag	Yes
405	Suspension	Suspension	Rear
406	Suspension	Suspension	Short and long arm
407	Suspension	Suspension	Leaf
408	Suspension	Suspension	Leaf
409	Suspension	Suspension	yes
410	Suspension	Suspension	Coil
411	Suspension	Suspension	Yes
412	Suspension	Suspension	Front
413	Suspension	Suspension	Yes
414	Suspension	Suspension	Independent
415	Suspension	Suspension	Rigid
416	Transmission	Transmission	Yes
417	Transmission	Differential lock	Yes
418	Transmission	Transmission	Yes
419	Transmission	Transmission	3.1
420	Transmission	Active differential	Yes
421	Transmission	Transmission	0.7
422	Transmission	Differential lock	yes
423	Transmission	Active differential	Rear
424	Transmission	4X4 specifics	14.7
425	Transmission	Axle Ratio :1	Yes
426	Transmission	4X4 specifics	Yes

427	Transmission	4X4 specifics	23.7
428	Transmission	Drive	Rear-wheel
429	Transmission	Transmission	Yes
430	Transmission	Axle Ratio :1	3.2
431	Transmission	Drive	Yes
432	Transmission	Transmission	Automatic
433	Transmission	Transmission	6
434	Transmission	Transmission	Yes
435	Transmission	Transmission	Automatic with manual mode
436	Transmission	Powertrain type	Yes
437	Transmission	Powertrain type	Combustion
438	Transmission	Transmission	2.4
439	Transmission	Transmission	0.9
440	Transmission	Transmission	1.2
441	Transmission	Transmission	1.5
442	Transmission	Transmission	Yes
443	Transmission	Transmission	4
444	Warranty	Warranty anti-corrosion	100000
445	Warranty	Warranty full maintenance	38623
446	Warranty	Warranty anti-corrosion	Yes
447	Warranty	Warranty anti-corrosion	72
448	Warranty	Warranty full maintenance	Yes
449	Warranty	Warranty roadside assistance	160930
450	Warranty	Warranty full maintenance	24
451	Warranty	Warranty anti-corrosion	160930
452	Warranty	Warranty full maintenance	24000
453	Warranty	Warranty whole vehicle - M	57935
454	Warranty	Warranty whole vehicle - M	36000
455	Warranty	Warranty powertrain - M	Yes
456	Warranty	Warranty powertrain - M	100000
457	Warranty	Warranty powertrain - M	60
458	Warranty	Warranty whole vehicle - M	36
459	Warranty	Warranty roadside assistance	60
460	Warranty	Warranty roadside assistance	Yes
461	Warranty	Warranty roadside assistance	100000
462	Warranty	Warranty whole vehicle - M	Yes
463	Warranty	Warranty powertrain - M	160930

464	Color	Blue Granite Metallic	Exterior
465	Color	Silver Ice Metallic	Exterior
466	Color	Summit White	Exterior
467	Color	Black	Exterior
468	Color	Deep Ruby Metallic	Exterior
469	Color	Victory Red	Exterior
470	Color	Blue Topaz Metallic	Exterior
471	Color	Brownstone Metallic	Exterior
472	Color	Tungsten Metallic	Exterior

## Possible Warranties

**5** | Warranties Found

#	Type	Miles	Months
1	Warranty roadside assistance	100000 miles	60 months
2	Warranty whole vehicle - M	36000 miles	36 months
3	Warranty powertrain - M	100000 miles	60 months
4	Warranty anti-corrosion	100000 miles	72 months
5	Warranty full maintenance	24000 miles	24 months

**Are you a California Resident?** Report something missing or inaccurate by visiting: [beenverified.com/contact/vehicle-history-report-inquiry/](https://beenverified.com/contact/vehicle-history-report-inquiry/)

**Disclaimer:** The information contained in any report and on our website is not necessarily 100% accurate, complete or up to date, nor a substitute for your own due diligence. Our data comes from a wide variety of sources, but some municipalities and jurisdictions are slow to report and digitize their data, so we cannot guarantee or warrant full accuracy of ALL search results. This report does not contain detailed information regarding a vehicle's repair history nor information on all motor vehicles in the United States because some states are not yet providing their vehicle data to the system. Currently, the data provided by states is provided in a variety of time frames; while some states report and update data in "real-time" (as title transactions occur), other states send updates less frequently.

Information on previous, significant vehicle damage may not be included in the system if the vehicle was never determined by an insurance company to be a "total loss" or branded by a state titling agency.

A vehicle history report is NOT a substitute for an independent vehicle inspection. Before making a decision to purchase a vehicle, users are strongly encouraged to also obtain an independent vehicle inspection to ensure the vehicle does not have hidden damage.

It may not currently include commercial vehicles if those vehicles are not included in a state's primary database for title records (in some states, those vehicles are managed by a separate state agency), although these records may be added at a later time.

Brand types and definitions vary by state, but may provide useful information about the condition or prior use of the vehicle.

The information used to compile this report is aggregated from various government agencies, non-profit organizations, and industry sources. The accuracy and reliability of the information supplied depends primarily on the reporting sources, and all entities involved in compiling this report accept no liability for any errors or omissions.



**NMVTIS Disclaimer:** The National Motor Vehicle Title Information System (NMVTIS) is an electronic system that contains information on certain automobiles

---

titled in the United States. NMVTIS is intended to serve as a reliable source of title and **brand** history for automobiles, but it does not contain detailed information regarding a vehicle's repair history.

All states, insurance companies, and junk and salvage yards are required by federal law to regularly report information to NMVTIS. However, NMVTIS does not contain information on all motor vehicles in the United States because **some states** are not yet providing their vehicle data to the system. Currently, the data provided to NMVTIS by states is provided in a variety of time frames; while some states report and update NMVTIS data in "real-time" (as title transactions occur), other states send updates less frequently, such as once every 24 hours or within a period of days.

Information on previous, significant vehicle damage may not be included in the system if the vehicle was never determined by an insurance company (or other appropriate entity) to be a "total loss" or branded by a state titling agency. Conversely, an insurance carrier may be required to report a "total loss" even if the vehicle's titling-state has not determined the vehicle to be "salvage" or "junk."

A vehicle history report is NOT a substitute for an independent vehicle inspection. Before making a decision to purchase a vehicle, consumers are **strongly encouraged to also obtain an independent vehicle inspection** to ensure the vehicle does not have hidden damage. The **Approved NMVTIS Data Providers** (look for the NMVTIS logo) can include vehicle condition data from sources other than NMVTIS.

#### **Consumer Access Product Disclaimer**

NMVTIS data **INCLUDES** (as available by those entities required to report to the System):

- Information from **participating** state motor vehicle titling agencies.
- Information on automobiles, buses, trucks, motorcycles, recreational vehicles, motor homes, and tractors. NMVTIS may not currently include commercial vehicles if those vehicles are not included in a state's primary database for title records (in some states, those vehicles are managed by a separate state agency), although these records may be added at a later time.
- Information on "brands" applied to vehicles provided by participating state motor vehicle titling agencies. Brand types and definitions vary by state, but may provide useful information about the condition or prior use of the vehicle.
- Most recent odometer reading in the state's title record.
- Information from insurance companies, and auto recyclers, including junk and salvage yards, that is required by law to be reported to the system, beginning March 31, 2009. This information will include if the vehicle was determined to be a "total loss" by an insurance carrier.
- Information from junk and salvage yards receiving a "cash for clunker" vehicle traded-in under the Consumer Assistance to Recycle and Save Act of 2009 (CARS) Program.

Consumers are advised to visit **[www.vehiclehistory.bja.ojp.gov](http://www.vehiclehistory.bja.ojp.gov)** for details on how to interpret the information in the system and understand the meaning of various labels applied to vehicles by the participating state motor vehicle titling agencies.

Copyright © 2024 BeenVerified, Inc. Inc. All Rights Reserved.