

Wilcom embroidery test report

W-001

COMMENT

With background removal enabled, Wilcom probably misread the green as the background and removed it. Test to run: preprocess the image by removing the background before sending it to Wilcom, or set removeBackground to false and compare the results.

SOURCE



► Request XML

RESULT



► Response XML

W-002

COMMENT

Good result.

SOURCE



► Request XML

RESULT



► Response XML

W-003

COMMENT

Needs evaluation to see whether it can be improved; try preprocessing.

SOURCE



► Request XML

RESULT



► Response XML

W-004

COMMENT

Very poor result, but the image resolution after background removal may be low. Try preprocessing before sending it to Wilcom.

SOURCE



► Request XML

RESULT



► Response XML

W-005

SOURCE



► Request XML

RESULT



► Response XML

W-006

COMMENT

The source image is too detailed, but try fine-tuning the API parameters to see whether it can be improved.

SOURCE



► Request XML

RESULT



► Response XML

W-007

COMMENT

Result has defects. Need to understand whether the source image has issues and whether we can detect them before sending the request to Wilcom.

SOURCE



► Request XML

RESULT



► Response XML

W-008

SOURCE



► Request XML

RESULT



► Response XML

W-009

COMMENT

Unsatisfactory result: the background was removed, but not completely. Test again without background removal.

SOURCE



► Request XML

RESULT



► Response XML

W-010

COMMENT

Excellent result.

SOURCE



► Request XML

RESULT



► Response XML

W-011

COMMENT

Insufficient result. Need to understand whether it can be improved by changing API parameters.

SOURCE



► [Request XML](#)

RESULT




► [Response XML](#)

W-012

COMMENT

Same background removal issue as W-001, but it is probably manageable.

SOURCE



► [Request XML](#)

RESULT



► [Response XML](#)

W-013

COMMENT

Needs improvement; investigate how to improve it.

SOURCE



► Request XML

RESULT



► Response XML

W-014

SOURCE



► Request XML

RESULT



► Response XML

W-015

SOURCE



► Request XML

RESULT



► Response XML

W-016

COMMENT

Although the request includes five colors, Wilcom uses only one. Test other gradients.

SOURCE



► Request XML

RESULT



► Response XML

W-017

SOURCE



► Request XML

RESULT



► Response XML

W-018

SOURCE



► Request XML

RESULT



► Response XML

W-019

COMMENT

Excellent result.

SOURCE



► Request XML

RESULT



► Response XML

W-020

COMMENT

Good result.

SOURCE



► Request XML


RESULT



► Response XML

W-021

SOURCE



► Request XML

RESULT



► Response XML