

UR AERIAL SOLUTIONS

Aerial Property Maintenance Inspection Snapshot

Inspection ID:	db5f9e42...	Inspection Date:	2026-06-21
Property Address:	Zone coordinate (-33.951, 18.49), Industrial Area, Cape Town, South Africa	GPS Coordinates:	-33.951, 18.49
Maintenance Urgency:	HIGH (Action Recommended)	Max Conf Score:	100.00%

AI Inspection Results

Our proprietary exterior monitoring models scanned top-down imagery of your property. Below is the breakdown of issues detected:

Issue Category	Confidence Score	Status
Biological Growth (Algae, Moss, Mold)	100.00%	Detected
Surface Staining (Grime, Rust, Carbon)	42.72%	None / Minimal

Aerial View Snapshot

[Image snippet not available locally. Refer to Supabase cloud storage]

Proposed Drone Cleaning & Inspection Solution

UR Aerial Solutions offers high-efficiency drone exterior maintenance cleaning. Drone spraying has major advantages over traditional scaffolding or high-pressure washing:

- **Safety:** Zero-worker height risk. Drone spray operations are controlled remotely from the ground.
- **Speed:** Inspections and cleaning are completed in a fraction of the time, causing minimal business disruption.
- **Eco-Friendly Soft Washing:** We use specialized chemical solutions that dissolve mold and grime at low pressure, preserving your roof and surface structure integrity.

POPIA Compliance Notice:

UR Aerial Solutions respects your privacy and POPIA (Protection of Personal Information Act, South Africa) principles. This snapshot was generated from publicly available geo-spatial data and is intended for commercial property owners to assess preventative maintenance needs. If you do not wish to receive further automated inspection alerts, you can request immediate opt-out by contacting optout@uraerials.co.za or clicking unsubscribe in our communications.