

UR AERIAL SOLUTIONS

Aerial Property Maintenance Inspection Snapshot

Inspection ID:	e803103d...	Inspection Date:	2026-06-23
Property Address:	82 Vanguard Dr, Woodstock / Woodstock, Cape Town, South Africa	GPS Coordinates:	-33.9311374794894, 18.4426869236535
Maintenance Urgency:	CRITICAL (Immediate Action Recommended)	Primary Metric:	Haze: 0.0%

AI Inspection Results

Our computer vision facade analysis scanned Street View imagery of your property. Below is the breakdown of issues detected:

AI Metric Category	Measured Level	Threshold Status
Glass Haziness (Salt spray / Haze film)	0.0%	Clean
Facade Streaks & Water spots	33 streaks	Needs Cleaning (>5)
Spot Grime Coverage (Organic / Dust)	40.1%	Needs Cleaning (>10%)
Frame & Sill Grime Accumulation	55.1%	Clean
Building Height / Storeys	5 storeys	Target drone advantage (3+ storeys)

Facade Inspection Scan Snippet

[Image snippet not available locally. Refer to Supabase cloud storage]

Proposed Drone Cleaning & Inspection Solution

UR Aerial Solutions offers high-efficiency drone exterior maintenance cleaning. Drone spraying has major advantages over traditional scaffolding or high-pressure washing:

- **Safety:** Zero-worker height risk. Drone spray operations are controlled remotely from the ground.
- **Speed:** Inspections and cleaning are completed in a fraction of the time, causing minimal business disruption.
- **Eco-Friendly Soft Washing:** We use specialized chemical solutions that dissolve mold and grime at low pressure, preserving your roof and surface structure integrity.

POPIA Compliance Notice:

UR Aerial Solutions respects your privacy and POPIA (Protection of Personal Information Act, South Africa) principles. This snapshot was generated from publicly available geo-spatial data and is intended for commercial property owners to assess preventative maintenance needs. If you do not wish to receive further automated inspection alerts, you can request immediate opt-out by contacting optout@uraerials.co.za or clicking unsubscribe in our communications.