Fiber circuit: NF-FC-0002 · Stockholm - Oslo, pair 1

From sto-patch-osl-01 : Port 1 to osl-patch-sto-01 : Port 1
1 cable · fiber circuit · Active · Nordfiber AB
2 strands · 1550 nm · measured loss 95.52 dB

Shown from sto-patch-osl-01 : Port 1 to osl-patch-sto-01 : Port 1: the equipment beyond the circuit's end ports is left out.

sto-patch-osl-01

Patch Panel · Generic LC-24 trunk patch panel (24-pair)

IN	OUT
Port 1 Type: LC	**Trunk** Type: Splice Positions: 24

Status	Active
Tenant	Nordfiber AB
Site	Nordfiber Stockholm DC
Region	Nordics › Sweden
Location	Telecom Room
Rack	STO-TR-01
Position	U38 · front
Serial	GEN-STO-0004
Asset tag	NF-STO-00004

bb-cbl-00003

Colour: Blue
Type: Single-mode Fiber (OS2)
Length: 447.7 km
Status: Connected
Tenant: Nordfiber AB
Description: Leased 24-pair trunk (Polarlink Transit, PLT-100234), Stockholm - Oslo via Västerås, Örebro, Karlstad, Charlottenberg
Fiber cable: Corning ALTOS Loose Tube 48F SM
Fibers: 48 · loose tube
Sheath: HDPE, armoured (steel tape), duct
Fiber serial: CNG-ALTOS24-0003
Installed: 2021-09-01
Route marks: 0 – 447699 m
Fiber notes: Leased from Polarlink Transit under PLT-100234. 24 pairs (48 fibers). Lit with Nordfiber's own WDM equipment.
Strands: Tube 1-F1 (red), Tube 1-F2 (green)
Fiber circuit: NF-FC-0002 · Stockholm - Oslo, pair 1

osl-patch-sto-01

Patch Panel · Generic LC-24 trunk patch panel (24-pair)

IN	OUT
Trunk Type: Splice Positions: 24	**Port 1** Type: LC

Status	Active
Tenant	Nordfiber AB
Site	Nordfiber Oslo PoP
Region	Nordics › Norway
Location	Telecom Room
Rack	OSL-TR-01
Position	U41 · front
Serial	GEN-OSL-0002
Asset tag	NF-OSL-00002