MANGALORE REFINERY AND PETROCHEMICALS LIMITED (MRPL)
TECHNICAL SERVICES & ASSET INTEGRITY MANAGEMENT DEPARTMENT
ULTRASONIC THICKNESS INSPECTION REPORT

Report ID: MRPL-INSP-2024-P201
Equipment Tag: P-201
Equipment Description: Crude Feed Booster Pump
Plant Area: CDU-II Processing Area, Mangalore Refinery
Inspection Date: 2024-06-01
Survey Type: Statutory 5-Year Ultrasonic Grid Survey (Grids C1 through C8)

MEASUREMENT DATA & WALL THICKNESS READINGS:
Previous Wall Thickness: 6.0 mm (Baseline recorded 2019)
Current Wall Thickness: 4.5 mm (Measured June 2024)
Inspection Interval: 5.0 years (2019 - 2024)
Minimum Allowable Thickness: 3.5 mm (per ASME B31.3 / API 570)
Operating Pressure: 28.5 kg/cm2g
Material Specification: ASTM A216 WCB / 2205 Duplex SS Impeller
Mechanical Vibration: 3.2 mm/s RMS (ISO 10816 Zone A/B Compliant)
NDE Status: Zero pitting, cracking, or cavitation erosion observed.