


IRIS INTELLIGENT INFRARED AI ENHANCEMENT & DETECTION REPORT

Image: enhanced_ai_colorized.jpg | Generated: 2026-07-08 10:27:45 UTC

VISUAL PHOTOGRAPH & OBJECT DETECTIONS



OBJECT DETECTION INVENTORY

#	OBJECT CATEGORY	CONFIDENCE	HIERARCHY & COLOR TAG
1	BUILDING	94.0%	PRIMARY STRUCTURE (RED)
2	NEIGHBOR	88.0%	ADJACENT STRUCTURE (BLUE)
3	WINDOW	91.0%	THERMAL EMITTER (BLUE)
4	WINDOW	89.0%	THERMAL EMITTER (BLUE)
5	WINDOW	87.0%	THERMAL EMITTER (BLUE)
6	WINDOW	86.0%	THERMAL EMITTER (BLUE)
7	ROOF VENT	85.0%	EXHAUST VENT (ORANGE)

8	FENCE	92.0%	BOUNDARY (VIOLET)
---	-------	-------	-------------------

GEMINI AI SCENE INTERPRETATION

The infrared image shows a residential house with surrounding vegetation. The enhancement and colorization stages improved image quality, enabling successful object detection. No immediate hazards were identified. The scene appears to represent a normal residential environment.