

photoset

photo tier · 2 rooms · 3.81 m² [1.05, 6.56] · 11.4 s
every value carries a nominal 90% interval · * means the sensor never saw it



Rooms

Room	Area m²	Ceiling m	Walls	Openings
R1	1.77 (0.49-3.05)	2.55 *	4	0
R2	2.03 (0.56-3.51)	2.55 *	4	0

Damage and scope

no damage regions found
class would be shape-derived; naming a defect needs appearance

What to be careful of (2)

[warning] photo tier: 11 stills across 2 room folder(s). Depth is INFERRED, and there are NO camera poses
-- each photo is levelled against the floor it can see but never located. Rooms are therefore NOT stitched: they are placed side by side, and the whole-property stitch gate fails by construction. An L-shaped room returns as its bounding box
[error] 2 room(s) are reported as separate rectangles, laid out side by side and joined to nothing. With no camera poses there is nothing in the input that says how the rooms relate, so the whole-property stitch gate fails by construction rather than by accident. Each room is the bounding box of what one view could see: an L-shaped room returns as a rectangle