

RESIDENTIAL FIRE DRILL / EVACUATION RECORD

Site Address: 47 Maple St

DDSO / Provider Agency: Northstar DDSO

Date: 12/17/2026

Time Evacuation Started: 9:12 PM

Part of Day: Afternoon

Total time to evacuate to ground: 4 min 6 sec

Total time for all to reach safe area: 7 min

Centrally Monitored Fire Alarm Station: No

Time Monitoring Station Notified of Drill: 11:31 PM

Time Monitoring Station Reactivated: 9:19 AM

Time Monitoring Station Received Alarm: 4:21 AM

Weather Conditions: Mild

Method of Alarm Activation ☐ Pull Station ☒ Smoke Detector ☐ Other

Evacuation Type ☒ Full Evacuation to Outside ☐ Other

Type of Evacuation ☒ Announced ☒ Unannounced ☐ Supervised

Location of Simulated Fire: Basement

Blocked Exits by Simulated Fire: None

Location: 1st floor

RESIDENTS & EVACUATION DETAIL

Name	Away?	To Evacuate	At Safe Area	Details
T. Nguyen	N	1:04	2:42	Independent
R. Patel	N	3:47	5:55	Used main exit
L. Romano	N	2:27	4:38	Wheelchair ramp
K. Adams	N	1:03	3:44	Assisted

Description of evacuation: All residents evacuated calmly via the main exit.

Problems noted / actions: Exit light was dim; bulb replaced.

Did Evacuation proceed per plan: No

Were all exits/routes clear: Yes

Did alarms/strobes function: No

Was drill observed: No

Did evacuation time meet requirement ☐ Yes ☒ No