

RESIDENTIAL FIRE DRILL / EVACUATION RECORD

Site Address: 964 Oak St

DDSO / Provider Agency: Brookline Care Agency

Date: 02/24/2026

Time Evacuation Started: 12:30 PM

Part of Day: Morning

Total time to evacuate to ground: 3 min 15 sec

Total time for all to reach safe area: 7 min

Centrally Monitored Fire Alarm Station: Yes

Time Monitoring Station Notified of Drill: 4:47 PM

Time Monitoring Station Reactivated: 8:54 PM

Time Monitoring Station Received Alarm: 2:30 PM

Weather Conditions: Clear

Method of Alarm Activation ☒ Pull Station ☒ Smoke Detector ☐ Other

Evacuation Type ☒ Full Evacuation to Outside ☐ Other

Type of Evacuation ☐ Announced ☐ Unannounced ☒ Supervised

Location of Simulated Fire: Kitchen

Blocked Exits by Simulated Fire: Side exit

Location: 2nd floor

RESIDENTS & EVACUATION DETAIL

Name	Away?	To Evacuate	At Safe Area	Details
J. Rivera	N	3:36	2:44	Wheelchair ramp
K. Adams	N	1:00	3:43	Wheelchair ramp
T. Nguyen	Y	2:03	5:18	Used main exit
L. Romano	N	2:17	4:29	Assisted

Description of evacuation:

Staff assisted one resident with mobility needs.

Problems noted / actions:

None noted.

Did Evacuation proceed per plan:

No

Were all exits/routes clear:

Yes

Did alarms/strobes function:

No

Was drill observed:

Yes

Did evacuation time meet requirement

☐ Yes

☒ No