

Damaged road divider on Outer Ring Road

Road Damage

Severity: High

Municipal Corp (BBMP)

The concrete divider on ORR between Marathahalli and Bellandur has been broken in multiple places after a truck collision last week. The iron reinforcement rods are exposed and dangerous. Vehicles are crossing into oncoming traffic in the gaps, especially two-wheelers.

LOCATION

Outer Ring Road, Marathahalli, Bengaluru 560037

Open in Google Maps: <https://maps.google.com/?q=12.9545,77.6963>

TIMELINE

- **WIP** · @CivicRaptor · 15/6/2026, 10:27:02 am
On-site inspection done. Team dispatched with materials. ETA: 24 hours.
- **SOLVED** · @BengaluruBrave · 16/6/2026, 10:27:02 pm
Issue resolved. Site inspected and verified safe for public use.

