

GOVT.OF KARNATAKA
PUBLIC WORKS DEPARTMENT

Office of the Executive Engineer, Mysore Division, Mysore.

www.eemys@kpwd.gov.in

Telephone No.: Fax No.: 0821-2420810

No.: EE/PWD/MDM/A.E.-1/S.C/2022-23, No.: 1657/22.08.2022.

To:


THE HEAD MASTER
Mount Litera Zee School
H.D. Kote Road,
MYSORE.

Sir,

Sub: Regarding issuance of Safety Certificate of Mount Litera School Building of D. Saluhundi Village, Jayapura Hobli, Mysore Taluk.

- Ref: 1) Letter No.: 590, dt: 14.07.2022 of the Office of the Assistant Executive Engineer, Public Works Department, No.: 1 Sub-Division, Mysore.
- 2) Govt. Letter No.: (Education Dept.) PWD/59/BED/2019, dated: 06.05.2022.
- 3) Govt. Circular No.: ED/43/PGC/2022, dt: 18.05.2022.

With reference to the above subject, the Executive Engineer, Public Works Department, Mysore Division, Mysore and the Assistant Executive Engineer, No.1 Sub-Division, Mysore have inspected the building of Mount Litera School of D. Saluhundi Village, Jayapura Hobli, Mysore Taluk, the Assistant Executive Engineer, Public Works Department, Quality Assurance Sub-Division, Mysore has as per ISO/IEC National Building Code 2016 Group B (Sub Division B1 and B2) Education Building along with NDT test & Structural Stability Certificate and Technical Reports in the prescribed format has submitted a Report. The said Report has been certified by the Assistant Executive Engineer, Public Works Department, No.1 Sub-Division, Mysore by conducting spot inspection, vide Ref. (1).




The Original Document in
English is
and the translation is Verified by me
as true and Correct.

Kannada
...2...
Signature
12.12

On inspecting the said building, toilets and drinking water arrangements required for the building have been provided, cracks in the plastering of some of the walls of the building have found and Dampness occurred in the Toilet and roof of the staircase. It is 4-5 years since painting done to the building. It has been directed to carry-out minor repairs as stated above and to erect water proof to the roof and to paint the building vide Ref. (1) as reported by the Assistant Executive Engineer, Public Works Department, No. 1 Sub-Division, Mysore. Rest, the Assistant Executive Engineer, Public Works Department, Quality Assurance Sub-Division, Mysore has certified that the building is safe.

Further, relating to the safety of the building, the Assistant Executive Engineer, No.1 Sub-Division, Mysore in the above referred letter has reported that about the Concrete strength of the building, the Assistant Executive Engineer, Public Works Department, Quality Assurance Sub-Division, Mysore has taken-up the Physical Observation & Accordingly necessary field Tests, and it is found that the building is strong as per the report of the test conducted by the Technical Section of the Sub-Division with the Consultants.

The said Institution, as per the Circular No. PWD/59/BED/2019 dated: 06.05.2022 of the Govt. of Karnataka, have remitted the prescribed fee of Rs. 5,000-00 on dated: 19.08.2022 to the Accounts Section to obtain Safety Certificate of the said building. On verifying all the records furnished by the said Institution, by considering the certificate issued by the Assistant Executive Engineer, Public Works Department, Quality Assurance Sub-Division,




/ 3 /

Mysore and on **inspection** by the Technical Team of the Public Works Department in respect of the said building, since it is found from the Test Reports that the said building is " Structurally Stable", for the current Academic Year Building Safety Certificate has been issued.

Yours faithfully,

Sd/-

Executive Engineer,
Public Works Department,
Mysore Division, Mysore.



The document in respect of **KANNADA**
is translated to **English**
and the translation is Verified by me
as true and Correct.

enulou
NOTARY MYSORE

17 MAY 2023

Founder Trustee
Founder Trustee
SANTO EDUCATIONAL TRUST
(Mount Litera Zee School)
MYSORE-570 008.

Principal
PRINCIPAL
MOUNT LITERA ZEE SCHOOL
MYSORE-570 008



ಸಂ:ಕಾಇಂ:ಲೋಇ:ಮೈವಿಮೈ:ಸ ಇಂ-1:ಸುಪ್ರಪ:2022-23:

NO 1657
22-08-22

ರವರಿಗೆ

ಮುಖ್ಯೋಪಾಧ್ಯಾಯರು,
ಮೌಂಟ್ ಲಿಟರರಾ ಜೀ ಸ್ಕೂಲ್,
ಹೆಚ್.ಡಿ. ಕೋಟೆ ರಸ್ತೆ,
ಮೈಸೂರು.

ಮಾನ್ಯರೇ,

ವಿಷಯ: ಮೈಸೂರು ತಾಲ್ಲೂಕು, ಜಯಪುರ ಹೋಬಳಿ, ಡಿ.ಸಾಲಿಂಡಿ ಗ್ರಾಮದ
ಮೌಂಟ್ ಲಿಟರಾ ಶಾಲೆಯ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು
ನೀಡುವ ಬಗ್ಗೆ.

ಉಲ್ಲೇಖ

1. ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ
ಇಲಾಖೆ, ನಂ.1ನೇ ಉಪವಿಭಾಗ, ಮೈಸೂರು, ಇವರ ಕಛೇರಿ ಪತ್ರ
ಸಂಖ್ಯೆ 590 ದಿನಾಂಕ 14.07.2022.
2. ಸರ್ಕಾರದ ಪತ್ರ ಸಂಖ್ಯೆ (ಶಿಕ್ಷಣ ಇಲಾಖೆ) ಲೋಇ:59:ಬಿಇಡಿ:2019
ದಿನಾಂಕ 06.05.2022.
3. ಸರ್ಕಾರಿ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ ಇಡಿ:43:ಪಿಜೆಸಿ:2022 ದಿ. 18.05.2022

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಮೈಸೂರು ತಾಲ್ಲೂಕು, ಜಯಪುರ ಹೋಬಳಿ, ಡಿ. ಸಾಲಿಂಡಿ ಗ್ರಾಮದ
ಮೌಂಟ್ ಲಿಟರಾ ಶಾಲಾ ಕಟ್ಟಡವನ್ನು ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ಲೋಇ., ಮೈಸೂರು ವಿಭಾಗ, ಮೈಸೂರು ಹಾಗೂ
ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.1 ಉಪವಿಭಾಗ, ಮೈಸೂರು ರವರು ಪರಿವೀಕ್ಷಣೆ ಮಾಡಿದ್ದು, ಸಹಾಯಕ
ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ಗುಣ ಭರವಸೆ ಉಪವಿಭಾಗ, ಮೈಸೂರು, ರವರು ISO/IEC
National Building Code 2016 Group B (Sub Division B1 and B2) Education Building ರನ್ವಯ NDT
test & Structural Stability Certificate ಹಾಗೂ ತಾಂತ್ರಿಕ ವರದಿಗಳೊಂದಿಗೆ ನಿಗದಿತ ನಮೂನೆಯಲ್ಲಿ ವರದಿಯನ್ನು
ಸಲ್ಲಿಸಿರುತ್ತಾರೆ. ಸದರಿ ವರದಿಯನ್ನು ಸ್ಥಳ ಪರಿಶೀಲಿಸಿ ಉಲ್ಲೇಖ (1) ರಲ್ಲಿ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.1ನೇ ಉಪವಿಭಾಗ, ಮೈಸೂರು, ರವರು ದೃಢೀಕರಿಸಿರುತ್ತಾರೆ.

ಸದರಿ ಕಟ್ಟಡವನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ, ಕಟ್ಟಡಕ್ಕೆ ಅವಶ್ಯಕ ಶೌಚಾಲಯಗಳು ಮತ್ತು ಕುಡಿಯುವ ನೀರಿನ ವ್ಯವಸ್ಥೆಯನ್ನು
ಕಲ್ಪಿಸಲಾಗಿದ್ದು, ಕಟ್ಟಡ ಕೆಲವು ಗೋಡೆಗಳ ಪ್ಲಾಸ್ಟರಿಂಗ್ ಕ್ರಾಕ್ ಕಂಡುಬಂದಿರುತ್ತದೆ ಮತ್ತು ಶೌಚಾಲಯ ಹಾಗೂ ಮೆಟ್ಟಿಲುಗಳ
ಮೇಲ್ಛಾವಣಿಯಲ್ಲಿ ಡ್ಯಾಂಪ್‌ನೆಸ್ ಕಂಡುಬಂದಿರುತ್ತದೆ. ಕಟ್ಟಡಕ್ಕೆ ಬಣ್ಣವನ್ನು ಬಳಿದು 4-5 ವರ್ಷಗಳಾಗಿರುತ್ತದೆ. ಮೇಲೆ ತಿಳಿಸಿರುವಂತೆ
ಸಣ್ಣ-ಪುಟ್ಟ ರಿಪೇರಿಗಳನ್ನೊಳಗೊಂಡಂತೆ ಮೇಲ್ಛಾವಣಿಗೆ ವಾಟರ್ ಪ್ರೂಫ್ ಅಳವಡಿಸಲು ಹಾಗೂ ಕಟ್ಟಡಕ್ಕೆ ಬಣ್ಣವನ್ನು
ಮಾಡಿಕೊಳ್ಳಲು ತಿಳಿಸಿರುವುದಾಗಿ ಉಲ್ಲೇಖಿತ (1)ರ ಪತ್ರದಲ್ಲಿ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ
ಇಲಾಖೆ, ನಂ.1ನೇ ಉಪವಿಭಾಗ, ಮೈಸೂರು, ರವರು ವರದಿಪಡಿಸಿರುತ್ತಾರೆ. ಇನ್ನುಳಿದಂತೆ ಕಟ್ಟಡವು ಸುರಕ್ಷಿತವಾಗಿದ್ದು,
ಉಪಯೋಗಕ್ಕೆ ಯೋಗ್ಯವಾಗಿರುವ ಬಗ್ಗೆ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ಗುಣ ಭರವಸೆ
ಉಪವಿಭಾಗ, ಮೈಸೂರು, ರವರು ದೃಢೀಕರಿಸಿರುತ್ತಾರೆ.

ಮುಂದುವರೆದು, ಕಟ್ಟಡದ ಸುರಕ್ಷತೆಗೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.1 ಉಪವಿಭಾಗ,
ಮೈಸೂರು ರವರು ಉಲ್ಲೇಖ ಪತ್ರದಲ್ಲಿ ಕಟ್ಟಡದ ಕಾಂಕ್ರೀಟ್ ಸದೃಢತೆಯ ಬಗ್ಗೆ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ಗುಣ ಭರವಸೆ ಉಪವಿಭಾಗ, ಮೈಸೂರು, ಇವರ Physical observation & Accordingly
necessary field Tests ಪರೀಕ್ಷೆಗಳನ್ನು ಕೈಗೊಂಡು, ಸಮಾಲೋಚಕರೊಂದಿಗೆ ಉಪವಿಭಾಗದ ತಾಂತ್ರಿಕ ವರ್ಗವು ನಡೆಸಿರುವ
ಪರೀಕ್ಷೆಯ ವರದಿಯಂತೆ ಕಟ್ಟಡವು ಸದೃಢತೆಯಿಂದ ಇರುವುದು ಕಂಡುಬಂದಿರುತ್ತದೆ ಎಂದು ವರದಿ ಮಾಡಿರುತ್ತಾರೆ.

ಸದರಿ ಸಂಸ್ಥೆಯವರು ಕರ್ನಾಟಕ ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ ಲೋಇ:59:ಬಿಇಡಿ:2019 ದಿನಾಂಕ 06.05.2022. ರಂತೆ ಸದರಿ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪಡೆಯಲು ನಿಗದಿಪಡಿಸಿರುವ ಶುಲ್ಕವಾದ ರೂ. 5,000.00 ಗಳನ್ನು ದಿನಾಂಕ 19.08.2022 ರಂದು ಲೆಕ್ಕಶಾಖೆಗೆ ಪಾವತಿಸಿರುತ್ತಾರೆ. ಸದರಿ ಸಂಸ್ಥೆಯವರು ನೀಡಿರುವ ಎಲ್ಲಾ ದಾಖಲೆಗಳನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ಗುಣ ಭರವಸೆ ಉಪವಿಭಾಗ, ಮೈಸೂರು, ರವರು ಕಟ್ಟಡವು ರಚನಾತ್ಮಕವಾಗಿ ಸುರಕ್ಷಿತವಾಗಿದೆಯೆಂದು ನೀಡಿರುವ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪರಿಗಣಿಸಿ, ಹಾಗೂ ಕಟ್ಟಡವನ್ನು ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆಯ ತಾಂತ್ರಿಕ ತಂಡ ಪರಿಶೀಲಿಸಲಾಗಿ ಕಟ್ಟಡವು "Structurally Stable" ಇರುವುದಾಗಿ ಪರೀಕ್ಷಾ ವರದಿಗಳಿಂದ ಕಂಡುಬಂದಿರುವುದರಿಂದ ಪ್ರಸಕ್ತ ಶೈಕ್ಷಣಿಕ ಸಾಲಿಗೆ ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು (Building Safety Certificate) ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,


ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್

ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಮೈಸೂರು ವಿಭಾಗ, ಮೈಸೂರು.