



Insurance Company Accident Report

Part 1. Driver Information

FIRST NAME	LAST NAME	ID NUMBER	
Daniel	Rivera	778-23-5610	
MOBILE PHONE NUMBER		DATE OF BIRTH	
(555) 901-2345		07/14/1981	
ZIP CODE	CITY	HOUSE NUMBER	STREET
77005	Houston	8921	Cypress Avenue
LICENSE NUMBER	LICENSE PLATE NUMBER	VEHICLE MAKE AND MODEL	VEHICLE YEAR
R892-3456-7810	LMN 4321	Ford Explorer	2020

Part 2. Vehicle Owner Information

FIRST NAME	LAST NAME	ID NUMBER	
Daniel	Rivera	778-23-5610	
MOBILE PHONE NUMBER		DATE OF BIRTH	
(555) 901-2345		07/14/1981	
ZIP CODE	CITY	HOUSE NUMBER	STREET
77005	Houston	8921	Cypress Avenue

Part 3. Other Involved Parties (USE ADDITIONAL FORMS IF NECESSARY)

Other Vehicle 1

FIRST NAME	LAST NAME	ID NUMBER	
Ashley	Johnson	445-67-8901	
MOBILE PHONE NUMBER		DATE OF BIRTH	
(555) 234-5678		1995-04-18	
ZIP CODE	CITY	HOUSE NUMBER	STREET
60609	Chicago	678	Washington Boulevard
LICENSE NUMBER	LICENSE PLATE NUMBER	VEHICLE MAKE AND MODEL	VEHICLE YEAR
J234-5678-9012	DEF 2468	Nissan Altima	2022

Other Vehicle 2

FIRST NAME	LAST NAME	ID NUMBER	
Brian	O'Connor	662-54-9087	
MOBILE PHONE NUMBER		DATE OF BIRTH	
(555) 789-3456		05/19/1990	
ZIP CODE	CITY	HOUSE NUMBER	STREET
77019	Houston	3205	Westheimer Road
LICENSE NUMBER	LICENSE PLATE NUMBER	VEHICLE MAKE AND MODEL	VEHICLE YEAR
O789-3456-1209	GHI 7539	Chevrolet Malibu	2021

Other Vehicle 3

FIRST NAME	LAST NAME	ID NUMBER	
MOBILE PHONE NUMBER		DATE OF BIRTH	
ZIP CODE	CITY	HOUSE NUMBER	STREET
LICENSE NUMBER	LICENSE PLATE NUMBER	VEHICLE MAKE AND MODEL	VEHICLE YEAR
INSURANCE TYPE	POLICY NUMBER	AGENT	INSURANCE COMPANY NAME

Part 4. ACCIDENT INFORMATION

ACCIDENT DATE	TIME	CITY	ACCIDENT LOCATION
02/08/2025	7:45 PM	Houston	Intersection of Westheimer Road and Montrose Boulevard
NUMBER OF VEHICLES INVOLVED	WAS A POLICE REPORT MADE? (YES/NO)	IF YES, WHAT POLICE AGENCY	
3	Yes	Houston Police Department, Report #2025-02-08-5678	
ACCIDENT DESCRIPTION			
At 7:43 PM on February 8, 2025, Ashley Johnson was driving eastbound on Westheimer Road, approaching Montrose Boulevard. The light turned yellow as she entered the intersection, and she attempted to proceed through. At 7:44 PM, Brian O'Connor was traveling westbound on Westheimer Road and began turning left onto Montrose Boulevard as the light changed. At 7:45 PM, Daniel Rivera was waiting at the red light on Montrose Boulevard. When his light turned green, he began to drive northbound through the intersection. Johnson's Nissan Altima struck O'Connor's Chevrolet Malibu in the rear passenger side as he turned. The force of the impact pushed O'Connor's vehicle into Rivera's Ford Explorer, which had just entered the intersection. Johnson's vehicle sustained heavy front-end damage. O'Connor's vehicle had significant damage to the rear quarter panel. Rivera's vehicle sustained damage to the driver's side door and fender. EMS evaluated all three drivers on the scene. Johnson and O'Connor complained of minor shoulder pain but declined hospital transport. Rivera was uninjured. All three vehicles required towing.			

Part 5. DIAGRAM DESCRIPTION OF ACCIDENT

		NORTH	INSTRUCTIONS DRAW PICTURE OF ROADWAY AT PLACE OF ACCIDENT. NUMBER EACH VEHICLE AND SHOW DIRECTION OF TRAVEL BY ARROW.												
		EXAMPLE → ←	SYMBOLS <table border="0"> <tr> <td>1. VEHICLE</td> <td></td> <td>4. RAILROAD</td> <td></td> </tr> <tr> <td>2. MOTORCYCLE</td> <td></td> <td>5. UTILITY POLE</td> <td></td> </tr> <tr> <td>3. PEDESTRIAN</td> <td></td> <td></td> <td></td> </tr> </table>	1. VEHICLE		4. RAILROAD		2. MOTORCYCLE		5. UTILITY POLE		3. PEDESTRIAN			
1. VEHICLE		4. RAILROAD													
2. MOTORCYCLE		5. UTILITY POLE													
3. PEDESTRIAN															