

Compiled visit record

This is not a photographed hand-filled booklet. None naming this facility is on file. The Word toolkit beside this page is written from the visit record below.

Facility. Kamoru HC III

Local government. Kotido District

Date of visit. 2026-08-26

Verifiers. Mworozzi Davis, Nalukwata Shadia

Supervisor. Kassim Luminsa +256 702 806116

Circumstance. Entered. Equipment and the supplier delivery note were photographed. No booklet was filled on site.

From the visit.

- The person in charge was engaged with other partners through the visit and is not named.
- A supplier delivery note of 10 June 2025 heads the facility Kamoru HC II, Payangara, Kotido and carries 44 lines. Every line is ticked on that paper. A tick on a delivery note is not a ground count.
- No hand-filled booklet naming this facility is on file. The schedule is written from the photographs. The delivery note's 44 lines and 94 items are the supplied side and are not written here as found.
- The discussion guide was not filled on a form. Questions 2, 3 and 4 are what the facility told the team; 1a and 1b were not answered.
- Nothing was counted against the delivery note, so not one of its 44 lines has a found quantity.
- One table is engraved. The microscope and the centrifuge carry the facility's own mark, which is not engraving. No serial number was read.
- The programme list and the delivery note both read HC II; the facility's own markings and the team read HC III.