

23rd - Oct - 2025

SCHOOL INTERVIEW/DISCUSSION GUIDE

Name of school: NAMBOKO SEED SECONDARY SCHOOL

1a	Does the Facility have a record of all assets provided under UgIFT. (Obtain a record and verify if it has the costs and numbers supplied)	Yes.
1b	If Not ask how many were supplied and when.	

2	How does this facility Maintain (repair/service/replace) the assets provided under Ugift
---	--

Yes

The school is still under defect and maint liability period. In other words the contractor come and repair / replace

3	Does the facility take regular record about functionality/ or breakdown of the assets provided? Nonfunctional/ working, and reasons for non-functionality.	Yes No.
---	---	------------

Yes No

They have ~~been~~ done they are still under defect liability period.

4	How has the UgIFT support helped in service delivery in the area, any issues, challenges and any recommendations for better program implementation.
---	---

- The ugift has Improved Edn service provided as the material.

Challenges

- Lack funding
- Inadequate service materials

PROCEED TO VERIFICATION AFTER THIS DISCUSSION

Recommendation

- The ~~dismission~~ should come early enough & commission should be done early
fencing of the school to avoid Insecurity

SCHOOL FURNITURE

(School Desks, Office chairs, Laboratory stools, Book shelves)

Name of LG, NAMKINDRIA DISTRICT

	Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number. (engrave no.)	Date of Purchase
Sch. 229	chairs	Echn	-	wooden with metallic stand.		Some are engraved but not numbered	
13.	office tables with desk.	Echn		wooden with metallic stand		labelled	
	Desks 118	Echn		wooden with metallic stand		labelled	
119	Laboratory stool	Echn.		wooden with metallic handle		labelled.	
37	Tables	Echn	-	wooden with metallic handle		Not engraved	
28	Book shelves.	Echn	-	wooden with metallic handle		Labelled	

NAME OF SCHOOL NAMBOKO SEED SECONDARY SCHOOL

Date Placed in Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
23 rd 10-25						good condition	229 chairs but 17 Non functional the other functional
23 rd 10-25						good condition	functional and they were broken independent blocks
25 rd 10-25						good condition	118 functional physically good; counted.
23 rd 10-25						good condition	119 physically counted 2 broken
23 rd 10-25						good condition	37 physically counted functional in good use.
23 rd 10-25						good condition	28 functional in good shape.

ICT ITEMS TO VERIFY

(Desktop Computer, Server Processor, Network Switch 24 Port, Multipurpose Printer, UPS, Projector, Air Conditioners, Server, CCTV Camera)

Name of LG...NAMISINGIA DISTRICT.

Equipment/ Item	Department	Asset Number	Item Description	Life Months	In	Tag Number (engrave no.)	Date of Purchase
Desktop computer	Edn	-	Black with Black Screen			Not engraved	
20 UPS	Edn	-	Black Colour Unomat Internal			Not engraved.	
1 projector	Edn	MRJA H002511 00EB98410	Acer Black			Not engraved	
2 Air conditioners & 100 processor		-	Big boxer			Not engraved	
1 camera CCTV	Edn		white with black Screen				
1 Server processor	Edn	-	Not seen			Not seen	

Name of School: NAMBOKO SEES SECONDARY

Date Service	Placed In	Cost	Recovery Cost	Acc Dep Cost	Net Value	Book Yld Deprn	Equipment status	Remarks
28 rd -10-25							good condition	1 functional in the computer office 1 in the secretary office 8 monitors stolen cpu stolen were 14 6 functional in the computer room.
28 rd -10-25							good condition	2 nonfunctional 19 functional in the secretary office.
23 rd -10-25							good condition	functional but kept in the deputy office.
23 rd -10-25							good condition	functional but kept in the store.
							good condition	Camera functional but CCTV nonfunctional but they are all in good condition.
Not								

At Scan

The server processor not scan. I was told by the H/M through the

The server processor
hadn't been seen. It was told
by the H/M through the
ICT teacher that it was one
of the things that were
maybe stolen.

Equipment/ Item	Department	Asset Number	Item Description	Life Months	in	Tag Number (engrave no.)	Date of Purchase
1. server	Edm	03556-070	Black				
		160-084	Roll			Not	
			inter			engraved	
			wire				
Network							
switch	Edm	-	whites			Not	
24 port			wire and			engraved	
			Black				
multi purpose							
printer	Edm	-	HP			Not	
			Printer				
			HP				
			LaserJet			engraved	
			pro.				
			MFP				
			4103dw				
Public							
Address	Edm	-	2 tops				
system			speaker				
			2 base			Not	
			4 speakers			engraved	
			mixer				
			box				
1. generator	Edm		Red &			Not	
			grey handle			engraved	
			fashion				
			series				
4. Fire extinguishers			Red with				
			black				
			handle			Not	
			2 powder			engraved	
			2 carbondioxide				

Date placed in service	Cost	Recovery Cost	Acc Dep Cost	Net Value	Book Ytd Depn	Equipment status	Remarks
						good condition	functional in the server room.
13 rd - 10-25							
						good condition	functional in the server room.
						good condition	functional in the secretary's office.
10-25							
						good condition	functional in but stored in deputy's office.
						good condition	functional in secretary office.
						good condition	functional but not in use.
0-25							

BUILDINGS TO VERIFY

(Non- Residential and Residential, Kitchen, Toilets
Pit latrine Water tanks, Fences etc.)

Name of LG... NAMKINDRIA DISTRICT

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
Non Residential						
Bulding		-	3 classroom block		Labelled	
			2 classroom each			
			wall mounted			
			cupboard &			
			open shelves			
Administration			- H/M			
Block			- Reception			
	Edn		- Deputy			
			store secretary		Labelled	
Science						
Laboratory	Edn	-	2 big room		Labelled	
			2 unit store		Not	
					engraved	
Library &			Library		Not	
ICT lab			ICT lab		engraved	
Multi						
Purpose Hall			3 compartment		Not	
					engraved	
Pit			girls			
latrines			1 changing room			
			distance			
			distance for pwd			
			Boys		Not	
			distance			
			distance for pwd		engraved	
			1 bathroom			

Staff pit latrine.

- distance female/male.
2 sets

Name of School.....NAMBOKO SEED SECONDARY SCHOOL.

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
10-25						good condition	functional clean and in good use
						good condition	functional clean and in good use.
10-25						good condition	functional and good use.
10-25						good condition	functional but ICT Lab is no dust and computers are not covered and very disorganised
						good condition	functional and in good shape.
0-25						good condition	functional in good shape.

BUILDINGS TO VERIFY

(Non- Residential and Residential, Kitchen, Toilets
Pit latrine Water tanks, Fences etc.)

Name of LG NAMKINDWA DISTRICT

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
Water tanks	-	-	1 for 10000 LTR. 1 for 3000 LTR. with water pump		Not engraved	
Residential staff quarter	-	-	3 block 2 unit each each 2 bedroom sitting room store.		Not engraved	
Pit latrine	-	-	3 block 2 chamber 2 bathroom Each		Not engraved	
Kitchen	-	-	3 block 2 unit each		Not engraved	
water tanks	-	-	5000 LTR.		Not engraved	
	Not seen				Not engraved	

Date of Purchase

good	There was
condition	one functional but
	In btr laboratories
	classroom black
	5000 Ltr.