

- Challenges
- Under staff in all departments
 - They Established A'level to support students in A Level
 - Limited classrooms & to accommodate learners; 51-120; 105-140.
 - Water challenge

SCHOOL VERIFICATION CHECKLIST

Challenges

- Electricity is not at school, the school uses a generator which is expensive during examination periods.
 - The school is exposed to natural hazards like strong winds and storms.
On 29/05/2026, the roof of ridge was blown away and rain water entered the computer Lab.
The fence was broken down, Roof of Staff Pit latrines were blown off.
 - One staff per subject is affecting service delivery
- Recommendations

- * Urgent need for electricity in the school to support to support ICT Lab.
- * At least two member of staff per every subject.
- * Addition on classrooms to accommodate the number of learners.

1C
022

SCHOC

Name of school:

1a	Does the Facility UglIFT. (Obtain a record supplied)
1b	If Not ask how

2	How does this Ugift
---	---------------------

They face
so the

3	Does the fac breakdown c Nonfunction functionalit
---	---

at. the
There is r

4	How has the are recomm
---	------------------------

SOP Se
in so
Long a
secon

PROCEED TO

The s
School

109 & Lab Equipment 18/02/2026
~~and~~

SCHOOL INTERVIEW/DISCUSSION GUIDE

Name of school: SOP SOP SEED SCHOOL

1a	Does the Facility have a record of all assets provided under UgIFT. (Obtain a record and verify if it has the costs and numbers supplied)	No
1b	If Not ask how many were supplied and when.	05/02/2026 for furniture

2	How does this facility Maintain (repair/service/replace) the assets provided under Ugift
---	--

any facility is still under defect Liability period
so the constructor does the repair.

3	Does the facility take regular record about functionality/ or breakdown of the assets provided?	No records are kept at school.
	Nonfunctional/ working, and reasons for non-functionality.	One camera is nonfunction.

at the motherboard got burnt.

There is no electricity at the school

4	How has the UgIFT support helped in service delivery in the area. any issues, challenges and any recommendations for better program implementation.
---	---

SOP SOP seed school is the only government school in SOP SOP sub county. It has reduced on long distance learners were moving to access secondary Education

PROCEED TO VERIFICATION AFTER THIS DISCUSSION

The school has improved on business around the school and this has promoted peaceful co existence

SCHOOL FURNITURE

(School Desks, Office chairs, Laboratory stools, Book shelves)

Name of LG. Tororo District

NAME OF SCHOOL

ST. LOP

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
Desks	Edn	-	Timber & Iron/metal		Engraved with no numbers -	
113						
Chairs	Edn	-	Timber and metal sitting base		Engraved not numbered	
262						
Office Tables	Edn	-	Wooden with metal stands		Engraved not numbered	
11						
Lab Stools	Edn	-	Wooden sitting base and metal stands		Engraved not numbered	
125						
Book Shelves	Edn	-	Wooden & metal		Not Engraved	
17						
Computer tables	Edn	-	Wooden and metal		Not Engraved	
20						

Date Placed in Service	Cost	Recovery Cost
05/02/26	-	-
05/02/26	-	
05/02/26		
05/02/26		
05/02/26		
05/02/26	-	
05/02/26	-	

St Joseph Sopsop Seed Secondary School.

St. Joseph SOPSOP Seed Secondary School
~~SOPSOP SEED SCHOOL~~

NAME OF SCHOOL

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
05/02/26	-	-	-	-	-	Good Condition	All in use
05/02/26	-					Good Condition	7 Chairs are not engraved the school does not have special chairs
05/02/26						Good Condition	All in use 2 not engraved the school does not special office chairs
05/02/26						Good Condition	One broken stool, the rest are in good condition.
05/02/26	-					Good Condition	All in good working condition
05/02/26	-					Good Condition	All in good working condition

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
Staff room Tables 04	LD ⁿ	-	Metal and wood/ timber	-	Engraved Not numbered	
Library Tables 94	LD ⁿ	-	Metallie and Timber		Engraved not numbered	
Reception Lounge	LD ⁿ	-	Wooden		Not engraved	
Fire Extinguishers 11	LD ⁿ	-	9Kg Powder and CO2		Not Engraved	
Public Address System	LD ⁿ	-	Base Speaker of, Top Speaker 4 Mixer 1 04 Speaker Stands, and Wires		Not Engraved	
Gas Cylinders 02	LD ⁿ	-	SHILL Gas, 45Kg		Not Engraved	

[illegible]

[illegible]

ICT ITEMS TO VERIFY

(Desktop Computer, Server Processor, Network Switch 24 Port, Multipurpose Printer, UPS, Projector, Air Conditioners, Server, CCTV Camera)

Name of LG.....Gororo District.....

Equipment/ Item	Department	Asset Number	Item Description	Life Months	In Tag Number (engrave no.)	Date of Purchase
Desktop Computer 20	-	-	Dell, with a UPS, CPU Keyboard and Mouse		Not Engraved	
CCTV Camera 03	-		Mounted in corners to view the Computer Lab Thru a P.V.I.D. 01.04. 36701		Not Engraved	
Server Processors 02	-	-	Enclosed in metallic casing black in colour		Not Engraved	

Name of School..... St. Joseph SOPSOP Seed School

[illegible]

Equipment/ Item	Department	Asset Number	Item Description	Life Months	in Tag Number (engrave no.)	Date of Purchase
Net- work Switch 24 port 02	-	-	White Coloured Circular		Not Engraved	
Multi Purpose Printer 01			HP LaserJet P10 MFP 4103dw		Not Engraved	18/02/26
UPS 21	-		KSTAR		Not Engraved	18/02/26 25
Projector 02	-		Acer Acer X 1123HP DLP Projector, AAP Model No ASV1904		Not Engraved	18/02/26 25
Projector Screen			White board Pull down format		Not Engraved	18/02/26 25
Air Condition	-		Sumsung		Not Engraved	18/02/26 25

Date placed in service	Cost	Recovery Cost	Acc Dep Cost	Net Value	Book	Ytd Deprn	Equipment status	Remarks
18/02/25							Good Condition	All in use.
18/02/26							Good Condition	In use in the ICF Lab.
18/02/26							Good Condition	All in use in the computer lab.
18/02/26							Good Condition	All in use
18/02/26							Good Condition	In use in computer Lab.
18/02/26							Good Condition	Mounted on the wall in the Control ICF Lab room.

BUILDINGS TO VERIFY

(Non- Residential and Residential, Kitchen, Toilets
Pit latrine Water tanks, Fences etc.)

Name of LG..... Tororo District.....

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (if engrave no.)	Date of Purchase
Guard/ Security House	-	-	Small house at the gate to manage entry and exit.		Not engraved	
Pit latrine 03 Blocks			One block with 4 stances and one Winal for boys, 1 block with 4 stances, 1 changing room and for girls and One block for teachers with two stances, MSF staff		Not engraved	

Name of School... St. Joseph Sopsop seed School

Date Placed in Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
05/02/2025 25						Good Condition	In use sheltering for security guard.
05/02/2025 26						Good Condition	All in use Each Block of Pflapines for students has one stance for students living with disability

BUILDINGS TO VERIFY

(Non- Residential and Residential, Kitchen, Toilets
Pit latrine Water tanks, Fences etc.)

Name of LG..... Geroro District

Equipment/ Item	Department	Asset Number	Item Description	Life In Months	Tag Number (engrave no.)	Date of Purchase
7 Blocks			One Admin, One Science Lab, One Library & ICT Lab, One Multi purpose Hall, 3 classroom blocks		Not Engraved	
3 Staff House Block	-	-	Each block has two units		Not Engraved	05/02/26
3 Staff Kitchen	-	-	Each kitchen block has two units		Not Engraved	05/02/26
Chain Link fence	-	-	Installed on all the school boundary		Not Engraved	05/02/26
Water Tanks	-	-	One 10,000 litre and one 3000 litre		Not Engraved	05/02/26

Teachers Residential Pit Latrines; There are three units with one stance and a bath room.

05/02/26

