

SCHOOL INTERVIEW/DISCUSSION GUIDE

Name of school: B. KHABUTOOLA SEED SECONDARY SCHOOL

1a	Does the Facility have a record of all assets provided under UgIFT. (Obtain a record and verify if it has the costs and numbers supplied)	Yes
1b	If Not ask how many were supplied and when.	But they have records for science equipment & chemical and ICT equipment

2	How does this facility Maintain (repair/service/replace) the assets provided under Ugift	Not yet because the contractor is still in the school.
---	--	--

3	Does the facility take regular record about functionality/ or breakdown of the assets provided? Nonfunctional/ working, and reasons for non-functionality.	No the school
---	---	------------------

No

Because the school is under the contractor.

4	How has the UgIFT support helped in service delivery in the area, any issues, challenges and any recommendations for better program implementation.	
---	---	--

Yes

- Access Edn nearer to the people because it's only school secondary in the all sub countries.
- Employment opportunities of the support staff.
- The for the case of the village ^{function} as wedding meeting the community make use of the multi purpose hall.

PROCEED TO VERIFICATION AFTER THIS DISCUSSION

Challenges

- They have few classrooms yet the number is increasing
- No teacher for the local language
- The boys pit latrine was constructed - Very near the class room



AND RECORDING
IT

SCHOOL VERIFICATION CHECKLIST

Recommendations:

- More classroom block needed because the numbers keep on increase so the available classroom are not enough.
- They need teachers for local language.
- The boys pit latrine is too constructed far way from the classroom.

SCHOOL IN

Name of school: B K

1a	Does the Facility have UGIFT. (Obtain a record and supplied)
1b	If Not ask how many

2	How does this facility Ugift
---	------------------------------

Not yet to school.

3	Does the facility have breakdown of the a Nonfunctional/ functionality.
---	---

No
Because

4	How has the U the area, recommendation
---	--

- YES
- Access Edh School so
 - Employment
 - The for

PROCEED TO VERIF
The comm

Challenges

- They have
- No teachers
- No teachers
- The boys

SCHOOL FURNITURE

(School Desks, Office chairs, Laboratory stools, Book shelves)

Name of LG... MANAFWA DISTRICT

	Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
188	School chairs	Edn	-	wooden with metallic stands		Engraved but not numbered	
48	School Table	Edn	-	wooden with metallic stands		Engraved but not numbered	
10	office Tables	Edn	-	wooden with metallic stands		Engraved Not numbered	
119	School desks	Edn	-	wooden with metallic stands		Engraved Not numbered	
130	Lab stool	Edn	-	wooden with metallic stands		Engraved Not numbered	

NAME OF SCHOOL KIRABUTOOLA JESU SCHOOL SCHOOL

Date Placed in Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
						not all are in good condition	181 functional & in good shape 7 Non functional
						not in good condition	47 functional and in use 1 Non functional
						good condition	10 functional and they are used in different department.
						2 not in good condition	117 functional and used in classroom 2 Non functional
						5 not in good condition	125 functional and in use 5 Non functional

ICT ITEMS TO VERIFY

(Desktop Computer, Server Processor, Network Switch 24 Port, Multipurpose Printer, UPS, Projector, Air Conditioners, Server, CCTV Camera)

Name of LG... MANAFWA DISTRICT

Equipment/Item	Department	Asset Number	Item Description	Life Months	In	Tag Number (engrave no.)	Date of Purchase
20 Desktop Computer	Edu	-	Blank Boxes			Not engraved	
1 Server						Not engraved	
processor	Edu	-	Boxes				
1 Network switch 24 port	Edu		Boxes			Not engraved	
1 Multipurpose printer	Edu	- CNRS45 GHH	white hp	-		Not engraved	
1 Server ups	Edu	-	Boxes	-		Not engraved still new	
1 Air conditioner			Boxes	-		Not engraved	
20 UPS		-	Boxes	-		Not engraved	
CCTV camera	Edu	-	Boxes	-		Not engraved	

Name of School... KHABUTOOLA S.B.S. SECONDARY SCHOOL

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Value	Book Yld Depn	Equipment status	Remarks
15 th 01 2025	Total 93,000,000					good	functional but
						condition	they kept in the
	Total 6,500,000						store for safety reason.
15 th 01 - 25						5	
						good	functional but
						condition	still in the box
	Total 1200,000					good	functional but
						condition	not arranged
15 th 01 - 25	Total 5000,000					good	not installed
						condition	functional
							and being used
							In the secretary's
							office
15 th 01 - 25	Total 3,400,000					good	functional but
						condition	still kept in
							the box not
							yet installed
	Total 5500,000						
15 th 01 - 25						good	functional
						condition	but not
							installed.
15 th 01 - 25	Total 12,000,000					good	
15 th Jan - 25						condition	functional but
							not installed.

(Non- Residential and Residential, Kitchen, Toilets
Pit latrine Water tanks, Fences etc.)

Name of LG...MANAFWA DISTRICT.

516 laboratory

The classroom and other ^{store} blocks are good shape well constructed and still under construction,

Name of School... KHAPOOLA SEEN

[illegible]

Name of School... KHATOOLA SEED SECONDARY SCHOOL

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Depn	Equipment status	Remarks
						good condition	functional but over kept under store and lbw being used.
						good condition	functional and lbw in good shape & being used.
						good condition	functional and in good shape and lbw being used.
						good condition	functional but the computer are kept and lbw not installed fully.
						good condition	lbw are still under construction in side but they were 'lbw'

BUILDINGS TO VERIFY

(Non- Residential and Residential, Kitchen, Toilets
Pit latrine Water tanks, Fences etc.)

Name of LG..... INKANA DISTRICT.....

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
Pit latrines Edn						
Boys pit latrine		4 latrine.	4 latrines		Not	
		1 bathroom	1 bathroom	-	engraved	
		1 for PWD	1 for PWD			
Girk.						
Boys pit latrine		4 latrine	4 latrines			
		1 changing room	1 changing room			
		1 for PWD	1 for PWD	-	Not	
					engraved.	
Staff pit latrine		2 latrines	2 latrines		Not	
		1 male 1 female	1 male 1 female		engraved	
Klato tanks						
		1 for 1000 LTR	1 for 1000 LTR		Not engraved	
		1 for 5000 LTR	1 for 5000 LTR			
		1 for 3000 LTR	1 for 3000 LTR			
		Electric water pump	Electric water pump			
Residential building						
Building		3 block	3 block			
		2 sitting room each	2 sitting room each			
		2 bed room each	2 bed room each			
		2 store each	2 store each			
Kitchen Edn		3 blocks	3 blocks			
		2 units each	2 units each			
pit latrines Edn		3 pit latrine block	3 pit latrine block			
		2 latrines each	2 latrines each			
		2 bathroom each	2 bathroom each			

Klato tanks. Edn

- The staff quarters have no functional water tank because it is still under construction, so the use for the school.

Name of SCHOOL... KIKATOOLA REED SECONDARY SCHOOL

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
						good condition	functional but H/m and 16 was constructed so nearer to the classroom
						good condition	functional in good shape and in use
						good condition	functional in use
						good condition	functional and all in used
						good condition	functional in good shape but they are not enough for teachers
						good condition	functional in good shape and being used.
						good condition	functional in good shape and being used.