

Nakwasi Seed Secondary School - facility report

1. Identification

Facility	Nakwasi Seed Secondary School
Named on the programme list	Nakwasi Seed School
Type	School
Local government	Butaleja District
Region / sub-region	Eastern / Bukedi
Date of visit	2026-08-31
Team members present	Sophie Nankyanzi, Butsiba Peter
Informant interviewed	Not named in the record
Supervisor	Kassim Luminsa
Supervisor's contact	+256 702 806116
Date of submission	

2. Entry

The school was photographed and a hand-filled toolkit that names it is on file. The signboard reads NAKWASI SEED SEC SCH. The guide names NAKWASI; the furniture page names NAKWAJI; the buildings pages name NAKWATI. No visitors' register was seen. No access problem was reported.

3. Condition and status

The four things the exercise exists to establish. Only what was established on site appears here; the rest is marked as not reported, not guessed.

Dimension	What was established on site
Ownership	Recorded as fully owned by the Ugandan Government. No title was produced.
Functionality	Furniture mostly functional, with about thirty ordinary chairs broken. ICT recorded as functional; computer batteries no longer hold charge. Buildings recorded as functional.
Usage / performance	In use. ICT equipment is moved to the administration block in the holidays for safety.
Location	Recorded on the filled pages: administration block, three classroom blocks, a main hall, a science laboratory, an ICT block, six pit latrines, three residential blocks and three water tanks.

4. Supplied against found

The district produced no record of assets. The filled pages are the found side: 120 desks, 302 ordinary chairs, 192 stools, 102 ordinary tables, 25 office chairs, 5 office tables, about ten library shelves seen, 28 desktop computers, one projector and one printer, with a second printer out for service. No supplied paper names this school.

5. Engraving and identification

Nothing was recorded as engraved. Building lines carry painted names such as Administration Block and SCIENCE LAB rather than an engraved number.

6. Obsolete, unserviceable or for disposal

About thirty of 302 ordinary chairs are broken. The make of the furniture is recorded as poor, with weak screws and a rough texture.

7. Operation and maintenance

The school has a maintenance plan and a budget line for repairs, windows and printer servicing. Stock is taken each term. It did not receive an internet package for a year, so the server was not connected. Theft and lack of a fence are recorded as risks.

8. Queries

- Settle the three spellings of the school name on its own filled pages.
- Confirm the date engraving will be done and who will do it.

- Confirm where the printer that is out for service now stands.
- Count the library shelves; ten were seen and the total was not certain.
- Confirm the date the team stood here; the photographs reached the record on 31 August and the filled pages on 1 September.